Folder 2 -
Building-Structure
Inventory Forms
#1 - 76

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

1-3

YOUR NAME: Loren J. McNeil DATE: January 1975

YOUR ADDRESS: R#1 Argyle, N.Y. TELEPHONE: 854-3423

ORGANIZATION (if any):

* *

IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: South of Callaway Road
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Loren McNeil ADDRESS:
6. USE: Original: Home Present: Storage Place
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☒
   Interior accessible: Explain

Callaway


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☒
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: 4-75



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Set off the road in hilly farm land

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Chair rail, had a beautiful pine built in corner cupboard with lower shelves, upstairs beaded pine sheathing painted old red, delicate molding up around window + doors - plank.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1810c

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

William Reid - 1913
Robert McFarland 1916
Loren McNeil 1941
J. McKnight on 1866 Atlas
J. Gilchrist 1853 map

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ballou DATE: July 22, 75

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Braymer Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Callaway Rd.
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: William Braymer ADDRESS: R.D. Argyle
6. USE: Original: farmhouse Present: farmhouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: slate roof
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P16-2



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: horse barn torn down

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1838 Samuel Wilson orig. owner ?

1885 John Robinson + Sarah to James + Charity Pollock

1897 Henry McNeil

Lincoln McNeil

Raymond Beame

1952 Bill Braymer

21. SOURCES:

1853 Map - A. Sill

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Dec. 9, 75

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Callaway Road
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Geo. L+ Alvane Payne ADDRESS:
6. USE: Original: farmhouse Present: summer house
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets alone on a back road.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

5-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Oct. 3, 1995

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: off Callaway Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Francis Clark ADDRESS: R.D.1 Argyle
6. USE: Original: Farm house Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☑
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☑ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☑
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: 95 111



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Building sets off in a field surrounded by trees

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Beautiful doorway with side-lights

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: One of many brick houses in the general area.
Grew potatoes

S.F. Barker 1866 Atlas
Gourlay
Jas. Reid, about 1910 bought it

Tom Valeau
Weeks
Clark

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Baillon DATE: Mar. 76'

YOUR ADDRESS: TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Howard Clark ADDRESS: R.D. Salem
6. USE: Original: Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: 24-25A



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets just outside the hamlet of Belcher

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Albert Crozier

21. SOURCES: 1853 Map - Queen Clark

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: 11/28/75

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Halls Pond Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Maurice Woodard ADDRESS: R.D.2, Salem
6. USE: Original: farmhouse Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐ b. wood frame with light members ☑ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Building sets on a country road outside of a hamlet

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

last resident Joe Eagle

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: July 8, 75'

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Hall Pond Rd.
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Cleoth Moffit ADDRESS: R.D.2, Salem
6. USE: Original: Farmhouse Present: Farmhouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain N/A


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known): Been done over recently - Porch added

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: farmland
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Set high on a hill overlooking valley and Vermont hills.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Ross Williamson + father Thomas
to
Kenneth Coombs
to
Moffit

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: July 1, 1975
YOUR ADDRESS: R.D.2, Salem, N.Y. TELEPHONE: 854-3520
ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Maurice Woodard ADDRESS: R.D.2, Salem
6. USE: Original: farmhouse Present: farmhouse - tenant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: slate roof
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☑ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Farmhouse set in a hilly landscape.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

late Federal, eye brow windows and beautiful deeperet doorway with heavy moldings.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: ~~past owner thinks~~ after civil war

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

There was story and a half ~~addition~~ original much earlier - torn down, ~~to the west~~.
Present house was added to ~~it's east on rear site~~
John Conety (from Ireland) bought around 1880's
Geo. White owner before Conety
— Allen before White

21. SOURCES:

Louise Conety 1853 Map - W. Bradford

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 11511
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Rollon DATE: July 1, 75'

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Louise Lonely ADDRESS: R.D. 2 Salem
6. USE: Original: farmhouse Present: farmhouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



D Belcher V

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☑ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: had a large barn

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1870's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Grew potatoes - filled cellar to the floor level

Libby Crosier got it from James Sloane
to
John Conely + Louis Conely

Sloane made money hay, horses, cat. during the war during depression made some pay up, ~~By building~~ they did by building house badly.

21. SOURCES: J. Sloane 1853 Map

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

11-2

YOUR NAME: JAMES J GAMBEE DATE: 1 OCT 1974
YOUR ADDRESS: HALLS POND ROAD SALEM, N.Y. TELEPHONE: 518-854-3490

ORGANIZATION (if any): HEBRON PRESERVATION SOCIETY

* *

IDENTIFICATION

1. BUILDING NAME(S): SCHOOL HOUSE #4
2. COUNTY: WASHINGTON TOWN/~~CITY~~: HEBRON VILLAGE: —
3. STREET LOCATION: HALLS POND ROAD
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: JAMES J. GAMBEE ADDRESS: SALEM, NEW YORK
6. USE: Original: SCHOOL HOUSE Present: GUEST HOUSE (DWELLING)
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain BY PERMISSION

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☒
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. mas WP ~~wood~~ bearing walls ☐
   d. met
   e. othe (CB)
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☒ if so, when? 1864 AND 1973
    c. list major alterations and dates (if known):

IN 1973/74 CONVERTED FROM ONE ROOM ABANDONED SCHOOL HOUSE TO GUEST COTTAGE WITH KITCHENETTE, BATH AND CELLAR PLAY ROOM.

12. PHOTO:

13. MAP:



HP-1

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: APPROX — 1810

ARCHITECT: UNKNOWN

BUILDER: DITTO —

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

MOVED DURING CIVIL WAR (1865)
LAST USED AS SCHOOL HOUSE ABOUT 190
USED AS LOGGERS CABIN — THEN HOME FO
2 YEARS BY FAMILY NAMED "DUTCHER" — IDLE FO
40 YEARS THEN MOVED AGAIN — PLACED ON
HILLSIDE, COMPLETE CELLAR — FRONT PORCH AND ALL
FACILITIES — ELEC — BATH ETC,

21. SOURCES:

22. THEME:

12

12-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: JAMES J. GAMBEE DATE: 1 OCT '74
YOUR ADDRESS: HALLS POND ROAD SALEM NEW YORK TELEPHONE: 518-854-3490
ORGANIZATION (if any): HEBRON PRESERVATION SOCIETY

* *

IDENTIFICATION

1. BUILDING NAME(S): FARM HOUSE - EAGLES REST FARM
2. COUNTY: WASHINGTON TOWN/~~CITY~~: HEBRON VILLAGE: —
3. STREET LOCATION: HALLS POND ROAD
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: JAMES J. GAMBEE ADDRESS: SALEM, N Y.
6. USE: Original: DWELLING Present: DWELLING
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain PRIVATE HOME

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):
    2 ADDITIONS - 1970, BEDROOM WING ON SOUTH
    KITCHEN WITH BEDROOM ABOVE ON N/WEST,


12. PHOTO:

AFTER 1ST CLEAN UP, PAINT JOB AND POND BUILT - FILLED 1965

13. MAP:

AFTER ADDITIONS - 1969





13-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: JAMES J. GAMBEE DATE: 9 DEC, 1975
YOUR ADDRESS: HALLS POND ROAD SALEM, NEW YORK TELEPHONE: 518-854-3490

ORGANIZATION (if any): HEBRON PRESERVATION SOCIETY

* *

IDENTIFICATION

1. BUILDING NAME(S): TENANT HOUSE - GAMBEE FARM (EAGLES REST)
2. COUNTY: WASHINGTON TOWN/~~CITY~~: HEBRON VILLAGE: ——
3. STREET LOCATION: HALLS POND ROAD
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: JAMES J GAMBEE ADDRESS: SALEM, N.Y.
6. USE: Original: TENANT HOUSE, BLACKSMITH Present: DWELLING
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain DWELLING

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stuc[illegible] ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): COMPLETELY RESTORED IN 1975. LAST USED AS DWELLING IN 1890's — SINCE AS BARN - BLACKSMITH SHOP ETC.

12. PHOTO: 1974



13. MAP: 1975



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: SPECTACULAR CATARACTS & FALLS BEHIND
j. ~~other:~~ HOUSE

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: WATER FALLS

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: CIRCA 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

Historic Resources Survey

Missing Pages

#. Hebron-T-002-01-02

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Billow DATE: July 1, 75'

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3320

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Irwin Zwies ADDRESS: R.D. 2, Salem
6. USE: Original: Farmhouse Present: residence & Antique Shop
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: Slate roof
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Pond
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Geo. McKernon
to
Clayton Hall
to
Irwin Zwieg

21. SOURCES: 1853 Map - P. Qua

22. THEME:

Doris Manley - State Asst. Researcher

15-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115-11-
QUAD
SERIES
NEG. NO.

YOUR NAME: Joyce Day DATE: 7/14/75

YOUR ADDRESS: R.D. #2 Salem TELEPHONE: 854-3485

ORGANIZATION (if any): Hebron Preservation Soc.,

* *

IDENTIFICATION

1. BUILDING NAME(S): Dwelling
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION: Co. Rt. 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mrs Frank W. Day ADDRESS: RD 2 Salem
6. USE: Original: farmhouse Present: farmhouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☑ if so, when? 1924
    c. list major alterations and dates (if known):
    1943 bath; bedroom added, kitchen extended
    1924 kitchen, dining rm. added

Direction house faces

12. PHOTO:

13. MAP:





HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☑ e. shed ☐ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: Hilly
j. other: Horse Barn

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Farm house sets back from road

present

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Original building was an inn built about 1790 on the Old Post Road by Jesse Day. The present house was built by Horace Day in 1924

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1790

ARCHITECT: _____

BUILDER: _____

old

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Sets on the site of an early inn built by Jesse Day in 1790.

Horace Day
Frank W. Day

21. SOURCES:

Horace Day

16-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Joyce Day DATE: Nov. 30, 75

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 0

ORGANIZATION (if any): & Hebron Preservation Soc.

* *

IDENTIFICATION


1. BUILDING NAME(S): was Dist. Sch. #3
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION: Co. Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Horace Day ADDRESS: Hartford, N.Y.
6. USE: Original: district school Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when? c. list major alterations and dates (if known):

1957 - 30 X 30 addition
1956 - Converted to dwelling

12. PHOTO:



13. MAP:



HP-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
At end of village

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
swings & teater totters

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Illustrates rural district school

21. SOURCES:
H. Day

22. THEME:
Education

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Joyce Day Brown DATE: Dec. 3, 1975

YOUR ADDRESS: R.D. 2 TELEPHONE:

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION


1. BUILDING NAME(S): ~~Dimmick~~ Day Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION: Co. Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Minnie Day ADDRESS:
6. USE: Original: farmhouse Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain ?


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑?
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? ?
    c. list major alterations and dates (if known):

12. PHOTO: P11-8

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Hilly
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Near road. Garage on North. Cow barn across road.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Joyce Day Brown DATE: Dec. 3, 1975

YOUR ADDRESS: R.D.2 TELEPHONE:

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Hebron
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Helen Toomey ADDRESS: R.D.2, Salem
6. USE: Original: residence Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: 76-5



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
none
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Near road - front facing road.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Cellar goes all the way under front pourch.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Andrew Foster moved here when his son Jessie married and remained in the Flack house.
Been empty over 10 years.

21. SOURCES:

22. THEME:

19-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Rollin DATE: Dec. 3, 75

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION: #30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ~~Minnie Day~~ Zich. McNeil → ADDRESS: R.D. 2
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): made into a garage Nov. 1975

12. PHOTO: P6-4



13. MAP:



UP 1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: H; 11/r
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ballou DATE: Dec. 3, 75'

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION


1. BUILDING NAME(S): Belcher Methodist Episcopal Church
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION: Co. # 30 So
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Minnie Day ADDRESS: R.D. 2, Salem
6. USE: Original: Church Present: storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (/Rs) ☐
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☑ if so, when? 1875 by oxen on frozen stream bed
    c. list major alterations and dates (if known):

12. PHOTO: P11-9

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐ carriage
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Church sets in picturesque small village nestled between the hills.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

History Stenciling is still visiable - brown tones on beige, Iron stove still in foyer.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: ? 1839

ARCHITECT: ?

BUILDER: ?

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Early surviving Methodist structure

21. SOURCES:

His. of the Meth. Church

22. THEME:

Religious

21-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: July 6

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Gordon, Eva Clark ADDRESS: R.D.2, Salem
6. USE: Original: dwelling Present: dwelling
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Set on a hillside on a winding road ~~in~~ the hamlet of Belcher.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Sylvester Reynolds (1900 - 1930c)
to
G. Clark

21. SOURCES: ~~Map~~ Map with help of Horace Day, A. Knapp early 1900's

22. THEME:

22-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bullon DATE: Dec. 28, 1974

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Pres. Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S): Dwelling Brookside
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mrs. Graham Toomey ADDRESS: R.D.2, Salem, N.Y.
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior access: explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: old drug store + P.O.

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets back from winding road thru hamlet of Belcher, across a stream.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Dental molding ~~over~~ under cornice, protruding caps over lower windows, eye brow windows.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1810 - 1820 c

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

One of the building infront of the house was the P.O. & drug store - unchanged, used for storage - charming - shelves for mail.
Dr. I.H. Clough
Pitt Clough
Jenny White
James Gibbons
1934 Mattie McWhorter
Tamie

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Oct. 75'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ~~John Scott~~ Wash. Co. ADDRESS: ~~R.D.2, Salem~~
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: covered with asbestos brick
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: P11-12



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Some early window sash remain 12/8, inside water pump

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: would think before 1820

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES: 1866 Atlas Wm. Day

22. THEME:

24-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ballou DATE: Dec. 3, 75

YOUR ADDRESS: P.O.Z TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Clark House
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION: Co. # 30
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: ~~John Smith~~ Clark ADDRESS: P.O.Z, Salem
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P14-11



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets in a charming early village of mostly Fed. houses.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE


19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Federal House with dentil molding & decorative frieze



decorative caps over windows, nice details.
This was the Methodist parsonage.
John Willis (lived there early 1900's - 1917-18)

J. Smiths

21. SOURCES:

22. THEME:

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in the charming village of Belcher.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c 1820

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Owners: J.F. Maines 1866
J. Kane - carried mail

21. SOURCES:

22. THEME:

26-2

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Joyce Day DATE: 1/14/75

YOUR ADDRESS: R.D.#2 Salem TELEPHONE: 854-3425

ORGANIZATION (if any): Hebron Pres. Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S): Dwelling + Store
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: Belchen
3. STREET LOCATION: Co. Rt. 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Hammond ADDRESS: R.D.#2 Salem
6. USE: Original: Store Present: Store & dwellings
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain yes, partly.


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: 26-3



13. MAP:



HP-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☑ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Building set on narrow winding road in the hamlet of Belcher.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

large cooking fireplace with bake oven, paneled door closes over oven area, another fireplace behind cooking fireplace. Nice wrought hardware, some 12/12 sash.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1790 - 1810c

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1890c John Gibson
John Carver
John Lundy
Albert Clark — Combs
Ina Thompson
Cassius Washburn

21. SOURCES: 1963 - Hammonds - opened in April

22. THEME:

Commercial

Sample

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bullon DATE: July 6, 1975

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Pres. Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Albert Clark ADDRESS: RD2, Salem
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: orchard,

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Set on a corner of a sparsely populated hamlet.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Delicate caps on windows - pierced blocks under eaves and window caps. Beautiful picket fence surrounds yard.



SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1810-1820c

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Was owned by the store owner.

G. Oatman 1866
J. Gibson
John Shields till 1910 (daughters: Mary Foster, Cora McEachron, Ida, teacher Rev. Willard
Albert Clark

Appears to have been built by same builder as Pres. Camp house on top of Presbytery Hill

21. SOURCES:

22. THEME:

11/27



SEP • 77



SEP • 77

11/27



SEP • 77



SEP • 77

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Loren J. McNeil Jr. DATE: January 1975

YOUR ADDRESS: R#2, Salem, N.Y. TELEPHONE: 854-3629

ORGANIZATION (if any): Hebron Pres. Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: ~~Salem~~ Hebron VILLAGE: ~~Belcher~~
3. STREET LOCATION: Halls Pond Road
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Loren McNeil, Jr. ADDRESS: R.D#2 Salem, N.Y. 12865
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: evergreen trees
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
B. Clapp 1866 Atlas
Margaret Slack
Sidney R. Robinson April 1, 1876
Sterlen Young April 1, 1916
Charles F. Hetty Aug. 15, 1923
John J. Higgins March 23, 1946
Herman Ehrnthalt Jr. Oct. 11, 1951
Thomas R. Jones Aug. 28, 1957
Loren J. McNeil, Jr. Aug. 14, 1972

21. SOURCES:

29-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115111
QUAD
SERIES
NEG. NO.

YOUR NAME: Loren J. McNeil DATE: January 1975

YOUR ADDRESS: R#1 Argyle TELEPHONE: 854-3423

ORGANIZATION (if any):

* *

IDENTIFICATION


1. BUILDING NAME (S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Belcher.
3. STREET LOCATION: Rout 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Loren McNeil ADDRESS:
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P14-19A

13. MAP:





HT-1

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Benjamin B. Oatman before 1909
Christine + Issac 1909
Zenus H Bentley 1912
Thomas Steventon 1916
Ethel M. Steventon —
Ruth Steventon 1930
Loren A McNeil 1933 (October)

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Joyce Day DATE: July 6, 1975

YOUR ADDRESS: R.D. 2 TELEPHONE:

ORGANIZATION (if any): Hebron Preservation Soc.

* *

IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Reid Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: John Clark ADDRESS: R.D. Salem
6. USE: Original: farm house Present: farm house
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints [–
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

1926 new kitchen + dining room + wood shed by Gordon Baydin

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: shale ledge in front lawn
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets in open hilly farm land.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Bath was the pantry

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1859 old house burned 1858

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Farm grew potatoes.

Joseph Reid to
Ralph Reid to
J. Clark

21. SOURCES:

Ralph Reid

22. THEME:

farm

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: J. Day DATE: July 6, 1975

YOUR ADDRESS: R.D. 2 TELEPHONE:

ORGANIZATION (if any): Hebron Preservation Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S): Dairy Barn of John Clark
2. COUNTY: Wash TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: John Clark ADDRESS: R.D. 2
6. USE: Original: barn Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible
   Interior accessib

Main farmhouse came from Belcher Hotel

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ ...d and batten ☐ e. cobblestone ☐ f. shingles [ ] other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑ old
   b. wood frame with light members ☑ new
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

1902 30x40 ft. or. barn by Henry Cornell-Silo in corner of barn 2x4 + logs
1923 17x32 ft added on West end 1 row stanchions * main framework came
1950 Lean-to 17x57 making 2 " " from Belcher Hotel
1961 36x63 added on East end (tore off some old + used for machine shed)

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Hilly
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Hilly open farm land.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: —, 1923 addition built from Belcher Hotel

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Old barn by Dewy Cornell

21. SOURCES:

Ralph Reid

22. THEME:

32-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Loren J. McNeil DATE: January 1975

YOUR ADDRESS: R#1 Argyle, N.Y. 12809 TELEPHONE: 854-3423

ORGANIZATION (if any): Hebron Preservation Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION: Warnick Rd.
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Loren McNeil ADDRESS: R#1, Argyle, N.Y.
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):



before ~ 1906

13. MAP:



MAY 15 1947 James V. and IDA McNEIL (1906) To LOREN AND Gladys L. McNEIL

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Set on a hill in rolling farmland, beautiful views.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Eye brow windows

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

F. Russell 1866 Atlas + 1853 Map

21. SOURCES:

33-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: July 6, 1975
YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520
ORGANIZATION (if any): Hebron Pres. Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Crosier Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Maurice Woodard ADDRESS: R.D.2
6. USE: Original: farmhouse Present: farm house
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: P14-34



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐4 b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

hilly farmland

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Building had 12/8 windows - 3 garrison windows in both gable ends + 2 chim. + 3 lights above side door, much earlier than it looks at present, may have fireplaces left.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1810 c

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

~~third~~ house built by early settler - John Cary, 1755-1823, orig. was a log cabin just to the left* of the existing house. *south
2nd house of existing house
Owners. Partial list: John Cary, John Cary, Jr.
Isaac Oatman
Mrs. Isaac Oatman
Joe Eagle
M. Woodard

21. SOURCES:

John Cary 1755-1823 by Rev. Seth Cary

22. THEME:

John Cary 1755 - 1823
by Rev. Seth. C. Cary
Dorchester Center, Bos. Mass 1908
Murray + Emery Co., Bos. Mass.

John Cary's parents: James Cary; Anne Taplin
" " born Kinderhook, Columbia Co. Feb. 23-1755

Enlists as priv. in Revol. in Preston, Conn.
Company of Capt. Ebenezer Witter
Served 6 days

Again enlists May 19-1775, 4th Co.
Capt. Obadiah Johnson + 3rd Reg.
of Col. Israel Putnam

Bought a farm in Halifax, Ver. next his father Sept. 23

1777 hired someone to go to service in him so he could plant his crops, man killed at Saratoga.
He went to Battle of Benn. but was to late

Married Mary Rude Nov. 12, 1780
moved up Conn. Riv. then up the Deerfield Riv.
where they first lived

(1) Daughter born: Susannah — 1781 b. d. 1847 Castile, N.Y.
Halifax, Ver.
moved again to Hud. Valley - farm on White Creek in Salem and two others near Belcher, north + east,
4 sons - 4 daugh. - 4 became school teachers

4/29/1783
Bought Alex. Kennedy farm north half of (lot 21) Kempe Pat.
119 acres - paid 100 pounds - paid Feb. 7, 1816
boardered on east by Alex. Webster who came from Scot. 1772,
" on north by Jonathan Clough
Also bought (lot 38)
when Carys settled in Hebron there were no schools,
or church but it was organ. few years later by the
Pres. — they were miles from a gristmill

① Log Cabin - built first S.W. corner, just east of the little brook where it crossed the road.
1783 - out grew cabin
Settled - when the settled on Lot 21 they had 2 child.

② built sec. house west of present Woodard house
③ later years frame house Woodards was built


Died April 2, 1823

Children

2- James b. White Creek, N.Y. (Salem) d. North Creek, N.Y. 1865
war of 1812 M. Abagail Leonard 1790-1874
3- Catherine b. Belcher 1785 m. Geo. Liddle d. Johnsbury 1865
(one of her daug's, Rachel, married Isaac Morehouse, 7 child)
4- Isaac b. Belcher 1787 m. Anne Barton (12 child)
soldier in war of 1812 - liv. Minerva + Troy
5- ~~Daniel b.~~
Olive b. 1789 m. Simon Barton d. 1867 liv. Moriah, N.Y. about 1820 moved
6.- Mary - b 1791 - invalid lived home, d. 1849

7. John Cary, Jr. 1793 - 1865
was willed his father's farm, war of 1812 priv.
he recieved 160 acres
taught sch. 1815-16 - m. Catherine Cooley

8. Geo. b. 1799 Belcher d. Castile, N.Y. 1844 - sch. teacher
m. Adaline Burlingham



1908 from the Cary Book

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Oct. 3, 1975

YOUR ADDRESS: P.O.Z TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Crosier
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mrs. Dorthy Mitchell ADDRESS: 85 Hudson St. Hudson Falls, Ny. 142 John St.
6. USE: Original: home Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P16-5

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☑ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: one barn burned 1950

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets in rolling hills

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
1800's Gibson - ran the store in Belcher
1947 - Lydecker

21. SOURCES: 1866 Atlas - H. Hurd
1853 Map - A.C. Wood

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

35-3

YOUR NAME: Howard J. Crosier DATE: _____

YOUR ADDRESS: Salem N.Y. R.D.2 TELEPHONE: 854-3537

ORGANIZATION (if any): _____

* *

IDENTIFICATION

1. BUILDING NAME(S): Farm
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: Crosier Rd.
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Howard J. Crosier ADDRESS: _____
6. USE: Original: Farm Home Present: Farm Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain _____

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

Addition to House in 1941 - 3rd addition removed 76'

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Approximately 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Crosier in 1866 Atlas

21. SOURCES:

22. THEME:

56-5

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Gilbert H. Flint DATE: Jan. 10 - 1995

YOUR ADDRESS: Salem - N.Y. TELEPHONE: 518 854-3539

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION


1. BUILDING NAME (S): Flint Homestead
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Crosier Road
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Gilbert Flint ADDRESS: Salem - N.Y.
6. USE: Original: living quarters Present: living quarters
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible Explain Yes

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Addition of 1½ story part

12. PHOTO: 95-5A (N)



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☒ c. garage ☒
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☒ h. gardens ☒
i. landscape features: White House on Knoll
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☒ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) ?

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Three Picture windows installed in 1912
large stone fire place made of 4 kinds
Stone from the farm

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: ?


ARCHITECT: ?

BUILDER: ?

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
One of the first 3 residences
located in the Town of Hebron
Log Cabin built on site about 1770.
J. Crosier in 1866 Atlas

21. SOURCES:

22. THEME:


N
WOODS
WOODS
POND
FIELDS
CHAMBERLIN MILLS ROAD
FIELDS
1
2
3
4
5
BLACK CREEK
POND
NW
SE
PREVAILING WINDS
SWAMP
WOODS
BUILDING LEGEND
1 - MARY ANN CLARK HOUSE
2 - CHAMBERLIN RESIDENCE
3 - PECK RESIDENCE
4 - SWIFT RESIDENCE
5 - BOVEE RESIDENCE
6 - DUNBAR HOUSE
7 - GRIST MILL
TIPLADY ROAD
WOODS
FIELDS
FIELDS
TIPLADY ROAD
FIELDS
ALLEN ROAD
AREA SURROUNDING
CHARCOAL PLANT OF
HEBRON VALLEY PRODUCTS CORPORATION
SCALE 1"=660 FEET
CHARCOAL PLANT
HOUSES
3/21/74
CDS

51-5
37

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/111
QUAD
SERIES
NEG. NO.

YOUR NAME: _____ DATE: 75'

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): _____

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: Chamberlin Mills R.D.2
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Meredith Wilson ADDRESS: R.D.2, Salem
6. USE: Original: farmhouse Present: farmhouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: slateroof
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

12. PHOTO: P.7 - 11A



13. MAP: #22



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: Mill, milk house now studio

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
3 fireplaces, added one

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1820-25

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Basement high for potatoes,
Isaac Wilson, built for him when married
to
John Fraser to
Isaac Wilson to
John Allen to
William Glines to Bebe estate, broths + sis. Wilson

21. SOURCES:
Meredith Wilson
1853 Map I. Wilson

22. THEME:

38

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Gertrude Gettys DATE: July 8, 1975

YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854 7610

ORGANIZATION (if any): Hudson Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlin Mills Rd.
4. OWNERSHIP: a. public ☐ , b. private ☒
5. PRESENT OWNER: Mrs. Meredith Hilson ADDRESS: Salem, N.Y.
6. USE: Original: Dwelling house Present: Same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: 25-2



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c1786

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

James Wilson (one of them - were 3-4 James)
Came from west Greenwich, R.I.

21. SOURCES: Meredith Wilson
1853 Map - J. Wilson

22. THEME: Early Settlers

39-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: C. Donald Swift DATE: September 4, 1975

YOUR ADDRESS: Chamberlin Mills Road, Salem, N.Y. 12865 TELEPHONE: 518 854-7291

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Mary Ann Clark house
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Salem
3. STREET LOCATION: Chamberlin Mills Road near Tiplady Road
4. OWNERSHIP: a. public ☐ b. private ☒ 144 Grafton St.
5. PRESENT OWNER: Leon Chamberlin ADDRESS: Chevy Chase, Maryland 20015
6. USE: Original: Store and residence Present: Storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Not ordinarily


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: Solid plank walls
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. m oad bearing walls ☐
   d. m plain) ☐
   e. other Solid plank walls - stacked 1"x 5"
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? ☐
    c. list major alterations and dates (if known):
    Unknown
    Several alterations date unknown

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☒
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
One of a group of seven buildings surrounding Chamberlin Mills

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Circa 1840, possibly earlier

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Location of a store and repair shop serving Chamberlin Mills community

21. SOURCES: 1853 Map. B. Clark

22. THEME:

40-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: C. Donald Swift DATE: September 4, 1975
YOUR ADDRESS: Chamberlin Mills Road Salem, N.Y. 12865 TELEPHONE: 518-854-7291

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Chamberlin Residence 2
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Salem
3. STREET LOCATION: Chamberlin Mills Road near Tiplady Road
4. OWNERSHIP: a. public ☐ b. private ☒ 144 Grafton St.
5. PRESENT OWNER: Leon Chamberlin ADDRESS: Chevy Chase, Maryland 20015
6. USE: Original: Miller's House Present: Summer residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private residence


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent, ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? Appears to be 1920-30's
    c. list major alterations and dates (if known):
    At least one, date to be determined
    Picture windows and 2 porches, fireplace

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

One of a group of seven buildings surrounding Chamberlin Mills

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: About 1780

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Believed to be the miller's house built in connection with the saw mill and grist mill

21. SOURCES:

1853 Map - L. Chamberlin

22. THEME:

41-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: 10/3/75

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Corn Crib and Carriage Barn
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Chamberlin's Mills
3. STREET LOCATION: Chamberlin's Mills Road
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Leon Chamberlin ADDRESS: 144 Grafton St., Chevy Chase, Md. 20015
6. USE: Original: barn Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☑
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: house

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

42-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: C. Donald Swift DATE: August 8, 1975

YOUR ADDRESS: Chamberlin Mills Road, Salem, N.Y. 12865 TELEPHONE: 518-854-7291

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Swift residence 4
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Salem
3. STREET LOCATION: Chamberlin Mills Road near Tiplady Road
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: C.Donald Swift ADDRESS: Chamberlin Mills Road, Salem, N.Y.
6. USE: Original: Store & Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private residence


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. mo[illegible] if so,when?
    c. list major alterations and [illegible]nown):
    At least three, dates unknown

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: Adjacent to mill and stream

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
One of a group of seven buildings surrounding Chamberlin Mills

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Beautiful grape vine stencil and grained doors in dining room
side porch is randed at corner and has a marble floor.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Circa 1840, possibly earlier

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Location of store serving Chamberlin Mills community

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Baillon DATE: 10/3/75

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society


* *

IDENTIFICATION


1. BUILDING NAME(S): Carriage House
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Chamberlin's Mills
3. STREET LOCATION: Chamberlin's Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Donald Swift ADDRESS: R.D., Salem
6. USE: Original: carriage house Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☑ if so,when?
    c. list major alterations and dates (if known):



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Mill pond
j. other: Mill + houses

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Building is located next to the mill behind the Swift house in the Chamberlin's Mill Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

44-1

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: C. Donald Swift DATE: August 9, 1975

YOUR ADDRESS: Chamberlin Mills Road TELEPHONE: 518-854-7291
Salem, N.Y. 12865

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION


1. BUILDING NAME(S): Grist Mill 7
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Salem
3. STREET LOCATION: Chamberlin Mills Road near Tiplady Road
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: C. Donald Swift ADDRESS: Chamberlin Mills Road, Salem, N.Y.
6. USE: Original: Sawmill and grist mill Present: Storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Yes, but closed and locked


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P 1-24-30

13. MAP:





CDS 9/1/74

SWIFTS' CHAMBERLIN MILLS

The first sawmill was built on this site in 1778 and was operated by a partnership of six early settlers which included four Wilson brothers and was known as Wilson's mills. A grist mill was added in 1780 or 1781. In 1809 the mills were taken over by Palmer Jenkins and in 1818 the first of four generations of Chamberlins began operating the mills. Later, a cider press was added. Mill operation was discontinued in 1934 and the property was purchased by the Swifts in 1945.

There are interesting views of the 60 acre pond formed by the 14 foot high concrete dam across Black Creek and of the water cascading over the dam. The concrete supports for the large wooden pipe which carried water to the water power wheels may still be seen. The sawmill, now the location of a garden, has been removed but the remainder of the slate-roofed building, occupied by the waterwheels, grist mill and cider press, is still in sound condition. The heavy wood framing timbers, fastened together with wooden pins are of interest, as are the cider press, the grist mill and the old office. The large wooden box housing the two 50 horsepower water wheels, the wheels themselves and the many shafts and pulleys for transmitting the power to the machinery may be seen from the ground floor of the mill building.

Six of the houses which surrounded this early-day industrial complex, which also included a distillery and a fulling mill, as well as a post office, hardware store and blacksmith shop, are still in use. Across Black Creek is the charcoal mill which is presently operated by the Swifts.

Material from Mr Swift

Dr Mill

1778, by Wilson, Hamilton and Hopkins, who owned the water-power. The grist-mill afterwards passed into the hands of Palmer Jenkins. We add a copy of hte original contract, one hundred years old, procured by Hon. E. S. Spoor, the property of Chester H. Wilson. The latter also has the original survey of Campbell's Patent: "Articles of agreement made and passed between John Hamilton, David Wilson, Robert Wilson, John Wilson, James Wilson, and David Hopkins.

"Article 1. -That they agree to build a saw-mill on the falls on the Great cree, and each to do his equal part and propórtion.

"Article 11. OAn when money is to be paid, each to pay his equal sixth part.

"Article 111. -That when the jajority of the proprietors shall agree upon any point about the said mill, the rest are to abide by it.

"Article 1V. -That each ohe is to be at the place, ready to go to work, each day he works, by the sun an hour and a half high in the morning.

"To which agreement we bind ourselves. Witness our hands this 22d day of March, A.D. 1778.

"John Hamilton,
"David Wilson,
"Robert Wilson,
"John Wilson,
"James Wilson,
"David Hopkins."


James, a son of the James Wilson above, states that the same company built a grist-mill, probably two or three years later. It was on the site of Chamberlain's mills, and was orginally known as Wilson's. Asa Putnam built a cloth-dressing mill at the same place earlier than 1800.


Important man buried in old cemetery *Pg. 386*

Hon. Alexander Webster came from Scotland about 1772, and settled about three miles north of West Hebron. His children were two daughter and three sons. Nelly, one of the daughters, married Deacon John Steel, and the other, Mary, became Mrs. Garrett Quachenbush. The sons were George, James, Alexander, Jr. George succeeded to the homestead, which was afterwards occupied by his son, Simeon D. Webster. The old house and a portion of the

farm is now owned by J. Beattie.

Judge Alexander Webster, Sr., was, in his day, the prominent man in the town. His house, built at an early period, and still stadning, in a beautiful grove was for those days and elegant mansion. He was State senator from 1777 to 1785 inclusive, and from 1790 to 1793. He was a member of Assembly in 1788-89. He was the first judge of the court of common pleas in 1786, and was also a supervisor of the town. He died in the year 1810.





45 T

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 11511
QUAD
SERIES
NEG. NO.

YOUR NAME: C. Donald Swift DATE: October 14, 1975

YOUR ADDRESS: Chamberlin Mills Road TELEPHONE: 518-854-7291
Salem, New York 12865

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Hebron Valley Products Corporation Charcoal Plant
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Tiplad Road south of Black Creek
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: C.D.Swift ADDRESS: Chamberlin Mills Road, Salem, N.Y.
6. USE: Original: Hay barn Present: Charcoal Plant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain By arrangement


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☒
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☒ if so,when? 1965
    c. list major alterations and dates (if known): In 1965 barn was dismantled, and framework and slate were erected on a new concrete slab base. The extension on the road side of the building was made in 1967.

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐ Control house building
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: Adjacent to pond and stream

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Across Black Creek from the historic Chamberlin Mills.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Was formerly the location of a fulling mill.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Unknown

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

46-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: C. Donald Swift DATE: August 8, 1975

YOUR ADDRESS: Chamberlin Mills Road, Salem, N.Y. 12865 TELEPHONE: 518-854-7291

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Bovee residence 5
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Salem
3. STREET LOCATION: Chamberlin Mills Road at Tiplady Road
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: C.Donald Swift ADDRESS: Chamberlin Mills Road, Salem, N.Y.
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private residence


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☒ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: Adjacent to dam and mill pond and mill

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

One of a group of seven buildings surrounding Chamberlin Mills

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Basement once used for storage of cider barrels

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Circa 1840

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

47-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: C. Donald Swift DATE: August 8, 1975

YOUR ADDRESS: Chamberlin Mills Road TELEPHONE: 518 854-7291
Salem, New York 12865
ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Dunbar House 6
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Salem
3. STREET LOCATION: Chamberlin Mills Road near Tiplady Road
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: C. Donald Swift ADDRESS: Chamberlin Mills Road, Salem, N.Y.
6. USE: Original: Residence Present: Residance
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain Private residence


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:


9. STRUCTURAL SYSTEM: (if known)
a. wood frame with interlocking joints ☒
b. wood frame with light members ☐
c. masonry load bearing walls ☐
d. metal (explain)
e. other

10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?
c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐ ice house X
i. landscape features: adjacent to dam and mill pond
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: adjacent to dam and mill pond

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

One of a group of seven buildings surrounding Chamberlin Mills

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Circa 1840

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

48-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: C. Donald Swift DATE: September 4, 1975

YOUR ADDRESS: Chamberlin Mills Road Salem, N.Y. 12865 TELEPHONE: 518-854-7291

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Peck Residence 3
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Salem
3. STREET LOCATION: Chamberlin Mills Road near Chamberlin Mills
4. OWNERSHIP: a. public ☐ b. private ☒ Chamberlin Mills Road
5. PRESENT OWNER: Hollis D. Peck ADDRESS: Salem, N.Y. 12865
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private residence


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    Several, dates unknown

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

One of a group of seven buildings surrounding Chamberlin Mills

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: About 1780

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES: 1853 Map - Mrs. Stevens

22. THEME:

49-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ballou DATE: Oct. 75'

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlin's Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Al Baltz ADDRESS: R.D. Salem
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: house (main)

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located between W. Hebron His. Dist. and Chamberlin's Mills Hist Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

50

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ballou DATE: Oct. 75

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

Beautiful example of Cape Cod style "Deep-keep" square hewn log frame

* *


IDENTIFICATION

1. BUILDING NAME(S): LOG CABIN
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Heaphy Rd. off Chamberlin's Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: James Conway ADDRESS: R.D. Salem
6. USE: Original: early settlers cabin Present: summer home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. ston ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: hewn logs - slate roof
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other hewn logs
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐ recently repointed + fireplace added
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: rolling hills
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located close to the area of the earliest settlements. One later house very close to cabin and a new house, 1975, directly ahead of cabin, over looks the Vermont mountains.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Built with fine craftsmenship, square hewn logs with carefully dovetailed corners

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c1801

ARCHITECT: ~~Sam~~

BUILDER: Samuel Guthrie, presumed

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

In 1801 the west side of lot 14 on the DeForrest patent was purchased by Samuel Guthrie, Sr. who we presume built the log cabin. It is a beautiful example with dove-tailed joints. Had been covered with clap boards but where removed in the 1930's The only log cabin known in Washington County to be this untouched, some are known but with many alterations.

21. SOURCES: Deeds, Mrs. Conway
1853 Map. S. Guthrie
1866 Atlas - D. Guthrie

22. THEME: Early Settlers

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Billm DATE: Oct. 75'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Ferguson Lane
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Donald Shrinbunger ADDRESS: R.D.2, Salem
6. USE: Original: farm house Present: same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Building on the fringe of W. Hebron Hist. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES: 1853 Map - D. Clemmons

22. THEME:

52-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Oct. 75

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S): Williamson Place
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Ferguson Lane
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Harold McEachron ADDRESS: R.D. Salem
6. USE: Original: Farm House Present: vacant only barns used
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shi
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interl
   b. wood frame with light
   c. masonry load bearing wa
   d. metal (explain)
   e. other


pre-Civil War house. Earliest farmer attained land from a Grant

10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑S b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: Stream

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Located on the edge of W. Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES: 1853 Map J. Guthrie

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

52

YOUR NAME: MacClay Farms Inc. DATE: October 27 1975

YOUR ADDRESS: East Hebron Rd. Salem N.Y. 12865 TELEPHONE: 518-854-3438

ORGANIZATION (if any): Hudson Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Farmstead - House + 3 barns
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Rural
3. STREET LOCATION: Williamson Hill - Ferguson Lane
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: MacClay Farms Inc ADDRESS: Salem
6. USE: Original: Farmstead Present: buildings - storage; cropland worked
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain No

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☒
   d. metal (explain)
   e. other slate roof
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☒
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    None

12. PHOTO: 13. MAP:

You took this picture
it was a nice

HP-1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☒
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☒ c. garage ☐
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: rolling farm land 130 acres
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) No
Pre-Civil War Period House

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
"end of the road" location

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Pre-Civil War

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Earliest ~~owner~~ ness attained land from a grant 134 acres.- Mary Ann Campbell (1837-1884)
Mr. John Williamson, farmer - Sept. 2, 1868
Son Wesley b. July 1869
Property owned by James & Harriet G.N. Moore
sold to John Williamson Aps. 1, 1865
also property owned by David & Mary Culbertie sold to
John Williamson Mar. 12, 1860 Laurence Betty, Orphan
21. SOURCES: ~~Wesley~~ Williamson to McEachron
Deeds - Wash Co. Dodge Land
Book 54-pg. 28 Book 210 - pg 393
63-436 " 267 - pg. 147 to Hasbel McEachron
Mar. 4, 1958, 10 Ac.
22. THEME:

Further info. on Williamson Hill Farm owned by
Mac Clan Farms Inc.

found at Washington County Bldg.

Book 54 - Page 280 -

63 - 436
210 - 393
287 - 147

Deeds copied + available thru Harold McEachron
Pres. Mac Clan Farms Inc
Salem, NY.

Earliest owners obtained land from grant -

134 acres - Mary Ann Campbell (1837-1884)
m. John Williamson, farmer Sept. 2, 1868
had son Wesley July 1869

Property owned by James More + Harriet G Moore
sold to John Williamson April 1, 1865

also property owned by David and Mary Guthrie
sold to John Williamson March 12, 1866

property passed to son ~~Wesley~~ Williamson
then to (W. W.) Nephew, Lawrence Getty
→ Harold McEachron Mar. 4, 1950
sold to
then to
now owned by → Mac Clan Farms Inc. 1965
Harold McEachron Pres.

53-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Jan. 75'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: James Clark ADDRESS: R.D.2
6. USE: Original: home - farmhouse Present: home - farmhouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: siding added 1974
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ 2 b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

was Alex. Gourlay home on 1853 Map (Levey)

Clifton Day (Gourlay was his uncle)
Bennett

J. Clark

21. SOURCES:

22. THEME:

54-2

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE:

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Historic Committee

* *

IDENTIFICATION

1. BUILDING NAME(S): Flack House (Joe Brillon residence)
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Route 30 2½ miles no. of W. Hebron
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Joe + Sally Brillon ADDRESS: R.D. 2
6. USE: Original: Farm house Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):


Bathroom 1930's, built in kitchen 1971, elec. heating system 1968

12. PHOTO:

James Flack House



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☑
i. landscape features: rolling fields, stream, swamp
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: neighboring barns and farm houses

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) House sets on slight rise in a wide valley, fields in the valley and forests on the hill tops

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Note enclosed article

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1789c

ARCHITECT: _____

BUILDER: probably James Flack, Sr. & Jr.

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
One of few remaining early settlers homes left in fine condition. Very little was done to harm ~~the~~ its integrity through the years. ~~Elem~~ Center chimney homes are the exception in this area. The keeping room is a fine example of a Colonial interior, pine beaded sheathing and eight raised panels above the 10' stone + brick fireplace + bake oven.

21. SOURCES: 1853 Map - Alex. McWhorter
County clerks office - records of deeds and mortgages

22. THEME: Argyle: Then, Now & Forever

Early settlers - farmers

115/11 54



James Flack and his six-year old son, James Jr., came to Salem in 1767 with the famed pioneer preacher, Dr. Thomas Clark. They were two of Dr. Clark's 300 member imported Presbyterian congregation of Monaghan and Balliby, Ireland, who came to America to avoid, ironically enough, the troubles in Northern Ireland.

James Jr. eventually settled in the Hebron Valley where the house pictured is located, two and a half miles northwest of West Hebron on Route 30 toward Belcher. His early deed states: "This indenture made the twenty-fifth day of June in the thirteenth year of the Independence of the State of New York and in the year of Our Lord one thousand and seven hundred and eighty-nine." He obtained 119 acres on the northside of Lot 2, for 95 pounds, from the heirs of John Morin Scott, who in 1764 was granted 10,000 acres with John Kempe as a result of serving in the French and Indian war (thus the Scott-Kempe Patent).

Judging from the style of the house and the Flack deed in 1789, it would seem the house was built at this time even though in the attic there is a beam with the date of 1746 carefully carved into it. The house is post and lintel construction with plank walls all of chestnut set on a dry wall, stone foundation. After removing split lathe, four rooms of hand-planed, beaded pine sheathing was recently found. The house was heated by a central chimney having four fireplaces. The stone cooking fireplace has a five foot opening with a bake oven and ash pit on the side. The wall above this fireplace has eight raised wooden panels.

The dining room has a built-in raised panel corner cupboard and another small cupboard built into the fireplace wall above the bare oven, where perhaps herbs were kept dark and dry.

It is told that behind the borning room was a very large iron kettle, the type used for scalding hops, into which water ran continually from a spring far up the hill. During various digging projects, several sections of lead pipe were found.

Two of the bedrooms have bedwalls or bedsinks, recesses under the eaves where the beds were placed. These are thought to have been added during the mid 1800's.

Legend tells that there was a secret room in the base of the great chimney where the inhabitants could hide during Indian raids and that there was a separate flue to bring the oxygen. There are five flues, with only four fireplaces, but it has been found that the fifth flu leads from the bake oven.

After the house was sold by James Flack Jr. in 1826, the following people have owned it: Alexander McWhorter, Franklin Day, Andrew and Jessie Foster, Loren McNeil, W. Fortune, and Rose and Elinor Haddock. The present owners, Joe and Sally Brillon purchased the house in 1967 and are making extensive repairs to the interior. The exterior has been painted red.

55-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Baillon DATE: Oct. 3, 1975

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Roosevelt Reid to A. Craig ADDRESS: R.D.2, Salem
6. USE: Original: farm house Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: slate roof
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    addition to the west about 1972

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: slightly rolling hills
j. other: open well

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Wainscotting in kitchen 1870 type, also kitchen cupboards of that period middle part of the house the oldest, had a fireplace

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1853 map H. Pierce
also owned by Rogers

21. SOURCES:

22. THEME:

56-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Baillon DATE: Jan. 75'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Barnblat + Mount ADDRESS: R.D. Salem
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when? under reconstruction
    c. list major alterations and dates (if known):

Extensive reconstruction 1974-75'

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: reconstruction

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: hill + stream
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: (1800c)

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

This house was built as a center chimney home — when a bathroom was added the chimney was removed. Several mantles were there in 1974. Plank construction

1866 Atlas — Rogers

early 1900's Norman Williamson + son Lawrence

21. SOURCES:

close observation of interior in 1973

22. THEME:

57-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Jan. 75'

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Robt. McGreevy ADDRESS: R.D. 2, Salem
6. USE: Original: home - farmhouse Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Being remodeled 1974-75

12. PHOTO: P6-11



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: on a side hill with fields and woods behind

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1888

ARCHITECT: Andrew Beveridge

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Orig. owned by Andrew Beveridge

21. SOURCES:

22. THEME:

58-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ballin DATE: Jan. 75

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: John McFarland ADDRESS: R.D. 2
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: P6-16



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Owner says 1844 - seems earlier

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1853 - I. Thompson
1866 Atlas N. Reynolds

21. SOURCES:

22. THEME:

59-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brilin DATE: Jan. 75'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S): District School #2
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Adeline Dasard ADDRESS:
6. USE: Original: school house Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☑ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☑
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: P6-17



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: swamp
j. other: neighbors barns

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Set on the edge of a swamp.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1844

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Originally built as one of Hebrons one room schools, known as Salem School. or Brick School



Front did look like this.

21. SOURCES:
John McFarland

22. THEME:

Education

60-2

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: _____ DATE: _____

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): _____

* *


IDENTIFICATION

1. BUILDING NAME (S): _____
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Robt. Webber ADDRESS: 105 Tregarone St, Timonium Md. 21093
6. USE: Original: home Present: abandoned
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingle ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO: 115-3A



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: hill, stone walls
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets on a hill close to valley, stone walls and fields

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):


This house has and had some of the best architectural features of any house in Hebron, modillions under the cornice [F] [S], had two fireplaces, 6 panel doors, center stairs with ornaments on side, caps with modillions over windows, plank house,

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1790-1800c

ARCHITECT: _____

BUILDER: _____



20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Saw mill built on the property 1910-15
Cobbers shop near road

1866 - Pierce
Ed Bevridge (saw mill)
1853 Map - Ackley on Hall

21. SOURCES:

22. THEME:

61-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Oct. 3, 1975

YOUR ADDRESS: R.D.2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Robt. Webber ADDRESS: 105 Tregarone St. Timonium, Md. 21093
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: Slate roof
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? ?
    c. list major alterations and dates (if known):

12. PHOTO: P 15-11



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: house

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Building sets close to the road

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Thought to have been a cobblers shop

21. SOURCES:

22. THEME:

62-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Alvin W. Stewart DATE: Dec. 1974

YOUR ADDRESS: R.D. #2 Salem, N.Y. 12865 TELEPHONE: 518-854-7222

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/~~CITY~~: HEBRON VILLAGE: ~~West~~ Hebron
3. STREET LOCATION: West Hebron - Belcher Road
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Alvin W. Stewart ADDRESS: R.D. #2, Salem, N.Y.
6. USE: Original: Dwelling Present: Dwelling
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: P6-19



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☒ e. shed ☐ f. greenhouse ☐
g. shop ☒ h. gardens ☒ STORE HOUSE ☒
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets in the valley with fields and woods.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Between 1855 and '60

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

J. F. Randles in 1866 Atlas

21. SOURCES:

22. THEME:

63-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bullen DATE: July 6, 1973

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Pres. Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Geo. Mallary ADDRESS: R.D.2
6. USE: Original: house Present: house
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Eye brow windows

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Geo. Ferguson ?
Burr Harwood

1866 - Map - A. Johnson

21. SOURCES:

22. THEME:

64-2

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: James Jarrell DATE: 9/30/74

YOUR ADDRESS: 336 West Main TELEPHONE:
Rockaway, N.J. 07866

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S): House and farm buildings
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: —
3. STREET LOCATION: Route 31 - 1½ mi no. of West Hebron
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: James Jarrell ADDRESS:
6. USE: Original: Farm family residence Present: Family residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain private home


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☒
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): 1948 - exterior renovation
    heating system
    bathroom

12. PHOTO:



13. MAP



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☒
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: located on hill with lawn + trees
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: rural

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
2-3 mile proximity to community and other historic (1775-1800) homes

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Cape cod style, back roof eave slopes to 1st floor level
H+L hinges, original floor + room arrangement
Double fireplaces (back to back)

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: late 1700's
ARCHITECT: ? Earliest known owner - John J. McClellan
BUILDER: ?

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
one of earliest houses in area

21. SOURCES: family history

22. THEME:

Where the Southwest corner of the town of Hebron meets the Town of Argyle, Washington County, the McClellan Homestead was established about 1780 by Alexander McClellan, his wife and 2 sons. The had left County Monaghan, Ireland in 1770 because of the religious persecution of Protestants. After landing in America, they stayed in Philadelphia for some time then moved to Schenectady, Stillwater, and then Hebron.

Alexander McClellan and sons James and William were listed as first members of the Associate Reformed Church (now United Presbyterian church of Hebron) whose congregation was organized 1780.

The McClellan property passed from the first settler, Alexander, to his son James, then to his son, John Stewart McClellan who willed the farm to his son, James E. McClellan; who then willed it to his daughter, Mrs. Foster McEachron. Harold McEachron purchased the farm from his mother in 1941. The original house on this farm was restored in 1948 by Mrs. Foster McEachron (great grand-daughter of the original settler) and occupied by Mr. & Mrs. Robert C. Young. In 1972 James Jarrell of Rockaway, N. J. purchased the house and 5 acres.

This James E. McClellan built a new house on the farm, across the road from the original house, in 1882 at the time of his marriage to Mary Sill of North Argyle. They had one daughter, Marian (Mrs. Foster McEachron).

Certain details of interest are found in the James E. McClellan diary kept while building this house.

> Carpenters bill $325.42 part of which was paid in butter at 30¢ per pound.
>
> 13 Chestnut doors cost $11.20
>
> Newell post $5,00

This house was sold in 1941 to Harold McEachron who operated the

farm land in conjunction with his farm on Route 30 Salem.

The house was remodeled in 1947 at the marriage of Harold McEachron to Pearle Roberts of Waterville, New York.

In 1972 the house and 2½ acres was sold to Mr. & Mrs. Theodore Henning of Princeton, New Jersey.

In 1973 the house and 2½ acres was sold to Mr. & Mrs. Edmond Reid of Camden Valley, New York.

The remaining 152 acres of cropland, pasture land and forest are still owned and operated by MacClan Farms, Inc. of Salem. Harold McEachron is great, great, great grandson of Alexander McClellan, the original settler.

Compiled for Historic
Highlights of Hebron
October 1974.

65-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Edmond Reid DATE: 9/30/74

YOUR ADDRESS: RFD. Salem, N.Y. 12865 TELEPHONE:

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S): House & shed E. Reid residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: —
3. STREET LOCATION: Route 30 - 1½ miles No. of West Hebron
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Edmond Reid ADDRESS: Salem NY. RD #2
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain private home


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    built 1882 -
    1941 - kitchen, central heat interior decoration
    1973 - new heating system remodeling rooms

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☒
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: below road level, along brook
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: rural

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Opposite original home (1775-1800) of farm owner - in area of many historic homes

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Mid 1800's - 2 story

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1882

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Panels under the windows (interior), molded plaster design on ceiling (circle),

21. SOURCES:

22. THEME:

66-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Baillon DATE: July 6, 1975

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Pres. Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Harold & Mabel Worthington ADDRESS: R.D.2, Salem
6. USE: Original: Farmhouse Present: Farmhouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: slate roof
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☑ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐ henhouse, ~~pump~~
i. landscape features: _____
j. other: part of one barn was house, moved from immedia corner

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

House sets in valley floor, land rises around it,

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Eye brow windows

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Farmhouse

Patterson
Jas. Crozier Sr. 1910

21. SOURCES: 1866 Map M. Dougan

22. THEME:

67-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillm DATE: Jan. 75'

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Rout 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Michael Preziose ADDRESS: Jericho, Vt.
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: hill + stream
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Previous owners: (not complete)
— Donaldson Lashey
— H. Worthington
— Markham
— Mrs. Mallory
— Henry Brownell

21. SOURCES:

22. THEME:

68-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Jan. 75'

YOUR ADDRESS: R.D 2 TELEPHONE: 854-3520

ORGANIZATION (if any): ~~Salem~~ Hebron Preservation Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mrs. Adelade Mieth ADDRESS:
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES: not shown in 1853 map, shown on 1866

22. THEME:

364-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillen DATE: Nov. 30

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Higgins Rd.
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Higgins ADDRESS: R.D. Salem
6. USE: Original: farmhouse Present: farmhouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____


15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☑ e. sheds ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: rolling fields - woodlots
j. other: sap house

16. SURROUNDINGS OF THE BUILDING -(check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Ceilings in some rooms have wood covering, narrow boards, beaded laid in a pattern. Doorways + window have heavy molding



SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c 1870-80

ARCHITECT: —— Percel

BUILDER: _____, he was a mason

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Percel's sold their entire crop of potatoes 21,000 bushels and used the money to build this house - got between 2-3 thousand dollars.

This farm has always had a good sugar bush; has an operating sap house.

Higgins bought in 1917 and have always had a dairy. Some milk went to the cheese factory in E. Hebron in the summer - Salem in winter.

21. SOURCES:

Mrs. Higgins

22. THEME:

Farming

70-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115111
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brilles DATE: Nov. 30

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Sheldon Farm
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Sheldon Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Steve Sheldon ADDRESS: R.D., Salem
6. USE: Original: farmhouse Present: farmhouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: hilly
j. other: sap house

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Farm sets up on a hill out of E. Hebron

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Federal period house with eye brow windows and deep set center doorway. Triangular window with divisions in the peaks of the gable ends.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Well estab. sugar bush, sap house – Farm grew potatoes

21. SOURCES:

22. THEME:

Farming

71-2

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Nov. 30, 1975

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): United Presbyterian Church
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: E. Hebron
3. STREET LOCATION: Route 22
4. OWNERSHIP: a. public ☑ b. private ☐
5. PRESENT OWNER: Presby. Church ADDRESS: R.D., Salem
6. USE: Original: Church (same) Present: same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain for services or meeting


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: 05-20-20A



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Church sets in E. Hebron, oldest settlement in town of Hebron

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Bell tower with bell, however it is a new bell.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1846 at a cost of $1,500

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

History of Church included

21. SOURCES:

Wash. Co. His. 1878
Caroline Wilson his.

22. THEME:

Religious

115/11/71

Mrs. Caroline Wilson Write... History Of Hebron Presbyterian Church

The Hebron Presbyterian church, midway between Salem and Granville on route 22 will be 150 years old this year. The exact anniversary falls on the 24th of February and was noted in the services of the church last Sunday. Mrs. Caroline Wilson, long a resident in Hebron, with many descendants located there, gave a short historical report of the founding of the church. The congregation will meet, according to the pastor, Rev. Cecil Plumb, on April 13 to make final arrangements for more ambitious celebrations in the warmer weather. Mrs. Wilson's sketch follows.

The Hebron Presbyterian Church

In 1769 or 1770 three men from Rhode Island came to this vicinity to establish homes. David Whedon located on the farm now owned by Frederick Burnham. John Hamilton located on the farm now owned by Norman Williams and Robert Creighton located on the farm now owned by Archie White. In 1772 seven families from Little Nine Partners, Dutchess county, New York, bought 1,000 acres of land from the Campbell patent and established homes here. This part of the country was a wilderness at that time. There were no roads, no post-office, no schools, no churches and no stores. The newest stores were at Lansingburg and Whitehall. These settlers built log cabins with fireplaces and lived from off the land.

They were a Godly people. Each morning family worship was held in their cabins. The father would read from the Bible and offer a prayer for divine guidance. On Sunday, all work ceased. It was the day for rest. The Bible was read and the children were taught from the catechism. The children learned the ten commandments, the twenty-third Psalm and were told many of the marvelous stories in the Bible—Noah and the flood, David and Goliath, Joseph and his coat of many colors.

The population increased and the people wanted a church. A dam was built across the Black creek at what is now Chamberlain's Mills and a sawmill was erected. These pioneers cut trees in the forest, hauled them to the sawmill and had them made into building material for a church. The church was built in 1790 on land now owned by the Jamison family. There was no money to pay a minister, but the church could be used for prayer meetings and Sunday school. Occasionally a minister would come from distance on horseback and conduct ervice in the church.

days and the pastor's salary was small. Three hundred dollars being an average salary. However, the pastor was furnished with a parsonage and enough land to keep a cow and horse. He was also expected to keep a pig and some hens. Each fall a donation was given for the pastor's family. It was a get-together for the whole congregation. Each guest brought something in the food line. Fruit, vegetables, jellies, pickles and meat of various kinds were brought and a social evening was enjoyed.

In 1845 owing to the poor condition of the church building, it was decided to build a new church and to change the location. The congregation couldn't agree on where to locate the new church. It was finally voted to build the church where it now stands. In 1846 this church was built. Captain John Brown, a carpenter, and great-grandfather of Merritt Brown, and Sylvester Spoor, a mason and a grandfather of Wilson Durham, were the buiders of this church. During the following year, 1847, some of the congregation who were dissatisfied with the location of this church, built a church with the Methodist form of government, in Porter, a short distance south of Mrs. Doubleday's home.

In 1851 the Adventist church was built about a mile south of this church. Thus one strong church with a large congregation was divided into three weak churches. These three churches struggled for more than 30 years to keep their church doors open. Then the Methodist church and the Adventist church were closed. Some of the members went to the church in North Hebron. Some went to a Rupert church and others were received into this church.

During these 150 years this church has had more than 20 different pastors. When without a pastor, a student from a theological seminary would sometimes spend his summer vacation here and conduct services in this church. Among these students was the Rev. William Kepler, now pastor of Northminster church, Washington, D. C. Since the advanced cost of living, it has not been possible for this church to raise the salary for a resident minister. As the Salem Presbyterian church was having a similar difficulty, it was suggested that the two churches unite and engage a minister to be pastor of both. Since that arrangement, we have had the following pastors: The Rev. Eliot Presby, the Rev. William Mitchell, the Rev. William Barlow, the Rev. John Aalfs,

In 1799 a sto[ck] mpany was formed that built a ro[ad] ith toll gates from Lansingburg [to] ranville. It was called the Gre[at] orthern turnpike. It was later e[x]ded to Whitehall. This road has [been] en rebuilt several times and is n[ow] the state highway route 22. Sta[ge] aches passed over this road every [da]y. In 1800 a post-office was opene[d] in the buiding now owned by Anto[ne] Stipek. William Porter was pos[t] naster. That same year a store was opened by Dr. David Long. The Hebron population increased and the desire to have a resident minister increased.

In 1804 it was decided to have a resident minister. As many of the congregation were of Scotch descent, it was decided to organize the church under the Presbyterian form of government. A meeting was called for February 24. Nine men and seven women attended. Two ministers, the Reverend Preston and the Reverend Coe came from the Presbytery. The church was organized with 16 members and three elders. It was called the Hebron Presbyterian church. The elders were John Wilson, James Wilson and Daniel Hopkins. The following year Rev. Walter Fullerton became pastor of the church. The church membership increased. Old and young attended the services. The parish extended from North Hebron to the Salem line. Abram Case who located on the farm now owned by Rollin White, and who raised the first corn grown in Hebron, was a member. Judge David Hopkins, a state senator, who lived where the Ensigns now live, was an elder in this church. Discipline was strict. Profane language, falsifying the truth or intoxication would bring a church member before the session for a reprimand. The usual punishment was to drop the transgressor from membership until repentance was assured.

The only wagons at that time were the farm wagons. Chairs were built wide enough to seat two people and were placed in the front part of the wagons for the fathers and mothers. The children would sit on the straw covered floors of the wagons or sleighs and ride to church. Many of the people came to church on horseback. It was the popular mode of travel. A story has been handed down that when Mr. and Mrs. Archibald Woodard were married, the wedding was held out doors, on the hill near Major Mayr's home. The ceremony was conducted with the bride and groom each on horseback. They later kept a tavern where Mr. and Mrs. Frank Nelson now live.

Money was not plentiful in those

the Rev. Ira Stanton and our present pastor, the Rev. Cecil Plumb.

Not all of the ministers who have occupied this pulpit have been Presbyterian ministers. The Rev. Duke King, pastor of Rupert Congregational church, is a congregational minister. The Rev. Stewart Irwin was a retired Methodist minister. The Rev. Frederick Turner was an Episcopal minister. The Rev. William Barlow and the Rev. Ira Stanton were Baptists. However, all of these ministers used the same Bible that we use and we are grateful to them for their help in keeping our church door open. May this church continue to be an influence for good for the next 150 years.

Delivered in Hebron Presbyterian church Sunday, February 21, 1954, by Caroline Wilson, a member here for seventy years.

72-1

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Nov. 26, 75'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Hopkins - Ensign House
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: E. Hebron
3. STREET LOCATION: Route 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Grace + Betty Ensign ADDRESS: R.D., Salem
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? c. list major alterations and dates (if known):

P2-18A



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Building sets to the north of the Hamlet of E. Hebron on the old Great Northern Turnpike; this is the earliest settlement in Hebron.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Photos indicate the sophisticated wooden detail of this delicate Federal period house. It is Hebron's finest house of this period however interior features have been altered, partitions changed, fireplaces removed one mantle remains. Chair rails & cornices have rope molding; some door hardware, one upstairs bedroom has block molding, raised panels in the wainscotting - old red paint & early wall paper.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1790

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

This is the house of one of Hebron's first settlers who eventually became a N.Y.S. Senator.


Architecturally it is a fine example of Federal period architecture with all of the various cornices and molding. It is unusual in that it has 4 carved panels across the front of the house - details on another sheet.

21. SOURCES:

22. THEME:

115/11/[redacted]

Boynton-Ensign house and farm



One of the early houses in East Hebron is now the home of Mrs. Owen Ensign and Betty Ensign on Route 22.

The picture shows the house and farm buildings as they were in 1901. Far left in picture is a root cellar where potatoes, one of the main crops in Hebron, were stored. The walls were stone with a slanted roof starting from the ground.

The house was built in 1790 by David Hopkins who was supervisor of town of Hebron, judge of county court, member of assembly and a state senator. He had twelve children. David Hopkins and his family came in 1772 to take possession of the land. The land was part of the two thousand acres granted to Lt. Nathaniel McCullock and sold by him to Duncan Campbell, who sold part of it to David Hopkins and others settling in the area.

W.J. Joslin, owner of the farm in 1846, sold one-half acre to present East Hebron Presbyterian church for $100. This land is located in front of the Hopkins family cemetery.

Many different families have owned and lived in the house over the years. Many changes and additions have been made. The back part of the house must have been added fairly early. The attic floor of the addition is made from wide boards. This addition has contained kitchen, dining room, pantry and woodshed since it was built. The addition as well as main part of the house have some HL hinges.

In the late 1800's an addition was added to the main part of the house to make it suitable for two families. This was believed to be done by Silas Boynton, who was married to Lydia Ann Ayers. They lived in the house for at least twenty years. Frank Boynton, who later inherited the house and farm, lived in the addition with his wife, Cora Allen Boynton.

During the years fireplaces were removed and partitions were changed to make the house keep up with the new modern conveniences such as wood stoves.


Much of the original house remains as it was. There is a palladian window in the upstairs front hall. Under this is the front entrance with a large front door with fanlight and side windows. The door has large lock and large key. There is decorative carving around palladian window and on front of house. The attic windows, on north and south of house, are fancy oval ones. The north side of house has sand inside for insulation. Inside the house the downstairs front hall has an arched ceiling. Some of the window panes are antique glass. There are many antique brass and iron doorknobs. Most of the rooms have high ceilings, fancy molding around the ceiling, and chair rails. The attic entrance in the main part of the house has a small trap door over the stairs, so is not accessible as storage area.


Several rumors have passed down by word of mouth through the years. It was considered a haunted house at one time, but ghosts must have left before present owners came, since none has appeared in over fifty years. Upstairs is a small room with a high small window above the roof. This room has been called the tramp room. It was told tramps were allowed to sleep in this room, but the door was locked. The tramps were told not to smoke for if there were a fire they would burn with the house.

Owen Ensign purchased the house and farm in 1913, operating it as a dairy farm until 1960. He married Grace Steele from Shushan in 1918. Since his death in 1968 the house has been occupied by his wife, Grace, and daughter, Betty.


The Ensigns have tried to restore the house partially to the way it was originally. In the 1930's the addition on north of house and front porch were removed. The double doors at front entrance were removed and replaced by the original front door used in the addition. The fanlight and side windows, which were found in attic, were put back around the door. Few other structural changes have been made by them, but much work has been done to the house to keep it in its original state.

115/11







Carved Panels on Facade (4)



11/72







73-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bullen DATE: Oct. 3, 1975

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: North of W. Hebron
3. STREET LOCATION: corner Route 30 & 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mrs. Fenton Reid ADDRESS: R.D.2, Salem
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): Extensive rehabilitation by the Reids after 1958

12. PHOTO: P1



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Building sets at the end of town with scattered buildings

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Hard to tell what is original.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____
ARCHITECT: _____
BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Not shown on 1853 map

1866 W. Getty

~~1866~~ Adison Smith had a butcher shop in small barn next to the house.

Reids purchased 1958

21. SOURCES: owner says 1st reference to house on property was ~~Atlas~~ 1825.
Other owners: 1866 W. Getty
after Smith
Chas. Warster
____ Butner

22. THEME:

74-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Nov. 28, 1975

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): McCleod Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: Route 31-30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Richard McCleod ADDRESS: R.D. 2, Salem
6. USE: Original: Covenenter Presbyterian church parsonage Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☑
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located on the edge of West Hebron Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Panels under windows (interior), Greek moldings, ministers study was room on the right front

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Was the parsonage for the Covenenter Presbyterian Church, next door to the church

R. Copeland 1866
?

21. SOURCES:

Owner

Other owners: Percival Shaw
_____ Schieber (10-12 years)
_____ Miotk
Richard McCleod

22. THEME:

Religious

75-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Oct. 75

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Jerry Clough ADDRESS: R.D.2, Salem
6. USE: Original: Covenenter Church Present: storage of farm equip.
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☑ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☑ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☑
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: stream behind
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Building is on the edge of an historic district

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Entrance to church + wagon sheds (gone) used to be in the rear behind parsonage.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1831

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES: Wash. Co. His.

22. THEME:

76-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 11511
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Oct. 75

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: TOWN/CITY: VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Douglas McNeil ADDRESS: R.D.2 Salem
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☑
i. landscape features: _____
j. other: Stream behind

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Building located on the edge of a historic district

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1895 Fred Fraser to Will. McEachron 117 - P. 487
1916 John Donaldson & others to Norman Gould 163 - P. 510
1950 Norman Gould to Co. Welfare 291 - P. 277
1956 County to P. McNeil 350 - P. 128

21. SOURCES: Deeds

22. THEME: