Folder 4 -

Building-Structure Inventory Forms

~~#1 - 76~~

~~#77 - 172~~

#173 - 290

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

173 -3

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Big Town Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Saint Summershield ADDRESS: R.D. Salem
6. USE: Original: farm house Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Alex Keys (Mabel Goodell) wife

21. SOURCES:

174a-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ballou DATE: Feb. 76'

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Bramley Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Casper Bramley ADDRESS: R.D. Salem
6. USE: Original: farmhouse Present: farmhouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if
    c. list major alterations and dates (if kn

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: _____
j. other: sap house

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Sap house on Blossom road belongs to this property

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Greek Revival, with triangle molding in gable end, door with side lights, wide pilasters

Morgan
Parrish

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

174-2

YOUR NAME: Sally Brillon DATE: May 76'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlin's Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Meredith Wilson ADDRESS: R.D.2 Salem
6. USE: Original: Mill Present: storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☑ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☑
i. landscape features: Stream
j. other: house, studio

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Building located at the edge of Chamberlin Mills Historic District in the yard of the Meredith Wilson home.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Evidence exists that this was ~~was~~ once a mill, iron rods stretch across to the plates. There are several fly-wheels - wooden.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: probably 1780's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

One of the first mills in Hebron, important for its role in the early settlement of this town.

21. SOURCES:

Meredith Wilson

22. THEME:

Settlement

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

175-3

YOUR NAME: Sally Bullen DATE: May 76'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Wilson Carriage House
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlin Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Meredith Wilson ADDRESS: R.D.2, Salem
6. USE: Original: Carriage House Present: Storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: vertical siding
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☑ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☑
g. shop ☐ h. gardens ☑
i. landscape features: mill, studio, house
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Building is located in Chamberlin's Mill Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Building built into the bank with fine stone masonary.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

The carriage house is evidence of a building needed to house the various horse drawn vehicles needed in this area

21. SOURCES:

22. THEME:

Transportation

176-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Billen DATE: Mar. 76'

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlin's Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Wilfam, Inc. ADDRESS: R.D.3, Salem
6. USE: Original: farm use Present: farm use
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☑
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☑
i. landscape features: _____
j. other: house, wooden silos

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Building in Chamberlin's Mill Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

double wooden silos

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1820-25

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

177-2

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bailey DATE: Mar. 76'

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlin's Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Donald Swift ADDRESS: R.D. Salem
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☑
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ h. other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



HP-1 ICE HOUSE

13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: homes

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Buildings in Chamberlin's Mill Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Ice house sets down close to the mill pond.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

The ice house is a remenant of a past industry that existed on Chamberlins Mill Pond. Ice was used local and sold to surrounding area as a commercial venture.

21. SOURCES:

22. THEME:

178-2

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 1151/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bullen DATE: May 76'

YOUR ADDRESS: TELEPHONE: 854-3520

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S): Ferguson Lane Bridge
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: Ferguson Lane
4. OWNERSHIP: a. public ☑ b. private ☐
5. PRESENT OWNER: town ADDRESS:
6. USE: Original: bridge Present: bridge
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: metal
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with in[illegible]nts ☐
   b. wood frame with lig[illegible]oers ☐
   c. masonry load bearin[illegible]ls ☐
   d. metal (explain)
   e. other Lattice, pony truss, rosettes
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____


15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located on the edge of ~~then~~ West Hebron Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):



SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

One of very few lattice truss bridges left in Washington Co.

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

179-3

YOUR NAME: Sally Billon DATE: May 76'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Middle Rd. & Chamberlin's Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Eyebrow windows

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1830's -40's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

B. Rogers (1853 map)
Alex Sloane

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

180-3

YOUR NAME: Sally Bailey DATE: Mar. 76'

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Pres. Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S): James Wilson Barn
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlin Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Wilfarm, Inc. ADDRESS: R.D. Salem
6. USE: Original: farm use Present: farm use
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☑
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



NE-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: house

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in the Chamberlins Mill Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c1786

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

181-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: May 76'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Earl Wilson ADDRESS: R.D. Salem
6. USE: Original: farm Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



UP 1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Greek pediment, sun burst

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

~~East Wilson~~
Parrish

21. SOURCES:

22. THEME:

182-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ballou DATE: Mar. 76

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Koutrakas ADDRESS:
6. USE: Original: farm Present: residence (summer)
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ moved ☐ if so, when?
    c. list major a[illegible] dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Molded panels under the front windows, recessed door.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Milk house

Built a little before
1876 for Jim Braymer

James Hitt (↑ grandson)

Original house just so. of drive way.



21. SOURCES:
Arthur Smith

22. THEME:
Agric.

183-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ballou DATE: Mar. 76'

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Bird Construction ADDRESS:
6. USE: Original: farm Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: barns across rd
j. other: picket fence

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Block design in molding at front door, side lights.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Daniel Braymer
~~Austin Nelson~~
Cloise Shaw

21. SOURCES:

22. THEME:

184-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally, Billon DATE: Mar 76

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME (S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☑ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☑
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
dentil molding under the cornice

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Jacob Braymer
Alfred Braymer
Chas. Braymer
Robt. Liebig

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

185-3

YOUR NAME: Sally Bullock DATE: Mar. 76

YOUR ADDRESS: _____ TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

* *

IDENTIFICATION


1. BUILDING NAME(S): _____
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: _____
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Arthur Lessard ADDRESS: R.D. Salem or Granville
6. USE: Original: farm Present: _____
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

John Allen

Chas. ~~John~~ Allen (son)

21. SOURCES:

Maud Rogers

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

186-3

YOUR NAME: Sally Bullen DATE: Mar. 76'

YOUR ADDRESS: R.D.2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Preservation Society
R. D. #2, Salem, N.Y.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: A. Nanana ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____


15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Entrance



SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Robt. Hanna
Joe ~~McFadden~~ James McFadden
Nelson McCoy's parents lived there
(son)
~~Brayton~~

21. SOURCES:

22. THEME:

187-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ballou DATE: Mar. 76'

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Walt Glacier ADDRESS: R.D. Granville
6. USE: Original: farm Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c 1900

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Myra Nelson
Sara Jane Durfee
Jennie Durfee
Meritt Hollister

21. SOURCES:

22. THEME:

188-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: R.D.2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

* *

IDENTIFICATION


1. BUILDING NAME(S): Pleasant View Farm
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Walt Glacier ADDRESS: R.D. Granville
6. USE: Original: barn Present: barn
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☑
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: P12-2A

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Bank c 1900
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 11511
QUAD
SERIES
NEG. NO.

189-3

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Ronald Parker ADDRESS: R.D. Granville
6. USE: Original: farm Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: P12-2

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
S. Nelson (1853 map)
(Issac Gould (Everetts Grandfather))?
James Dorrance
Arthur ..

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

190-3

YOUR NAME: Sally Britton DATE: ~~854-3520~~ -Mar. 76'

YOUR ADDRESS: R.D.2 Salem TELEPHONE: ## 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Geo. W. Nelson ADDRESS: R.D. Granville
6. USE: Original: farm Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

Recessed front door removed

12. PHOTO: P12-1

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located on the Great Northern Turnpike

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Eyebrow windows

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

W. D. ELY (1853 map)
Daniel Greeley Nelson
Daniel E. Nelson
Geo. D. Nelson

It has been said that this house was at one time an Inn.

21. SOURCES:

Nelsons

22. THEME:

191-4

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bullen DATE: Mar. 76'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Nelson VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Geo. Nelson ADDRESS:
6. USE: Original: farm house (tenant) Present: ~~farm~~ barn
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explai
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):
    house made into a barn

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: barn yard

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in a barn yard

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Was a house now a barn.

John & Ida Fish

21. SOURCES:

Geo. Nelson

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

192-3

YOUR NAME: Sally Bullen DATE: Mar. 76'

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ~~Charles Hayes~~ Jim Nelson ADDRESS:
6. USE: Original: farm Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

G

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P12-8

13. MAP:



Slateville Rd.

X

Warner Rd. (X)

nr-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: wooden silo - no top

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Geo. Hanna

Arthur Roberts (quarryman)

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

193-3

YOUR NAME: Sally Ballou DATE: Mar. 76

YOUR ADDRESS: P.O.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Nelson McCoy ADDRESS:
6. USE: Original: farm Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: P12-7

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: slate quarry behind

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Abner Johnson
Roberts
Anton Andrea

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

194-3

YOUR NAME: Salle, Brillon DATE: Mar. 76

YOUR ADDRESS: R.D. 2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society ~~R.D. #2, Salem, N.Y. 12865~~

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Geo. E. Nelson ADDRESS: R.D. Salem
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: asbestos siding
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P12-21A-28

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Milo Hatch
Burt Hatch
Frank Nelson (Clara)

21. SOURCES:

22. THEME:

195-4

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bullen DATE: NOV 76

YOUR ADDRESS: TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society Hebron Preservation Society
[illegible] N.Y. 12865 R.D. #2, Salem, N.Y. 12865

* * * *

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
? C.S. Shaw (1853 Map)
Henry Nelson

21. SOURCES:
Jessie Garrity

22. THEME:

196-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society, P.O.2, Salem

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ADDRESS:
6. USE: Original: Farm Present: 1
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Five eyebrow windows

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

~~Dentons~~

Darrow
Hubert

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

197-4

YOUR NAME: _____ DATE: _____

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: Dorrance Lane
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Arthur Sidusky ADDRESS: West Pawlet or Granville
6. USE: Original: home Present: vacant after fire
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):
    Burned Recently (within 5-10 years)

12. PHOTO: P12-4A

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Andress + Waller (1853 Map)
slate
Lewis (Welsh)
Sudusky

21. SOURCES:

22. THEME:

198-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Billars DATE: Mar. 76'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Dorrance lane
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Arthur Dorrance ADDRESS:
6. USE: Original: home Present: —
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☑ g. stucco ☐ other: asbestos shingles
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Guthrie

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

199-3

YOUR NAME: Sally Bullen DATE: Mar. 76'

YOUR ADDRESS: P.O. 2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Geo. E. Nelson ADDRESS:
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Will. + John Clark

21. SOURCES:

Verna Garvey

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

200-4

YOUR NAME: Sally Bullen DATE: Mar. 76

YOUR ADDRESS: TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* * * *

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

John Smith

21. SOURCES:
Verna Garrett

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

201-3

YOUR NAME: Sally Ballin DATE: Mar. 76

YOUR ADDRESS: P.O. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ~~Hiram Stevens~~ Dave Harris ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain

like Forsione


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HP-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: built 1877

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Will. Brown, Emma Campbell Brown
Merritt Brown, Myrtle Nelson Brown

21. SOURCES:

Verna Garrety

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

202-3

YOUR NAME: Sally Ballou DATE: Mar. 76'

YOUR ADDRESS: TELEPHONE: 8543520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Myron Slater ADDRESS: R.D. Salem or Granville
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: asbestos shingles over it
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Looks as though it is an earlier house with Victorian dormers & window caps on the front.

Henry Nelson

21. SOURCES:

Verna Garrett

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

203-3

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3320

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: C. Lawrence, Jr. ADDRESS:
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☑ over g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HP-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____ _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Henry Wood

21. SOURCES:

Verna Garrett

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

204 -3

YOUR NAME: Sally Ballou DATE: Mar. 76'

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron ~~VILLAGE~~: PORTER
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Vincent Glovinco ADDRESS:
6. USE: Original: tenant farmhouse Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: P12-24

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: wooden silo wooden roof- board + batten



16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Judge Will. Porter's tennant house - where Samuel Smith lived, Arthur Smiths grandfather.

Abner Johnson

21. SOURCES:

Arthur Smith

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

205-3

YOUR NAME: Sally Britton DATE: Mar. 76'

YOUR ADDRESS: R.D.2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): ~~Hebron Preservation Society~~
R.D. #2, Salem, N.Y. 12865

* * * \

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Mabel Dennison

21. SOURCES:

Verna Garrety

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

206-3

YOUR NAME: Sally Ballou DATE: Mar. 76'

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Otto Dieffenbach ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: P12-12

13. MAP:





HP-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Newton Wright

21. SOURCES:

Verna Security

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

207-3

YOUR NAME: Sally Bullin DATE: Mar. 76

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Pres. Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Potter Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Everett Gould ADDRESS: R.D. Granville
6. USE: Original: farm Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



DOOR ↑ HP-1

13. MAP:



Map not right

NTB 2024 - Garrity Place - Now in pretty rough shape

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: open fields
j. other: lane with stone walls & maples

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: hills, magnificent view of Vermont

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Some raised panel doors, flush panel + batten
Very narrow eyebrow windows - two finished rooms on second floor
rest attic.
Chair rail, wainscotting in kit. (½), 6/6 + 9/6 windows, pantry, hand plane wood

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

James Livingston (orig.?) in 1840 sch. records
Hugh Qua 1844-48
Will. Dennison (dau. m. J. Potter)
Wm. + Josephine Dennison to John Potter (same as conveyed to Hugh Qua + wife to Wm. Dennison 4/1848 - about 100 acres) April 1, 1880, $4,000. John + Eliza Dennison Potter to their son, Jay Potter, 3/1/1917 - $3,500. Jay Potter m. Ada Wright + most their children will have an fam.

21. SOURCES:
On site observation
Arthur Smith

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

208-3

YOUR NAME: Sally Bullen DATE: Mar. 76

YOUR ADDRESS: R.D. Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S): [redacted]
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Potter Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Everett Gould ADDRESS: R.D. Granville
6. USE: Original: farm Present: tenant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
built 1902 by Chas. Smith — a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: wooden silo (30's built)

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Uzziel Laing was there in 1841, don't know how much earlier
Chas. Smith - 1889, Arthur's father

21. SOURCES:

Arthur Smith

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

209-3

YOUR NAME: Ivan R. Watrous DATE: 4-25-76

YOUR ADDRESS: RD West Paulet, Vt TELEPHONE: 642-2168

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S): House + Garage
2. COUNTY: Wash TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Dorance Lane
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Ivan Watrous ADDRESS: RD West Paulet, Vt
6. USE: Original: Dwelling Present: Dwelling
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapbo + b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobbles] f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HP-1

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
There used to be a grist mill on this property.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Borders the Indian River.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Traced back to 1856 & Possibly
ARCHITECT: earlier than this but wanted to
BUILDER: get this completed so didn't ~~go~~ go back any further.

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

210-3

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* * * * * * * * * * * * * R. D. #2, Salem, N. Y. 12865 * * * * * * * * * * * * *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Susan Valentine ADDRESS: R. D. Salem
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

211-3

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Sara Jenkins ADDRESS:
6. USE: Original: Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:

R.22

⊗

HR-1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c. 1830's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Brown

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115111
QUAD
SERIES
NEG. NO.

212-2

YOUR NAME: Sally Bullen DATE: Mar. 76'

YOUR ADDRESS: R. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Geo. E. Nelson ADDRESS:
6. USE: Original: farm - tavern Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known): remodeled in 1880's & 90's

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Back of house had cooking fireplace.
Molding of the early 1800.s
South end of building was moved across road - later torn down.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 130
Will. Roots. owned it when it was a tavern
J. ~~Will~~ Beattie
Maryetta Boynton
~~Archibald Woodard~~
(2) Frank Nelson 1884 (1) Albert Sunglove Nelson

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

213-3

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Harold Scudder ADDRESS:
6. USE: Original: farm - tavern Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☑ over g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): wing added (right)

12. PHOTO: P12-24

13. MAP:





HP-1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Toll house for 6. Nor. Turnpike was here

W. Durham

May have been used as a church.

21. SOURCES:

Verna Barrett

22. THEME:

HISTORIC AND NATURAL DISTRICTS
INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD.
SERIES
NEG. NO.

A 214-2

YOUR NAME: Sally Britton DATE: Mar. 76'

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Hres. Soc.

* *

1. NAME OF DISTRICT: Slateville Red Slate Quarries

2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Slateville

3. DESCRIPTION:

Several quarries in the immediate area, first opened in
in 1853 sold for $30,000
1855 Manhatten Tile & Slate Co. for $53,000
1891 Potters from Granville
1920 Rising - Nelson, operated it
Square tiles were made in various sizes 6", 9", 4", 12" etc..

4. SIGNIFICANCE: 1920 Slate 6.50 square

One of the few areas in the U.S. where ~~slate~~ red slate can be found.

Beautiful red slate wall near quarry - carefully laid up

One of the few places in U.S. where red slate can be found

5. MAP:

6. SOURCES:

Jessie Garrety

7. THREATS TO AREA:

BY ZONING ☐ BY ROADS ☐ BY DEVELOPERS ☐

BY DETERIORATION ☐ OTHER _____

ADDITIONAL COMMENTS:

8. LOCAL ATTITUDES TOWARD THE AREA: Ignored

9. PHOTOS:

ARCHEOLOGICAL SITE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK
518 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD.
SERIES
NEG. NO.

A 215-3

REPORTED BY: Sally Bailey

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Pres. Soc.

DATE: Mar. 76'

* *

1. SITE NAME: Marks Mills - Reid and Hanks

2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:

3. LOCATION: on the Indian Riv. boardering Poultney. Vt. area once called Marks Corners

4. PRESENT OWNER: Ivan Waltrous

5. OWNER'S ADDRESS: R.D. Granville

6. DESCRIPTION, CONDITION, EVIDENCE OF SITE:

☐ STANDING RUINS ☐ CELLAR HOLE WITH WALLS

☐ SURFACE TRACES VISIBLE ☐ WALLS WITHOUT CELLAR HOLE

☐ UNDER CULTIVATION ☐ EROSION ☐ UNDERWATER

☐ NO VISIBLE EVIDENCE ☐ OTHER concrete in flume area

7. COLLECTION OF MATERIAL FROM SITE:

☐ SURFACE HUNTING BY WHOM DATE

☐ TESTING BY WHOM DATE

☐ EXCAVATION BY WHOM DATE

☐ NONE

PRESENT REPOSITORY OF MATERIALS:

8. PREHISTORIC CULTURAL AFFILIATION OR DATE:

9. HISTORICAL DOCUMENTATION OF SITE:

1853 map - Marks Mills : grist + plaster

Ben Reed, Hanks father-in-law

Camilas Hanks - also wood-worker, repair, made sap buckets
had lathe + sm. saw
buckwheat and corn grinding (corn for the house)

Inform.: Arthur Smith, Jessie Garrety, Maud Rogers

10. POSSIBILITY OF SITE DESTRUCTION OR DISTURBANCE:

Modern garage erected near mill site

11. REMARKS:

12. MAP LOCATION

7 ½ MINUTE SERIES QUAD. NAME: _____

15 MINUTE SERIES QUAD. NAME: _____

U.S.G.S. COORDINATES: _____

D.O.T. COORDINATES: (if known) _____

ATTACH SKETCH, TRACING OR COPY OF MAP

SOURCE OF MAP:

13. PHOTOGRAPHS (optional)

(ATTACH)

ARCHEOLOGICAL SITE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK
518 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD. _____
SERIES _____
NEG. NO. _____

A 216-2

REPORTED BY: _____

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): _____

DATE: _____

* *

1. SITE NAME: U.S. Supreme Court Justice Samual Nelson Home
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: _____
3. LOCATION: across from District School No. #10

4. PRESENT OWNER: _____
5. OWNER'S ADDRESS: _____
6. DESCRIPTION, CONDITION, EVIDENCE OF SITE:

☐ STANDING RUINS ☑ CELLAR HOLE WITH WALLS
☐ SURFACE TRACES VISIBLE ☐ WALLS WITHOUT CELLAR HOLE
☐ UNDER CULTIVATION ☐ EROSION ☐ UNDERWATER
☐ NO VISIBLE EVIDENCE ☐ OTHER _____

7. COLLECTION OF MATERIAL FROM SITE:

☐ SURFACE HUNTING BY WHOM _____ DATE _____
☐ TESTING BY WHOM _____ DATE _____
☐ EXCAVATION BY WHOM _____ DATE _____
☑ NONE

PRESENT REPOSITORY OF MATERIALS: _____

8. PREHISTORIC CULTURAL AFFILIATION OR DATE: _____

9. HISTORICAL DOCUMENTATION OF SITE:

Relatives - Jessie Garrett

10. POSSIBILITY OF SITE DESTRUCTION OR DISTURBANCE:

11. REMARKS:

12. MAP LOCATION

7 ½ MINUTE SERIES QUAD. NAME: _____

15 MINUTE SERIES QUAD. NAME: _____

U.S.G.S. COORDINATES: _____

D.O.T. COORDINATES: (if known) _____

ATTACH SKETCH, TRACING OR COPY OF MAP

located directly across the road from school * 10 on the middle Road.

SOURCE OF MAP:

13. PHOTOGRAPHS (optional)

ARCHEOLOGICAL SITE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK
518 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD. _____
SERIES _____
NEG. NO. _____

A 217-2

REPORTED BY: _____

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): _____

DATE: _____

* *

1. SITE NAME: Alexander Webster Home

2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: _____

3. LOCATION: R. 31 next to Ralph Getty's house

4. PRESENT OWNER: Ralph Getty

5. OWNER'S ADDRESS: R.D.2, Salem

6. DESCRIPTION, CONDITION, EVIDENCE OF SITE:

☐ STANDING RUINS ☑ CELLAR HOLE WITH WALLS

☑ SURFACE TRACES VISIBLE ☐ WALLS WITHOUT CELLAR HOLE

☐ UNDER CULTIVATION ☐ EROSION ☐ UNDERWATER

☐ NO VISIBLE EVIDENCE ☐ OTHER building burned

7. COLLECTION OF MATERIAL FROM SITE:

☐ SURFACE HUNTING BY WHOM _____ DATE _____

☐ TESTING BY WHOM _____ DATE _____

☐ EXCAVATION BY WHOM _____ DATE _____

☑ NONE

PRESENT REPOSITORY OF MATERIALS: _____

8. PREHISTORIC CULTURAL AFFILIATION OR DATE: _____

9. HISTORICAL DOCUMENTATION OF SITE: Wash. Co. His. 1878 & photographs Gambrel roof, garrison windows, bed wells, end chimneys; built 1780-90. Also home of the Wm. McClellans.

10. POSSIBILITY OF SITE DESTRUCTION OR DISTURBANCE:

11. REMARKS:

12. MAP LOCATION

7 ½ MINUTE SERIES QUAD. NAME: _____

15 MINUTE SERIES QUAD. NAME: _____

U.S.G.S. COORDINATES: _____

D.O.T. COORDINATES: (if known) _____

ATTACH SKETCH, TRACING OR COPY OF MAP

SOURCE OF MAP:

13. PHOTOGRAPHS (optional)

(ATTACH)

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

218-3

YOUR NAME: _____ DATE: July 76'

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): Hebron Pres. Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: Halls Pond Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Montgomery ADDRESS: _____
6. USE: Original: _____ Present: _____
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. **PHOTO:**



13. **MAP:**



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

219-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: _____ DATE: May 76'

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: Chamberlin Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Franhofer ADDRESS: _____
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: siding
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
located just outside historic distric of W. Hebron

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Edward Irwin
Everette Williamson

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

220-3

YOUR NAME: _____ DATE: May 76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): Hebron Pres. Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: Chamberlin Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: J. Healy ADDRESS: _____
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

just outside of historic district.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Alexander & Eliza Dewey
to Henry Neville - Dec. 1, 1872
~~Ed~~ Sadie & Nettie Custer
Dan Hurd to Marietta Heath,
Nov., 1903

21. SOURCES:

22. THEME:

Plan. Dept.

221-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Mrs. Gertrude Getty DATE: August 15, 1974

YOUR ADDRESS: Salem, New York TELEPHONE: 854-7610

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: W. J. Cardwell ADDRESS: Bowie, Maryland
6. USE: Original: Dwelling Present: Dwelling
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain Private.


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other Post & beam construction, plank walls
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: large lawn, old maples
j. other: brooks, stone walls

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

It is an area of very old settlements, near a stage coach road and site of an old inn.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Panelled walls, wide floor boards, narrow clapboards, ~~sash~~ garrison windows

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1790 ?

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

It has a ~~central~~ replaced chimney with fireplaces in three rooms. It might be among the oldest houses in the town.

21. SOURCES: Harold Getty ~~homestead~~ father of Meredith, bought from Robt. Adams c1918
1853 - Sherman
1866 - J.A. Robinson

22. THEME:

NORTHUP-CARDWELL HOUSE

A mortgage, dated December 28, 1799, was executed by "John H. Northup of the town of Hebron in the county of Washington State of New York Blacksmith and Anna his wife" to "Richard Varick of the City of New York Esquire the only surviving executors of the last Will and Testiment of John Morin Scott late of said City Esquire." For fifty seven dollars twelve and a half cents, plus interest, the Northups bought twenty acres in the northeast corner of Lot 42 of a tract of 10,000 acres granted to John Morin Scott, John Taber Kemp Esquires, and others "by Patent under the great seal of the late Colony (now State of New York)..." This mortgage was registered January 23, 1800, on page 215, Book C of Mortgages, Washington County, New York.

An adjoining twenty acres in the north of Lot 42 were purchased by John H. Northup, Blacksmith, from John S. Nelson and Agnes his wife on October 4, 1805, for two hundred dollars. Entered in Liber 1, Page 467, and dated August 26, 1808, Washington County, New York.

These two parcels in Lot 42 appear to have been purchased to add to an adjoining parcel directly to the south comprising a part of Lot 31 which John H. Northup purchased from John Cole and on which the Northups built their house and conducted blacksmithing activities. The blacksmith shop according to firm physical evidence and local tradition, was located at the northwest side of the intersection between the west Hebron-North Hebron highway (County Route 31) and the lane* leading from that highway "to the house occupied by John H. Northup" (reference below). The exact date of the Northup-Cole purchase has not been determined; however, it appears clear that it was before 1800, because John H. Northup was identified as a Hebron resident blacksmith in 1799. The purchase of the Cole parcel is mentioned in a November 30, 1805 indenture by John H. Northup and Anna his wife to William Livingston by which the Northups, for one hundred dollars, sold 72 rods of land in the southern part of "a lot of land in lot 31 bought of John Cole." (Book of Deeds H, Page 273, Washington County, New York).

Based on clear evidence of Northup land ownership prior to 1800, and on architectural features and materials and methods used in the house at the end of the lane, it is concluded that the house was built at the time of land acquisition, i.e., during or before 1799, probably about 1795.

One acre three quarters and 24 rods of land were purchased on October 4, 1824, by John H. Northup from John Mcgibboney in Lot 31. This land appears to adjoin land already owned by the Northups. Also, it adjoined land "heretofore owned by Dr. Andrew Proudfit." (Book of Deeds-Grantee- R and S, Page 571).

---

*Located on Getty Lane which intersects Washington County Route 31 five miles north of West Hebron and two miles south of North Hebron.

Anna Northup survived her husband John H. Northup, because when she sold the farm to Lyman H. Northup of Sandy Hill on April 1, 1846, the text of the indenture identifies the approximately 150 acres as being "the premises occupied by John H. Northup at the time of his death." (Book of Deeds, Liber SS, Page 484, February 12, 1847).

The Northup farm contained what is now the farm of Warren J. Cardwell and Helen C. Cardwell, as well as the farm directly to the South owned by Delbert Ely and Emma Ely of Hebron, and known locally as "Uncle Walter's (Getty) place."

It is clear that there was a John H. Northup, Jr. (though not referred to as Jr.). On February 5, 1847, Lyman H. Northup and Elisa his wife, for $450, granted and sold to Jonathon Allen, in trust for the sole and only use and benefit of Maryette Northup wife of John H. Northup...all that certain piece of land ... being a part of the farm owned by Lyman H. Northup and occupied by John H. Northup. This parcel was the 10 acres in the southwest corner of the Northup farm and provided for a right of way through the lane or road leading from the highway to the house "now occupied by John H. Northup." (Book of Deeds - Grantee - Book 15, Page 51).

Lyman H. Northup and Elisa his wife sold the Northup farm to Jesse S. Sherman on April 30, 1851. Sherman is the name shown with the house on the 1853 map. John H. Northup (Jr., though not so identified) and Maryette apparently had moved into a house on Jonathon Allen's land because the name "Northup" is shown for such a house on the 1853 map. (Book of Deeds - Liber 25, Page 18).

Jesse S. Sherman and Lucinda his wife sold the farm to Edward G. Johnson on April 6, 1857. (Book of Deeds Book 37, Page 474).

Edward G. Johnson and Mary his wife sold the farm to Samuel Chapin on November 22, 1858. (Book of Deeds, Book 43, page 278).

Samuel Chapin and Mary his wife sold the farm to John A. Robinson on May 19, 1861. (Book of Deeds, Book 58, Page 248).

John A. Robinson sold two pieces of the farm in Lot 31 to David Irvin who had acquired 10 acres from Jonathon Allen, Trustee for Maryette Northup. (Book of Deeds, Book 49, Page 188; and Book of Deeds, Book 55, Page 585).

John A. Robinson and Emaline his wife sold the farm to William G. Wood on March 31, 1873. (Book of Deeds, Book 73, Page 325).

William G.=Wood and Almira his wife sold the farm to Robert Adams on March 31, 1884. (Book of Deeds Liber 95, Page 561).

Robert Adams and ~~Agatha~~ Agnes his wife sold the farm to Harold Getty on April 1, 1915. (Book of Deeds - Book 161, Page 361).

Harold Getty transferred the deed to the farm to himself and Alfreda his wife on September 26, 1933. (Book of Deeds, Book 208, Page 75).

Harold Getty and Alfreda his wife sold the farm to Warren J.

222-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION


1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: Bunker Hill Rd.,
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Harry Becker ADDRESS: _____
6. USE: Original: farm Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☑
   Interior accessible: Explain _____

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

modern Kitchen 1960 Bathrooms 1946
Hardwood floors 1957 Converted woodshed into family room with 1961 fireplace

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located on upper hill of west Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Hand-hewn boards in attic
wide Moulding around windows and doors.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Before 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

J. Patterson 1866 Map
also shown on 1853 map

W. Bristol
J. Hughey
R. Keys 1945-1973
H. Becker 1973 —

21. SOURCES:

R. Keys-Owner
History of Wash. Co 1878
Hebron Section
Atlas 1866

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

223-3

YOUR NAME: Gertrude Getty DATE: Dec. 24, 1976

YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854 7610

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Emma Keefe ADDRESS:
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Electric Lights 1931 Added 5' to back of house. Bathroom

12. PHOTO: P16-15



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located on the edge of West Hebron His. Dist. (within boundaries)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
New ceiling & floor in living room

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____
ARCHITECT: _____
BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
First deed- Oct 1, 1864 David Wilson to Agnes Shaw
Latest deed- 1930 Geo. Craig to George & Emma Keys
1866 Map Mrs. Brown

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

224-3

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: R. 31
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Mr. & Mrs. Delbert Ely ADDRESS: _____
6. USE: Original: Farm Home / Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☒
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO: D11-14

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☒
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: beautiful old barn complex - wooden silo

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Story and ½ - 4 rooms downstairs
3 rooms upstairs
July 1914 - Herder Silo Purchased $149.24
10 x 24

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Before 1863

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
1853 Northrup
1866 G. Dixon
~~Ebenezer Getty~~

Walter Getty

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

225-3

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: R. 31
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr. & Mrs. Delbert Ely ADDRESS: Granville N.Y. R.D. #1
6. USE: Original: _____ Present: Barn, Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private


DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

Bathroom, Furnace, Electricity

12. PHOTO: P11-116

13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☒ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☒ h. gardens ☒
i. landscape features: lawns, trees
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Large barns across the Road
Carriage - 1882 by E.J. Getty
Original section 1924? London Specifications John & Lloyd Getty
Original square house, 2 story, porch on 2 sides
wainscotting in the kitchen 1891

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: John Brown

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
On the site of an early tavern. Cellar stairs came from the old tavern.

21. SOURCES:

226-4

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: R. 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Roy + Carolyn Getty ADDRESS: _____
6. USE: Original: _____ Present: _____
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known): new barn 75-76

12. PHOTO:



13. MAP:



H1-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

E.J. Getty in 1866

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

227-3

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION


1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: R.30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Andrew Scott ADDRESS: _____
6. USE: Original: farm house Present: same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

12. PHOTO: P9-18A

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located on the edge of West Hebron Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Flush panel front door, plank house

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Bill Getty sold to Andy Scott's father

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

228-3

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: R.31 & Dunfler Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Vernan Chapman ADDRESS: _____
6. USE: Original: farm Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: asbestos shingles
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Area used to be known as McGibneyville
Chapman

1853 T. King
1866 T. Collins

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

229-3

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R.30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Andrew Scott ADDRESS: _____
6. USE: Original: cheese makers house Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located on the edge of West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

The cheese maker from the West Hebron Cheese Factory lived here. The cheese factory was across Route 30 and has since been torn down.

21. SOURCES:

Andy Scott

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

229-3

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R.30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Andrew Scott ADDRESS: _____
6. USE: Original: cheese makers house Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

230-3

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R.30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: William Grosbeck ADDRESS: _____
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☒ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO: P16-16A

13. MAP: 10/76





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1866 Map J. McWhorter

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

231-3

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R.30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Jerry Clough ADDRESS: _____
6. USE: Original: farm house Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located on the edge of West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1866 Map W. Getty
G.E. M'Eachron

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

232-3

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Eliz. Mulhaul ADDRESS: _____
6. USE: Original: home Present: _____
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Lebby Copeland

John Keller

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

233 -3

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R-30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: _____ ADDRESS: _____
6. USE: Original: Al Norton Present: _____
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located on the edge of the West Hebron Historic Distric

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

ARCHEOLOGICAL SITE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK
518 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD.
SERIES
NEG. NO.

A 234-2

REPORTED BY: Gertrude Gitty

YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854 7610

ORGANIZATION (if any): Nelson Preservation Society

DATE: Oct 4, 1976

1. SITE NAME: Reed's Saw Mill and Stone Dam, ~~Mansion, Grist Mill~~

2. COUNTY: Washington TOWN/CITY: Nelson VILLAGE: West Nelson

3. LOCATION: On Black Creek Extension on Patterson Hill Road just off Route 30.

4. PRESENT OWNER: Lillian Fowler

5. OWNER'S ADDRESS: Salem, New York R.D #1

6. DESCRIPTION, CONDITION, EVIDENCE OF SITE: P 1-4 A

- [x] STANDING RUINS
- [x] CELLAR HOLE WITH WALLS
- [x] SURFACE TRACES VISIBLE
- [ ] WALLS WITHOUT CELLAR HOLE
- [ ] UNDER CULTIVATION
- [ ] EROSION
- [ ] UNDERWATER
- [ ] NO VISIBLE EVIDENCE
- [ ] OTHER Waste, Rubble, ~~pieces of iron, int. grist mill foundations~~

7. COLLECTION OF MATERIAL FROM SITE:

- [ ] SURFACE HUNTING BY WHOM _____ DATE _____
- [ ] TESTING BY WHOM _____ DATE _____
- [ ] EXCAVATION BY WHOM _____ DATE _____
- [ ] NONE

PRESENT REPOSITORY OF MATERIALS: on site

8. PREHISTORIC CULTURAL AFFILIATION OR DATE: _____

HP-3

9. HISTORICAL DOCUMENTATION OF SITE:

Relatives of mill owners - 1866 map, Wash. Co. Hist. 1878
old photos - post card

10. POSSIBILITY OF SITE DESTRUCTION OR DISTURBANCE:

The mills were torn down in 1948 and sold for other buildings - area probably undisturbed

11. REMARKS: Wooden pickets, cut nails, glass shards, wooden pipes, and other laundry items were made here. A road crossed the dam and the miller lived on the other side

12. MAP LOCATION

7 ½ MINUTE SERIES QUAD. NAME: _____

15 MINUTE SERIES QUAD. NAME: _____


U.S.G.S. COORDINATES: _____

D.O.T. COORDINATES: (if known) _____

ATTACH SKETCH, TRACING OR COPY OF MAP

p3-214

concrete foundations
STONE DAM GONE OUT



SOURCE OF MAP:

13. PHOTOGRAPHS (optional)

(ATTACH)

Related to
Forms A336
A334

The mills in West Hebron were built by James Reid on land purchased in 1832. Records show a deed of 250 acres to James Reid - Aug. 15, 1766, a part of Lot 9, De Forest's Patent. Another deed is shown James & Margaret Reid to Wm. Reid - Apr. 4, 1856

This James Reid was a grandson of Wm. Reid who emigrated to America in 1764 from mills in Comrie, Scotland. He built mills at Dutch's Point, Salem.

After a few years he moved to Lick Springs, Argyle, where another mill was built. The history shows he was active in Argyle affairs. His son Wm. & grandson James grew up here.

James Reid came to this area to teach at Dist. #5, Hunter School. He married

4, De Dasest's Patent
Another deed is shown
James & Margaret Reid to
Wm Reid & Ops. 4, 1856
This James Reid was a
grandson of Wm. Reid who
emigrated to America in
1764 from mills in Comrie,
Scotland. He built mills
at Petch's Point, Salem.
After a few years he
moved to Lick Springs,
Argyle, where another
mill was built. The
history shows he was
active in Argyle affairs.
His son Wm. & grandson James
grew up here.
James Reid came to this
area to teach at Dist. # 5,
Rossster School. He married
the daughter of a local
farmer, James Cummings,
In 1882 he bought the farm
& water rights along Black
Creek.
Here he built a saw Mill,

grist mill + carpet shop. He + then his son Thos. Reid operated these mills until Thos's death in 1906.

A variety of wooden items were made here - pickets, brushmaker's blocks, wooden water pipe, cheese boxes, and burnt wood items

Another item states that on Dec. 19, 1856 Joseph & Geo. Reid leased a mill at West Nelson. They were educated machinists + manufactured brush heads, cheese boxes, shingles, + fence pickets.

A starch mill also in the area was run by Rae + McDowell in 1866. Later Thos. Reid bypassed this mill + manufactured various articles

Other Names connected with the Mills were Peter Laskin, Neil McIntyre, +

water pipe, Cheese boxes, and burnt wood items

Another item states that on Dec. 19, 1856 Joseph & Geo. Reid leased a mill at West Nelson. They were educated machinists & manufactured brush heads, cheese boxes, shingles, & fence pickets.

A starch mill also in the area was run by Rae & McDowell in 1866. Later Thos. Reid leased this mill & manufactured various articles

Other names connected with the mills were Peter Laskin, Neil McIntyre, & James & Bill Casey

Levi Copeland had a factory (mulhalls) to make potato hooks & metal items & sold them from a 2 story building on that lot.

Three women were employed upstairs Assembling the items.

They were taken to Emma Reid, wife of Wm. Reid, to be decorated with the popular, fire burning art and sold from her home.

Some of the items made were - tie racks, decorative wall plaques, match holders, plant stands and small boxes of many sizes.

The grist & cider mill nearest Paterson Hill Rd. was taken down in 1945. It was owned by Peter Laskin, James Foster, H Baskley, W. Reid & N. McIntyre

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

235-4

YOUR NAME: Gertrude Getty DATE: Jan. 15, 1976

YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R-30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Wood ADDRESS:
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: siding
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P5-13A



13. MAP:



ARCHEOLOGICAL SITE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK
518 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD.
SERIES
NEG. NO.

A 236-2

REPORTED BY: Sally Bullen

YOUR ADDRESS: R.D.2, Salem, N.Y. TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

DATE: 11/76

* *

1. SITE NAME: McIntyre's Grist Mill

2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: West Hebron

3. LOCATION: on Bunker Hill Rd. to the north before you cross Black Creek

4. PRESENT OWNER: Hunt or Fowler

5. OWNER'S ADDRESS: R.D.2, Salem

6. DESCRIPTION, CONDITION, EVIDENCE OF SITE:

☑ STANDING RUINS STONE WALLS ☑ CELLAR HOLE WITH WALLS

☐ SURFACE TRACES VISIBLE ☐ WALLS WITHOUT CELLAR HOLE

☐ UNDER CULTIVATION ☐ EROSION ☑ UNDERWATER

☐ NO VISIBLE EVIDENCE ☐ OTHER pieces of iron in cellar

7. COLLECTION OF MATERIAL FROM SITE: NONE

☐ SURFACE HUNTING BY WHOM _____ DATE _____

☐ TESTING BY WHOM _____ DATE _____

☐ EXCAVATION BY WHOM _____ DATE _____

☐ NONE

PRESENT REPOSITORY OF MATERIALS: _____

8. PREHISTORIC CULTURAL AFFILIATION OR DATE: _____

9. HISTORICAL DOCUMENTATION OF SITE:

10. POSSIBILITY OF SITE DESTRUCTION OR DISTURBANCE:

11. REMARKS:

12. MAP LOCATION

7 ½ MINUTE SERIES QUAD. NAME: _____

15 MINUTE SERIES QUAD. NAME: _____


U.S.G.S. COORDINATES: _____

D.O.T. COORDINATES: (if known) _____

ATTACH SKETCH, TRACING OR COPY OF MAP

P13-6

STONE DAM



SOURCE OF MAP:

13. PHOTOGRAPHS (optional)

(ATTACH)

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

237-2

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Richard Beattie ADDRESS: _____
6. USE: Original: blacksmith shop Present: storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: house

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in the historic district of W. Hebron

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Blacksmith Shop - run by Al Matteson

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

238 -1

YOUR NAME: Gertrude Gettys DATE: Feb 2, 1985
YOUR ADDRESS: Salem New York TELEPHONE: 854-7610
ORGANIZATION (if any): Hebron Preservation Society


* *


IDENTIFICATION

1. BUILDING NAME (S): Hebron Valley Grange
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION:
4. OWNERSHIP: a. public ☒ b. private ☐
5. PRESENT OWNER: Hebron Valley Grange ADDRESS: Salem New York
6. USE: Original: Church Present: Grange
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain: Yes Grange & public meetings as by appointment

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☒ if so, when? 1859
    c. list major alterations and dates (if known):
    Renovations & Stage - 1895 Outside painted
    New State Roof - 1911 Kitchen remodeled
    2nd Story Porch Enclosed
    Interior
12. PHOTO: P5 - 20A
13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☒
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Parking lot
j. other: Trees and lawn in front

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: Key building in West Haven His. Dist.
(Indicate if building or structure is in an historic district)
It is on an area of buildings of the same period and fits well into the landscape.
One of the minutes of 1911 states that a motion was adopted that pasts be bought + set at each side of the front steps

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
It is Greek Revival architecture. The entrio has rectangular top and chairs said with plastest moulds. It has added, board and batten, large stage with landings. Wainscoting is made from beaded hand planed sheathing.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: ~~Between 1839 & 1849~~ 1839

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
This building was purchased from the Campane Society of White Creek. It was taken down + past 1869 and used as a Methodist Church until 1894. It served known as Reed's Hall and Ashley Hall. Stage and remodeled building. Mediums Shows purchased in 1911 for $750. from Mrs. Matteson.

21. SOURCES: M. E. Church Records Washington Co. His. 1878 George Minutes

22. THEME:
W

Mrs. L. Matteson purchased it from Emma J. Reid - Dec. 1906
Orange purchased it in May 1911.

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

239 -2

YOUR NAME: Gertrude Getty DATE Oct. 15, 1975

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Lillian Bowker ADDRESS:
6. USE: Original: Residence mill owner Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain Lady does not want visitors


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Large trees, lawn
j. other: Remains of dam and old Mills

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☒
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: Black Creek runs & falls borders it

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

It is 2 story, central block with side wing
Water pump in front yard.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Before 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

It is an early Greek Revival home. A granddaughter of an early owner, Mrs Reid, says it was a stop in the underground railroad. Black Creek with a good water flow & falls borders the property. So early grist mill, saw mill & wood products mills were here. This area helped to develop the village & with the business enhanced the building of a large

21. SOURCES: home-Reed ✓
Mrs. Reid in 1866 map
Gazetteer Swackenhush- early grist mill
D & J. Reid Saw & Grist Mill
Steam - 1848
Ross & McDonalds 1866 - stasek

22. THEME:

240 -3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Mrs. Gertrude Getty DATE: Oct. 19, 1975

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐, b. private ☒
5. PRESENT OWNER: Meredith + Gert Getty ADDRESS: Salem, New York
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private.

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Furnace, bathrooms, insulation, modern kitchen, sanded floors, storm windows - 1960 - 1974

12. PHOTO: PI 8A



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: lawn, shrubs, garden
j. other: Walls of barn or carriage house

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: Grange Hall
stately maple trees

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) It fits well into district in an area of houses of the same period. In West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Greek Revival, wide boards, high ceilings, side wing
Center hall with open stairway, square nails
architrave trim on woodwork, sliding doors between
living & dining rooms

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Ground 1850

ARCHITECT: _____

BUILDER: _____
Will. McClellan 1865 R. Harsha

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: The Grange Hall besides it built in 1839 has some of the same features,

Mary J. H. Lester
to
Ada J. Cary Mar. 29, 1907
to
Mary J. McAuley
to
Alberta J. Mathison Mar. 13, 19[illegible]
to
Nastes T. Munro
to
Ethel M. Dean May 24, 1946
to
Buston & Sarah Lansing
Sept. 16, 1948
to
Betty Reid, heir May 18, 195[illegible]
to
Robert & Juliana Dolan

21. SOURCES: Deeds

22. THEME: 1866 Atlas

241 -3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Gertrude Getty DATE: Oct. 21, 1975
YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854 7610
ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: N. Hebron
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER Richard & Louise Brott ADDRESS: Salem, New York
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    Bathroom Remodel 1960

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☒ h. gardens ☒
i. landscape features: lawn, trees, fence
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☒
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Greek Revival influence, 2 story with sidewing, wide pine flat boards, architrave trim on woodwork, 6 over 6 window panes, 4 panel doors, some metal latches, smaller version of several similar houses in the area.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: before 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

At Matteson (present owner's great grandfather) had a blacksmith shop in back. This house is located across the road from Black Creek, falls & dam & mills so it was built & used at an early time. The blacksmith shop was very popular (pictured) At Matteson

Owners
J. McIntyre - 1866

21. SOURCES: 1866 Atlas

Robert Cosgrove

22. THEME:

Bk. 214
Pg. 470

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

242 -3

YOUR NAME: F.R. & L.C. KINTZING DATE: JUNE 2, 1974

YOUR ADDRESS: RD#1 SALEM TELEPHONE: 854-3216

ORGANIZATION (if any): Hebron Preservation Society R.D. #2, Salem, N.Y. 12865


* *


IDENTIFICATION

1. BUILDING NAME(S): Dwelling
2. COUNTY: WASHINGTON TOWN/CITY: HEBRON VILLAGE: W. HEBRON
3. STREET LOCATION: PATTERSON HILL ROAD
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: ABOVE Kintzing ADDRESS: ABOVE
6. USE: Original: DWELLING Present: DWELLING
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain NO

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):
    fireplace 1975
    insulation
    General repairs being made
12. PHOTO: P1-2A 13. MAP: 4 I





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

1½ story Plank walls/ Block lined
interior Chimneys Square Nails
Board & Batten Doors
Gable roof 6 Panel Doors
wainscotting & Chair Rail 2 Leaf Shutters
Indian Head Penny - 1864 - found in walls.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Before 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 1866 - P. B. Larkin (Robert Adams) deeded to Ed. Le Bardo Nov. 30, 1866

Peter B. Larkin owned a grist and saw mill across the road (Mill St.). Thriving - 1878

21. SOURCES:

Recorded: Jan. 27, 1937
Book 214 of deeds P. 470

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

243 -3

YOUR NAME: Ralph Lombardi DATE: 35-31-75

YOUR ADDRESS: R. D. 2 Salem, N.Y. TELEPHONE: None

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr. & Mrs. Ralph Lombardi ADDRESS: R. D. 2, Salem, N.Y.
6. USE: Original: residential Present: residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: PI - 4A



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Has tower on top approximately 9'x9' wide and 10 ft. high. Has wide board floors, square nails, scroll roof brackets.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1869

ARCHITECT: Unknown

BUILDER: Unknown

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Was used as a boarding house at time of Prof. Geo. Baldwin occupancy (1913-1918), he being a teacher at West Hebron village school. Wm. Reid to Levi Copeland 4/18/1882
Eliz. Copeland to Geo. Baldwin 2/18/1913
Geo. Baldwin to Walter & Martha Scott 5/21/1920

21. SOURCES: Abstract of title

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

244 -3

YOUR NAME: Mrs. Caroline A. Hunt DATE: Jan. 23, 1975
YOUR ADDRESS: R.F.D. # 1 Salem, New York TELEPHONE:
ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION


1. BUILDING NAME(S): Residence and small business
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R.30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mrs. Caroline Hunt ADDRESS: Salem, New York
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Open at certain hours


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Bathroom, furnace, water artesian Over period of last 20 years

12. PHOTO: P 1 - 3A 13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: please don't let there be at any time

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐ small - now
d. privy ☐ e. shed ☐ f. greenhouse ☐ being used for worksho
g. shop ☒ h. gardens ☐
i. landscape features: lawn surrounding - near brook
j. other: and site of old mill dam

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☒
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

This area was settled very early with a thriving business as a wheat grinding mill, starch mill. There is a large creek just behind this area. Located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Mostly wooden walls - some plaster - pine floors - some maple

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1885 deed ? (not shown on 1866 map)

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Wm. Reed to Mary Lanphier Apr. 1, 1885 Bk 100
1878
Millinery Shop - Miss A. E. Blair to Earle Hilson, Edith Hilson Stanley & Charles sold to Jennie M. Campbell Aug 26, 1911 Samuel B. Campbell - Florence Getty, Ivan Campbell - Apr. 1 1955 to Caroline Hunt - Dec. 25, 1955

21. SOURCES:

Owners - deed

22. THEME:

Liber 98 - page 191

Certificate of Authority NY 7109992
Extended to lifetime from State Department

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

245 -3

YOUR NAME: Gertrude Kelly DATE: Nov. 29, 1975

YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: East Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Marilyn & Don Chase ADDRESS: Salem, N.Y.
6. USE: Original: Residence Present: same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

since 1950 - furnace, new walls, floors, wall & a complete renovation

12. PHOTO: P1-11A

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: lawns, garden, large trees
j. other: Black Creek St. back of the property

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

It fits well into the area - in West Hebron Historic Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

It is 2½ story with side wing. Well constructed of sawed timbers. Many glass slides found in the attic of this house show how the whole area looked around 1890, bell on roof.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Around 1880

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Part of Lot 9, De Forest's Patent
Jesse D. Guthrie
to
Mary D. Lester June 1, 1882
to
Dr. D. H. Littlesey & D. B. Lester
Aug. 19, 1942
to
Stella S. Lester - June 9, 1941
to
Catherine G. Lester Nov. 1949
D. Howard R. Lester
to
David Lester Sept. 1950
to
Donald & Marilyn Chambers

21. SOURCES: Deeds

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

246 -3

YOUR NAME: Gertrude Getty DATE: Oct. 19, 1975

YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Ralph & Ruth Little ADDRESS: Salem
6. USE: Original: Residence Present: Same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Front, Door at back

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☒
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

outside chimney - 1974
Kitchens remodeled - 1970

12. PHOTO: P 1/0A

13. MAP:





UD 1

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: trees, lawn, bushes
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) located in West Hebron His. Dist.
This house is on a street with other houses of the same period as earlier. Each house in some way contributed to life of a thriving community, built up by water power

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Semi - 5 panel doors, architrave trim on woodwork wide floor boards - pine, full 2 story, side wing early victorian, high ceilings, center door and staircase, slate roof, double front doors, rounded glass, bracketed original cornices. It is changed very little

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: about 1860

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
One wing contained an undertaker's parlor when owned by J. Barkley. Barn was used for supplies and embalming. The second floor of the barn was used by the first Boy Scout troop in West Nelson.

J. Barkley to Dec. 1897
A.C. Barkley to Lynn Barkley
Lynn Barkley to June 1930
Josephine Kattenback to Dec. 1945
Ayle & Mary Andersson to Ralph & Ruth Little, June 8, 1966

21. SOURCES: Deeds 1866 Atlas
Liber 116 Page 243

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

247 -3

YOUR NAME: Mrs. Gertrude. Getty DATE: April 15, 1974

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Dwelling
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: 12.30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mr. & Mrs. Willard Bain ADDRESS: Salem, New York
6. USE: Original: Dwelling Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain: Front, 2 side doors, back

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: Siding added
9. STRUCTURAL SYSTEM: (if known)
   a. wood fram interlocking joints ☐
   b. wood fram light members ☑
   c. masonry lo aring walls ☐
   d. metal (exp)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Porch torn off, Siding added - 1958
Picket fence on all sides torn down
Double front doors replaced with single door } 1965

12. PHOTO: P/F 14A

13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: Lawn, trees, flowers, bushes
j. other: Driveway at the side

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
It is in a historic district of West Hebron

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
2 story with 1½ story wing. Bracketed roof supports & nearby houses built the same.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Before 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 1866 D. H. McClellan
Historic houses nearby are built the same

John McKesson Aug. 19
to Annette McAuley
Alberta Matteson

21. SOURCES: It is shown on 1866 Atlas as belonging to D. H. McClellan. Other facts given by present owners.

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

247 -3

YOUR NAME: Mrs. Gertrude. Getty DATE: April 15, 1974

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME (S): Dwelling
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: 12.30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mr. + Mrs Willard Bain ADDRESS: Salem, New York
6. USE: Original: Dwelling Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain Front, 2 side doors, back

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: Siding added
9. STRUCTURAL SYSTEM: (if known)
   a. wood fram interlocking joints ☐
   b. wood fram light members ☑
   c. masonry lo earing walls ☐
   d. metal (exp)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Porch torn off, Siding added - 1958
Picket fence on all sides torn down
Double front doors replaced with single door } 1965

12. PHOTO: P/T-14A

13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: Lawn, trees, flowers, bushes
j. other: Driveway at the side

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
It is in a historic district of West Hebron

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
2 story with 1½ room wing. Bracketed roof & cupolas
Nearby houses built the same.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Before 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 1866 H. H. McClellan
Hatties houses nearby are built the same
John McKesson Aug. 1911
to Annette McAuley
Alberta Matteson

21. SOURCES: It is shown on 1866 Atlas as belonging to H. H. McClellan. Other facts given by present owners.

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

248 -3

YOUR NAME: Mrs. Gertrude Getty DATE: August 16, 1974

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Dwelling
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr & Mrs. Edwin J. Dooley ADDRESS: Salem, New York, R.D. #1
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Front, side, back entrances

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☒ b. wood frame with light members ☐ c. masonry load bearing walls ☒ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? c. list major alterations and dates (if known):

Front Porch removed - 1967 Partitions & doors changed, closets added
Back woodshed - 1968 Modern kitchen - 1967 Deck added - Back - 1974
Carriage house fell 1961 Bathroom remodeled - 1969

12. PHOTO: P. 15A

13. MAP:





HP-1

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: lawn, trees, shrubs
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
~~It is an historic district~~
It contained a large barn and shed. It has the same architecture as nearby houses and seems to relate well to the street - In West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Center stairway, wide boards, some board & batten doors. Greek revival with side wing. With all renovations the outside has not been greatly altered

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Before 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
George Ashley owned a clothing store next door.
Aunt Sally ~~Bentley~~ Barkley hung herself in the hall. It was the house of Bill & Jim Craig (in the 1920's & 30's)
Gustaf Lot # 9 De Forest Patent
George Ashley - 1866
Grave
George Randles Annie C. to Wm. H. Barkley Dec 1, 1876
Marble works - 1878
Clothes Shop - upstairs - Lafayette Smart 1878

21. SOURCES: Deeds, atlases, 1866 Atlas

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

249 -3

YOUR NAME: DATE: 10/76

YOUR ADDRESS: TELEPHONE:

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: Main (only) R. 30
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Edwin & Evelyn Dodge ADDRESS: Salem, N.Y.
6. USE: Original: Shops-later dwelling Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain


DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. ~~tile~~ ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): Changed to dwelling house about 1900. or teens of 1900

Lower floor - marble shop
Upper floor - tailor shop

12. PHOTO: P11-17

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: lawn, trees
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

2 story. depth of the lot. wide boards. Stairway at front door. Plain woodwork. 4 panel doors

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

It was a mantle shop constructed by Wm. Barkley 1878.
Once the mantle shop was a harness shop of Lafayette Crosset.

adjoining

Rebecca Kays
to Mar 26, 1919
Grace P. Campbell

Jeannie Beatty Mar. 12,
to Elizabeth H. Kays 1918
May Hills
to Alvst & Evelyn Hills Jan. 7, 1944
to
Elizabeth D. Nelson
to
Charles A. Brown Jan. 12, 148
Margery K. Brown
to
Nat. Bank Argyle
to
Adelia Beggs July 15, 1971
to
Edwin J. Dooley & Evelyn A. Booth
Mar. 8, 1975

21. SOURCES: Deeds
Atlas

22. THEME: D

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

250
~~215~~-4

YOUR NAME: _____ DATE: 11/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION


1. BUILDING NAME(S): West Hebron Firehouse
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R.30
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: West Hebron Vol. Fire Co. ADDRESS: R.D.2 Salem
6. USE: Original: firehouse Present: firehouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: cement block
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☑
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO: P13-15A 13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located in West Hebron Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1948-49

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Built on the site of A. G. Ashley's Clothing Store - 1866 Atlas

21. SOURCES:

John Weaver

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

251-3

YOUR NAME: Gertrude Getty DATE: May 8, 1976
YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610
ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr. & Mrs. Arthur Harthington ADDRESS: Salem, New York
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO: PI 18-A



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: Lawns, Shrubs
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Symetrically Molded trim with corner blocks

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

252
[redacted]-2

YOUR NAME: _____ DATE: 11/3/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION


1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Arthur Worthington ADDRESS: W. Hebron
6. USE: Original: Store Present: Storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO: P13-14A

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located in West Hebron Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Under lower clapboards on the front are found the old store windows, roof extension in rear for pulley, double doors on ground level with transom above.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Operated for many years as a village store.

Atlas 1866 - W.W. McClellan, Dry goods and groceries etc...

later — Chas. Hanna - store

21. SOURCES:

22. THEME:

253-2

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Gertrude Getty DATE: Oct. 19, 1975

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610

ORGANIZATION (if any): Nelson Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME (S): Passmore
2. COUNTY: Washington TOWN/CITY: Nelson VILLAGE: St. Nelson
3. STREET LOCATION: Rt. 22
4. OWNERSHIP: a. public ☒ b. private ☐
5. PRESENT OWNER: United Presbyterian Church ADDRESS: Salem N.Y.
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain


DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ asbestos ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking P1 ☐
   b. wood frame with light memb ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

It has been renovated many times, but the outside as well nearly as the original

12. PHOTO: P1 21A

13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: Lawn
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
This is an imposing 2 story house Greek Revival with 2 story, 2 tiered porches across front. Fanlights at entrances at each story. Raised stairway from front entrance.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1862

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
This was purchased as the parsonage of the ~~United~~ Presbyterian Church in 1862 and has been continually used since. A new church (26 yrs. old) was built beside it.

21. SOURCES:
Shown on 1866 Map - Rev. Fisher resid.

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

254-3

YOUR NAME: _____ DATE: 11/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): HPS

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: United Pres. Church ADDRESS: _____
6. USE: Original: Church Present: Church
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☑ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☑
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    s and dates (if known):

P1-23A



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1948

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

255-3

YOUR NAME: _____ DATE: 10/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION


1. BUILDING NAME(S): James Burch
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: James Burch ADDRESS:
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: 1 P1-25

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1865 - Cyrus Shaw Mill - Nelson
to
1866 - J. Brown

1872 - leased by Ben Nelson to Caleb Reynolds

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

256 -3

YOUR NAME: Gertrude Getty DATE: Feb. 1975

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7618

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Arthur Cood ADDRESS: Salem, New York
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ h. other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other Brick lined
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Remodeled lower stairs 1967 side porch added 1970
Paneled down stairs 1967 New floors downstairs

12. PHOTO: P. I 26A

13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: small lawns - front, back
j. other: barn + tree stake & stumps

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) located in West Hebron His. Dist.,
This is an area with old buildings probably of around 1800 era, near the Black Creek and a cross roads area

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Square nails small panes upstairs - 6 over 6
Brick boards / 4 panel doors, walls not "true"
Front door with side lights, narrow clapboards
Plain trim, metal door latches

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: before 1866

ARCHITECT: _____

BUILDER: Copeland

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 1866 - D. C. Williamson
Early architecture and near area where hotel, stores & past office was completed around 1800. There was a blacksmith shop on the property until road was widened, before that a wagon shop

21. SOURCES:
Present owners - Natives of the area,
1866 Atlas

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

257-3

YOUR NAME: Gertrude Getty DATE: Nov. 10, 1985

YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: St. Hebron
3. STREET LOCATION: R.30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Selkirk St. Estate ADDRESS: Salem, New York
6. USE: Original: home Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? c. list major alterations and dates (if known): Residence 1941 Commercial insurance toilet & shower Kitchen

12. PHOTO: P1-24A



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Stone fence
j. other: Stone Shed Hebron Center

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Lip panel doors, hop locks
2 panel doors
wide floor boards

SIGNIFICANCE
19. DATE OF INITIAL CONSTRUCTION: Before 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
It was centrally located in the village
One of four houses designed with a central portion and two side wings (La Fever style)

21. SOURCES:

22. THEME:

1

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

258-3

YOUR NAME: Hebron Preservation Society DATE: 12/77
R.D. #2, Salem, N.Y. 12865
YOUR ADDRESS: TELEPHONE:

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Will. Riche ADDRESS:
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



M C Morris

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

heavy Greek Revival molding, deepset doorway

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115111
QUAD
SERIES
NEG. NO.

259 - 3

YOUR NAME: Gertrude Hetty DATE: May 15, 1975
YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854 7610
ORGANIZATION (if any): Nelson Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Nelson VILLAGE: West Nelson
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr. & Mrs. Robert Parker ADDRESS: Salem, N.Y.
6. USE: Original: Residence Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobble stone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   The me with interlocking joints ☒ pegged beams
   me with light members ☐
   ory load bearing walls ☐
   d. tal (explain)
   e. other Tap band turned legs
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    Dormers, bathroom & running water
    Panelled kitchen & dado 1965

12. PHOTO: P1-29



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: _____
j. other: ~~2 story barn, tenn. stone~~

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
2 side wings, rubble stone cellar walls
Rectangle square nails
2 panel doors plank floor boards
thick front doors 6 over 6 panes in windows
plain mantels, trim, narrow stair treads

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: before 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
The front room contained a millinery shop.
Manufacture & dealer in boots, shoes, rubbers
Oscar D. Sparhawk - 1878 Sarah J. Sparhawk
One of four houses of this design.
To
Lafayette Smart 2/1882
Asta Smart Nov. 3, 1930
Mary D. Williamson
Frances Williamson to
Robert and Alice Pinkerton

21. SOURCES: Deeds

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

260-3

YOUR NAME: _____ DATE: 11/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION


1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: John Wever ADDRESS: _____
6. USE: Original: garage Present: garage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: cement block
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☑
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO: P2-36

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

located on the site of an early general store.

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

261 -3

YOUR NAME: Gertrude Gilly DATE: March 5, 1975

YOUR ADDRESS: Salem New York TELEPHONE: 854 - 7610

ORGANIZATION (if any): Hebron Preservation Society
~~R.D. #2. Salem, N.Y. 12865~~

* *


IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: Main R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr & Mrs John Wever ADDRESS: Salem, New York
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain 3 entrance doors


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) _____ e. other _____
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):
    Enclosed porch, 1956, side wing, 1935, and back bedroom added 1954
    Modern kitchen (1950)

12. PHOTO: P2 - 31A



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☒
f. industrial ☐ g. residential ☒
h. other: It sits close to the road.

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) located in West Hebron His. Dist.
This building is very near the first established buildings - hotel, store & post office - 1780. It fits well into the historic district.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
one and a half story, gable roof, originally rectangular with wings added, pilasters at corners. Front entrance has transom, has sidelights and cornice with 36 in. doors. It is bracketed by panelled pilasters with astragal lure originally front hall, single flight stairs. Plastered walls. 2 panel doors. Thumb latches on some doors. Box locks

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: before 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Dr. Irwin

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

4
262 - 43

YOUR NAME: Gertrude Gettay DATE: Jan. 15, 1976

YOUR ADDRESS: Salem, N.Y. Hebron Preservation Society TELEPHONE: 854 7610

ORGANIZATION (if any): R D #2 Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Alister Campbell ADDRESS:
6. USE: Original: none Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    Old house but drastically remodeled

12. PHOTO: P2-32



HT-1

13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1866 map J.B. Keefe

James Craig

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

263-2

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: ~~C. Scott~~ Myatt Parker DATE: 11-4-76

YOUR ADDRESS: Salem N.Y. TELEPHONE: 854-3396

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S): Bedlam Corners General Store
2. COUNTY: Wash TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: Rt 30 Chamberlain Mills ROAD
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Donald Mercedes ADDRESS: West Hebron
6. USE: Original: Store Present: Store
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain Public Store

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Barn built- about 1900
Apartment modernized 1940

12. PHOTO: P2-33



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY: ~~None~~
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Key structure in west Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Old store windows intact, owners take pride in maintaining rural country store atmosphere.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1866 J. W. Getty
1878 Copeland & Matteson
1900 Peter Bussens
1934-1953 Oliver & Myrtle Barkley
1953-1957 Russell & Grace Sheldon
1957-1972 Carlton & Mabel Tyler.
1972-1974 Gordon & Pamela Simmerling
1974- Ronald & Hildegarde Reeder

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

264-3

YOUR NAME: Myrtle A Barkley DATE: 11-1-74
YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854-3296
ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐, b. private ☑
5. PRESENT OWNER: Vermit & May Colvin ADDRESS: Salem, N.Y.
6. USE: Original: Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain plank with Woden pegs


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): plumbing & electricity 1930; Garages - porch - heating system, new walls & floors 1939-74

12. PHOTO:



13. MAP



HT-1

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: _____
j. other: Stone fireplace

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located in West Hebron Historic Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Looks to be the oldest house in the village. Evidence of 4 fireplaces, (end chimneys) one mantle, dining room ceiling had been painted with a flower and leaf design (flaked off). Digging in the yard unearthed a wall running south of the house. Owners have been told the house was a church. It has been told that the library was formerly in the basement.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1866 Map - A McMillard

Whites had heard that a will, Malcomb ~~was a~~ who was a merchant lived here.

1888 George & Julie Stewart to Hiram Mann

1905 Hiram Mann to Charles McEachron

1905 Charles McEachron to George Ferguson

1905 George Ferguson to Helen McCloy

1930 Helen McCloy Estate to Helen McNeil

1939 Helen McNeil to Kermit & May White

21. SOURCES:

Liber 219 page 382 Jan

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

265-3

YOUR NAME: Sally Brillon DATE: Nov. 29

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): McMorris Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: Chamberlain's Mill Road
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Harold McMorris ADDRESS: R.D.2, Salem
6. USE: Original: residence Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located in the West Hebron Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Brackets on porch, ⌒ lintels, East lake door, molding intact, sliding double doors in parlor

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1870's or 80's (date on cistrn 1885)

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Style is consistent and compatible with historic district.

21. SOURCES:
Owner

other owners: Ken Coombs
Jamar Mullens
Stewart Adams

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

266-2

YOUR NAME: Gertrude Getty DATE: Jan. 15, 1976

YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society

R.D. #2 Salem N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S): Harold Matteson (Residence)
2. COUNTY: Wash TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: ~~E3~~ Chamberlini Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Harold Matteson ADDRESS: Salem, N.Y.
6. USE: Original: Dr. home and office outbuer Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P3-10A



HP-1 Madison written in concrete stairs

13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: Building used as Doctors Office early 1900

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Located in West Akron Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: about 1860

ARCHITECT: _____

BUILDER: built by Dr. Madison's father J.H. Madison

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Dr. J.H. Madison
Dr. W.B. Madison
The small Greek Revival Dr. office behind the house is a charming example of miniture temple form.

21. SOURCES:
on 1866 map

Owned by Dr. Madison in the late 1800's early 1900

Gordon Bardin

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

267 -2

YOUR NAME: Gertrude Gattis DATE: Nov. 20, 1925
YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610
ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION


1. BUILDING NAME (S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE West Hebron
3. STREET LOCATION: Chamberlins Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Allan Cathy Baer ADDRESS: Salem, New York
6. USE: Original: Residence Present: same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

P2-34A

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron Historic Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Large 2½ story building. Many features indicate an early house,

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

It has been a drug store, and a general store and dwelling. It is located near an intersection.

L.A. Pratt - Druggist - 187?

James Benton

to

L.A. Mattison May 18, 192?

to

Allan Bain 1951

21. SOURCES: Deeds

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

268 -3

YOUR NAME: Gertrude Getty DATE: Jan. 15, 1976

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ADDRESS:
6. USE: Original: Lyle Crosier ? home Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: alum.
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P2-30



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in W. Hebron Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

White sisters
E. Williamson
Minnie McConnell
Lyons
Nettie Beveridge
Edwin Ferguson
Lyle Crosier (18yrs.)

One of four house designed with a central structure and two side wings.

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

269-3

YOUR NAME: Myrtle Barkley DATE: 10-4-76
YOUR ADDRESS: Salem N.Y. TELEPHONE: 854-3296
ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Lydia Beneredge ADDRESS: Salem, N.Y.
6. USE: Original: Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: aluminum siding
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): plumbing, electricity, porches etc

12. PHOTO: P1-38



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Liber 54 page 3 1865 Joseph & Jane McKnight-
1865 Wm F McIntyre
1922 McIntyre to Margaret Howe
1924 Howard to Everett Williamson
Now owned by Lydia Williamson
Beveridge

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

270 -3

YOUR NAME: Gertrude Getty DATE: 10/15/1975

YOUR ADDRESS: Salem N.Y. TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society R. D. #2, Salem, N. Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME (S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: East Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr. + Mrs. D. Caldwell ADDRESS: Salem, N.Y. R.D. #1
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: siding
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☒ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) ____ e. other ____
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? ____
    c. list major alterations and dates (if known):

Aluminum siding, bathroom, modern kitchen
Cement block chimney 1976

12. PHOTO: P1-24A



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: Trees, lawn, bordered by
j. other: East Branch Black Creek

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: Next door was a Cooper Shop, in the early 1800's

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located on Black Creek in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Plank walls, Mortise & tenon joints, pegged, 4x4 studding, 6x6 window panes, Gr. Revival with back wing, Front Stairway

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: 1866 - Heirs of McGeoch
Ross Williamson
Kenneth Cooke
1965 Mr. & Mrs. Donald Caldwell

21. SOURCES: Owners 1866 Atlas

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

271-3

YOUR NAME: Gertrude Gitty DATE: Oct. 19, 1975
YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854 7610
ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence - Farm
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Estate-Maud Hanna ADDRESS: Salem, New York
6. USE: Original: Residence-Business (CHICKEN) Present: Unoccupied
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No. ☐
   Interior accessible: Explain Unoccupied


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    Bay window added
    Other not known

12. PHOTO: P11-18

13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☒ h. gardens ☒
i. landscape features: ~~fields, trees, lawn~~
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Greek Revival architecture.
Bathroom, electricity, no heating system.
State of deterioration

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: J. Thorn - 1866.
Remnants of carpenter shop with large fireplace
Erected in 1866 and until 1900.
People are waiting to restore it as soon as court case is settled.
1879 - Charles S. Hanna
1975 - in estate of daughter Maud Hanna

They raised fancy chickens for sale, Hebron Pres. Soc. has one of their pamph
advertising the breeds. (Faverolles chickens) Advertisment aftn 1905. Charles S. Hann

21. SOURCES: 1866 Atlas. Neighbors who had been there

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

272 -3

YOUR NAME: Gertrude Getty DATE: Oct. 10, 1976
YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610
ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME (S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr. & Mrs. John Tasso ADDRESS: Salem, New York
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other hand hewn beams
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
originally had double front doors & bathroom, furnace & lights - 1930's
kitchen enlarged - 1970-

12. PHOTO: P1 - 22A



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Lawns, shrubs, garden space
j. other: Smokehouse, Carriage House gone

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Is Greek Revival Architecture 2 story with side wing. It has a palladian window, 2 mantles, 6 panel doors, wide floors, square nails, escutcheons & plain trim with wide window & door casings between 2 front rooms. unusual window catches

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Before 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
One of four houses in the village with the basic center structure with side wing. This is the finest example.

1866 - owned by J.N. McClellan
1899 - J. & E. Donaldson to
A.V. McMillin to
1920 - Abbie Hanna to
1963 - Albert Hanna & Abbie Farm
1964 - John & Margaret Paterson

21. SOURCES:
Deed

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

273 -3

YOUR NAME: Gertrude Getty DATE: May 20, 1975

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr & Mrs. Richard Waite ADDRESS: Salem, New York
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐ b. wood frame with light members ☒ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? c. list major alterations and dates (if known):

1962–1978 Insulation, Panelling, storm windows, modern kitchen, ceilings heating system

12. PHOTO: P 1 20A

13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☒ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
located in W. Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Plastered walls with designs.
Bay window with wooden window seat Trim
4 panel doors

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1874

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Feb. 1902 - Mary Butler to Nancy Scott
1905 - Nancy Scott to Emma Rogers
1941 - Sadie Mahoffey + Ena Davis to Raymond + Sarah Lake to
1962 - Richard + Margaret Waite

21. SOURCES:
Deeds - Raymond Lake's father - eye witness

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

274 -3

YOUR NAME: Gertrude Getty DATE: March 15, 1975
YOUR ADDRESS: Salem, New York TELEPHONE: 864 7610
ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION


1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr + Mrs Robert Tourge ADDRESS: Salem, New York
6. USE: Original: Presbyterian Parsonage Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain 3 entrances

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM (if known): a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Kitchen - 1966 Panelling in living room - 1966
Bathroom - 1966

12. PHOTO: PI 19A



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: Nice lawn
j. other: A barn was torn down

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
located in West Hebron His. Dist

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Plank studding Central blacksmith backwing
Square Nails. Double front doors
Wainscoting, Chair rail, bay end porch, one story
Center Chimney Staircase enclosed between walls

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: About ~~1840~~ 1860 ~~ca~~

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
It is ~~right~~ next to the Classical School
built in 1855. It is simple of type,
~~with~~ Greek Revival
~~the~~ bracketed Cornices. It fits well into
the area. It was built as a passonage
for the Associate Presbyterian Church of West Hebron
established in 1799, and was used as such until 1938
when the Church merged with the Hebron United Presbyterians

21. SOURCES: Hebron Section of History of Washington County by
Ernsts and Ensign - 1878

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

275-3

YOUR NAME: Gertrude Getty DATE: Mass. 10, 1975
YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854 7610
ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Salvatore Vetrano ADDRESS: Salem, N.Y.
6. USE: Original: Residence boarding house Present: apts.
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain 2 front 2 back Private

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. [illegible] interlocking joints ☒ b. frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? c. list major alterations and dates (if known):

Remodelling is being done at present, inside and out. It has been a 2 family house

12. PHOTO: P1 17A



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☒ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: garden, lawn, driveway
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in W. Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Plank walls over brick floors, boards
Central block with 1 room 6 over 6 panes
Narrow clapboard Gabled roof with slate
Low stone foundation 2 story 4 panel doors,
three bay end porch Bracketed cornices thumb latches
center chimney Plain trim

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1840?

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Early Greek Revival
Ruins of tombstones found in the gardens.
In 1866 it contained a cabinet and millinier shop
owned by A. Rogg
Furniture operated by Robert Castes - 1878

21. SOURCES: Owners
Advertisement: Hebron Town Agricultural Society
Rules & By-laws - 1878

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 11511
QUAD
SERIES
NEG. NO.

276-3

YOUR NAME: Gertrude Getty DATE: Sept. 1974

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610


ORGANIZATION (if any): Hebron Preservation Society
Hebron Preservation Society
* * * * * * * * * * * * * * * * * R.D. #2, Salem, N.Y. 12865 * * * * * * * * * *


IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE West Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Jane TeBordo ADDRESS: Salem New York
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain front hall "entrances" private

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other. Pre-Cut Plastered walls
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    outside toilet removed
    fireplace added - 1950's
    Partition + sliding doors between parlors torn out - 1950's
12. PHOTO: P1-16
13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: trees, Shrubs, flowers
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☒
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) Yes
It fits well with the other houses along the street. Newest house in the West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Dark woodwork along stairway Tiffany windows Built-in china Closet Partition taken out between living room & dining room to make large room with fireplace added 9 ft. ceiling front porch

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1901

ARCHITECT: Pre-cut

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
This home was built in 1901 by Rev. George M. Oakley when he retired after 33 years as Pastor of West Hebron Associate Presbyterian Church. His wife lived here until 1907. It is said to be the first pre-cut home in the area - purchased from Sears Roebuck. Most of the area helped to erect it.

21. SOURCES:
1907 - To Hannah & Margaret McClellan
History of Hebron United Presbyterian Church
1790-1965

22. THEME:

277 -3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 11511
QUAD
SERIES
NEG. NO.

YOUR NAME: Gertrude Getty DATE: 10/15/1995

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R.30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr. + Mrs. Howard Sipe ADDRESS: Salem, New York, R.D.# 1
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain: 3 entrance doors Drive at the side

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☒ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? c. list major alterations and dates (if known): Originally open stairway from the front, changed to the side. Downstairs bedroom made into a bathroom. Upstairs hall made into 2 bedrooms. Front living room divided.
12. PHOTO: PI-13A 13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY: torn down
a. barn ☒ b. carriage house ☒ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: lawns in front & back - sloping
j. other: M.E. church close to North side

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: M.E. church & parking lot to North
Originally a picket fence surrended the lot.

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
- located in West Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): Paschal's front
Double door - Greek Revival Architecture, with back wing, wide boards on
2 story the flrs, square nails used, small window
panes, 6/6 upstairs, Asch stone trim, 6 panel doors
Plastered ceilings with decorated (swing) pediment
Boxed cornices.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Before 1866

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
It is in a village of many houses of similar early architecture. Being near to creek and water mill the owners of it was an important residence of the area

Owned by C. A. Getty - 1866
" by Alexander Williamson
Mar. 22, 19
Deeded to Hattie McClellan -
" to John & Susie Crowe - 1916
" to Earl D. Hickey - 1946
" to Clayton & Mary Barkley - 195
" to Kenneth & Kathleen Simpson - July 19

21. SOURCES: Deed Citations

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

278 -2

YOUR NAME: Gertrude Gotty DATE: Dec 6, 1994

YOUR ADDRESS: Salem, New York TELEPHONE: 854 - 7610

ORGANIZATION (if any): Hudson Preservation Society

* *

IDENTIFICATION


1. BUILDING NAME(S): West Hudson Methodist Church
2. COUNTY: Columbia TOWN/CITY: Hudson VILLAGE: West Hudson
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Methodist Church ADDRESS:
6. USE: Original: Church Present: Church
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Two entrance doors

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐ b. wood frame with light members ☒ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? c. list major alterations and dates (if known):

1938 - electric lights installed in old lamps.
1940 - outside painted
1960 - new Hammond organ, inside redecorated

12. PHOTO: P1-12A



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Parking lot in back
j. other: Front steps and Lawn with shrubs

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: Key structure in the West Hebron His. Dist.
(Indicate if building or structure is in an historic district)
This is on a street of well kept homes built at the same period as earlier. It fits well into the surroundings. It is within the Proposed district

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Enclosed sheet

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1823

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
This church has played continually much since services with an active congregation. It has always been well kept and extended as strength to the village. Here have been celebrated the 100th anniversary of the Methodist Society and the 100th anniversary of the Church building.

21. SOURCES: Church Records
"History of Washington County 1739-1878"

22. THEME:

This building was started in 1893. It is a handsome frame building with a single steeple, bell and beautiful stained glass windows. The contract $7,800. The frame is 85 x 61 feet. The spire rises one hundred and five feet. Two doors at the front open into a vestibule from which double doors open into the auditorium. Over the vestibule is a room for prayer meetings, at the rear end of the auditorium and a platform is a handsome black walnut pulpit and reading desk. Other fine work is elaborately executed as follows:

Aprons to the right of the pulpit bear the Lord's Prayer in gilt letters with the Apostles Creed and Ten Commandments in Greek and the Lord's

"Art of Peace over Land & Sea."
On the pedestal of the
Lady Pilgrim we see upon
Bible with a sheaf of wheat lies
drooping upon it. On
a panel to the left in
a cross. And crown, underneath is the apostles' Creed,
also in gilt letters. The
beautiful frescoing was
done by Mrs. Diedrich, a
New York artist.

(The picket fence around
the front was given by
Hebron Mrs. Reed, since removed.)

Cost of Building and furnishing the new M.E. Church

1874

Feb	26	W.W. Scanlan for Glass &c		65	00
Apr	1	Charles Getty for "Shed last"		12	00
—	—	J.W. McCarty for deed writing &c		5	00
May	1	Paid Lewis Gaspeland on Contract		1500	00
June	1	J. Dickenson for moving old Church		125	00
—	20	Paid Lewis Gaspeland on contract		1000	00
Aug	8	10 cts per foot on 355 ft of Stained glass		35	50
—	—	"Head pieces" to Stained glass		20	00
—	—	"Beading" sides of Stained glass		12	00
—	12	Church Young and Express on Same		36	00
—	27	Paid Lewis Gaspeland on contract		500	00
		Rufus Shaw for Stone work		28	00
Sept	2	A.T. Stewart for 62½ yds Terry for cushions		106	10
—	—	D.C. Hull & Sons for Twist —	—	100	05
—	—	Freight on Terry and Twist		3	00
—	17	Meneely & Kimberly for Bell (1000 lb)		395	44
—	17	King & Veillaucke for Frescoing		242	00
—	17	Paid Lewis Gaspeland on contract		500	00
—	17	Exchange on Check for Bell		1	00
—	17	Freight on Bell		3	36
—	17	— — "Trial" Bell		2	64
—	17	Return freight on bell on trial		3	30
—	17	L. Liddle 85½ yds Muslin for cushions		9	80
—	29	2 Chairs for "rostrum" and freight		21	35
Oct	15	4 Double Bracket Lamps at $4		16	00
—	—	2 Single Bracket Lamps		5	50
—	—	Nickell Plated "Student" Lamps for Pulpit		9	50
		Express on Lamps			70

1844

		Amount brought up from page 18		4758	27
Oct	16	A Roggy for Labor & materials on cushions		48	00
–	–	– " – Casting Pulpit Chairs		2	00
–	–	Whitmore Painting Church, one coat		23	00
–	–	6 Gallons Oil		6	00
–	–	Keiss & Beattie 100 lbs Lead		10	00
–	–	– " – – 50 lbs Zinc		7	00
–	–	W & J Bagley for securing 6322 ft Lumber		31	61
–	–	Paid Levi Copeland for "Settees"		120	88
–	24	J A Ferris Chandeliers & Trimmings		53	68
–	–	Freight on Chandeliers and Lamps		1	47
–	–	Paid Levi Copeland		1256	70
–	–	J Blashfield 222 yds Carpet at 95 cts p yd		210	90
–	–	Howe & Co Hooks and Screws		1	84
–	–	Bussers & Co. Thermometer			85
–	–	– Carved Basket for "Communion Setts"			90
–	–	– " Welcome Mat		3	00
–	–	– Step Ladder		2	25
–	–	– Black & Walnut Sidebury Steps		4	25
–	–	– 2 Collection Baskets			75
–	–	– " – –			28
–	–	Charles Whitcomb Clock		7	50
–	–	Bacinnel & Brown 52 Hymn	Books	38	48
–	–	– – 5 Tributes of Praise		4	00
–	–	– – Marking above Books		5	70
–	–	Express on Bible & Hymn Books			35
–	–	Nelson Stearns Mill Pulpit		45	00
–	–	6 yds Ticking for Cushions		8	20

1874

		Amount brought up from page 19		6652	91
Oct	24	J. H. Thomas. 304 lbs Russia Pipe		76	00
—	—	— — 8 Corrugated Elbows		12	16
—	—	— — — 2 Stable Bowls		6	50
—	—	— — — 2 "Gennett" Stoves		32	00
—	—	— — — Trimmings as per bill		1	63
—	—	2 Rattan Mats		3	00
—	—	3 Cocoa Mats		7	50
—	—	Express on above Mats			35
—	21	Paid Dr Isaac Dedicatory Services		100	00
—	—	S. D. Stewart for insuring Church 3 years		100	00
—	—	Paid Rev - Kimballs Expenses to Iowa		5	00
Nov	1	Interest on notes &c to date		93	33
		Express on Seedless &c		1	00
—	11	A Boggy Making Altar Cushions		5	00
—	—	— — Covering Sofa		6	50
—	—	— — — Buttons &c for Cushions		5	00
—	—	— — — Boarding Painters		4	50
—	19	Paid Mrs Eckleys for making Carpet		1	50
—	—	Oil Cloth Patterns		1	25
—	—	Door Guards			40
—	—	No 20 Gennett Stove for "Prayer room"		14	00
—	—	11 lbs Russia Stove Pipe		2	75
—	—	1 Elbow and Collar		1	20
—	—	1 Damper			25
—	—	15¼ lbs Zinc		2	50
—	—	Paid Blanchfield for Table		13	50
—	—	Wire Board		3	00

1874

		Amount brought up from Page	20	7152	74
Nov	25	Tin Shovel and Steam Pipe			75
—	—	53 Revised Hymns "		12	38
—	—	Paid Deacons for Table cloth		3	00
—	—	Stair Carpet		8	10
—	—	Rods for Stair Carpet		2	25
—	—	6 Black Walnut Chairs & freight		20	45
—	—	Paid J Blackfield for Book Case		15	00
—	—	Wm F McIntyre for repairing fire Screen		1	00
—	—	Fencing material		5	40
—	—	Paid Wm F McIntyre for 6½ days Labor		16	25
—	—	Paid Wm McFarland for digging post holes		2	00
1875					
Feb	10	Reuben Shaw for repairing Church		8	20
—	26	Pennsylvania Slate Co for Slate & Spouts for work		27	00
Mar	1	Ballance due on S S Library over and above receipts from penny collection, which was $27		38	76
—	22	R Copeland for cost of second hearse		104	00
—	—	T Copeland for 3 Barrels Lime		4	95
—	—	— — — Steam Pipe Hooks		3	00
		Interest on note at Bank of Salem, given			
		Ap 20th for 1 year, of $1256.70		87	96
Apr	1	Paid R Copeland for Labor		60	00
		Painting second hearse & fence		5	00
—	—	Paid interest on bill $3566. 6½ months		13	48
		Amounting to		7592	02

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

279 - 3

YOUR NAME: Gertrude Getty DATE: Mar. 7, 1975

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr. & Mrs. Fred Barnes ADDRESS:
6. USE: Original: Residence Present: 4
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain 4 entrance doors

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Insulation hotwater furnace bathroom Archway - probably double door between 2 living rooms

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: lawn, schubs, large trees, fields
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
located in W. Hebron His. Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Wainscoting in kitchen stone foundation
~~Wide board panelling upstairs~~ plank walks
Architrove trim
wide floor boards probably covered, sun burst in the pediment

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1869?

ARCHITECT: _____

BUILDER: Robert Copeland

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Greek Revival with sunburst, side wing 2 story

Robert + Betsey Copeland to
George Ashley April 3, 1869
Trustee + Martha Ashley
to Mar. 22, 1902
John + Martha Dunning
will of Martha Oct. 5, 1920
John Dunning to Guy Guthrie
& Maud D.
Guy Guthrie to Donald Reynolds
Dec. 7, 1970
to Fred Barnes 1973

21. SOURCES:
abstract of deeds

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

280 - #3

YOUR NAME: Gertrude Getty DATE: Jan. 12, 1975

YOUR ADDRESS: Salem, New York TELEPHONE: 854 7610

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: West Hebron
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr & Mrs. Fred Cary Jr ADDRESS: Salem, New York R.D#1
6. USE: Original: Parsonage - meth. Present: Private Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain /


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    Kitchen enlarged and modernized. 1969
    All modern facilities

12. PHOTO: P1-6

13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: terraced lawn

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
This building well fits the area. It is built on a hillside. It is in the historic district of West Hebron

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Contained a look out on the roof, Teakwood fireplace (marbleized effect) brought from England. ~~Contained a widow's walk on mansard roof~~ Cornices are supported with single brackets,

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1867-

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Original parsonage of Methodist Episcopal Church, It was a parsonage for more than 50 years.

21. SOURCES:

22. THEME:

ARCHEOLOGICAL SITE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK
518 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD. _____
SERIES _____
NEG. NO. _____

A281-2

REPORTED BY: Mac White

YOUR ADDRESS: R.D.2, Salem TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

DATE: 11/76

* *

1. SITE NAME: West Hebron Classical School - later W. Hebron Academy

2. COUNTY: Wash. TOWN/CITY: W. Hebron VILLAGE: W. Hebron

3. LOCATION: east side of village - N.E. corner of the large empty lot

4. PRESENT OWNER: W. Hebron Volunteer Fire Co.

5. OWNER'S ADDRESS: R.D.2, Salem

6. DESCRIPTION, CONDITION, EVIDENCE OF SITE:

☐ STANDING RUINS ☐ CELLAR HOLE WITH WALLS

☐ SURFACE TRACES VISIBLE ☐ WALLS WITHOUT CELLAR HOLE

☐ UNDER CULTIVATION ☐ EROSION ☐ UNDERWATER

☑ NO VISIBLE EVIDENCE ☐ OTHER _____

7. COLLECTION OF MATERIAL FROM SITE:

☐ SURFACE HUNTING BY WHOM _____ DATE _____

☐ TESTING BY WHOM _____ DATE _____

☐ EXCAVATION BY WHOM _____ DATE _____

☑ NONE

PRESENT REPOSITORY OF MAT 1954 _____

_____

8. PREHISTORIC CULTURAL AFFILIATION OR DATE: _____

9. HISTORICAL DOCUMENTATION OF SITE:

1866 map
Torn down 1973
It was sold to be dismantled for $280.00

10. POSSIBILITY OF SITE DESTRUCTION OR DISTURBANCE:

11. REMARKS:

12. MAP LOCATION

7 ½ MINUTE SERIES QUAD. NAME: _____

15 MINUTE SERIES QUAD. NAME: _____

U.S.G.S. COORDINATES: _____

D.O.T. COORDINATES: (if known) _____

ATTACH SKETCH, TRACING OR COPY OF MAP

SOURCE OF MAP:

13. PHOTOGRAPHS (optional)



(ATTACH)

Below the Devil's Threshing Floor stands a shrine to the memories of yesteryear, the old school house, torn down in the year 1973.

The West Hebron Classical school was chartered by the regents of the university of the state of New York March 22, 1855. Building was erected that summer.

At the opening session G. D. Stewart was the principal; Harriet N. Rowan preceptress; and J. T. McLean, assistant.

This academy was quite successful for a period of eight or ten years, when it became expedient to convert it to a union free school.

The Trustees made an agreement with the board of education of the union free school district that upon payment of one thousand dollars, to lease the academy building for a term of ten years.

In 1878 The principal was David Reid, intermediate teacher, Mary Wilson and Maggie Gibson primary department.

The high school department was discontinued about 1927 sending the pupils to Salem High School.

In 1939 a centralized school district was formed taking the seventh and eighth grades as well as students of high school age to Salem.

The last teachers of the first six grades to teach in the old classical academy building were Miss Leona Barkley and Miss Lura Belle McKinney.

Finally in 1954 the doors were closed having served the people of West Jefferson for a century or partly ninety-nine years.

also many from Argyle.

Now to go back to some interesting facts from 1855 to 1954 as related by citizens still living in 1976:—

Below the Devil's Threshing Floor stands a shrine to the memories of yesteryear, the old school house, torn down in the year 1973.

The West Hebron Classical school was chartered by the regents of the University of the State of New York March 22, 1855. Building was erected that summer.

At the opening session G. D. Stewart was the principal; Harriet N. Rowan preceptress; and J. F. McLean, assistant.

This academy was quite successful for a period of eight or ten years, when it became expedient to convert it to a union free school.

The Trustees made an agreement with the board of education of the union free school district that upon payment of one thousand dollars, to lease the academy building for a term of ten years.

ARCHEOLOGICAL SITE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD. _____
SERIES _____
NEG. NO. _____

A282-1

REPORTED BY: Myrtle Barkley

YOUR ADDRESS: Salem, N.Y. TELEPHONE: 854-3296

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N.Y. 12865

DATE: _____

* *

1. SITE NAME: Robert Creighton (first settler in valley)

2. COUNTY: Wash TOWN/CITY: Hebron VILLAGE: _____

3. LOCATION: Corner Scott Lake Rd & Chamberlain Mill Rd.

4. PRESENT OWNER: Myrtle Barkley & Gerrit White

5. OWNER'S ADDRESS: Salem, N.Y.

6. DESCRIPTION, CONDITION, EVIDENCE OF SITE:

- ☐ STANDING RUINS
- ☐ CELLAR HOLE WITH WALLS
- ☒ SURFACE TRACES VISIBLE
- ☒ WALLS WITHOUT CELLAR HOLE
- ☒ UNDER CULTIVATION
- ☐ EROSION
- ☐ UNDERWATER
- ☐ NO VISIBLE EVIDENCE
- ☐ OTHER _____

7. COLLECTION OF MATERIAL FROM SITE:

- ☐ SURFACE HUNTING BY WHOM _____ DATE _____
- ☐ TESTING BY WHOM _____ DATE _____
- ☐ EXCAVATION BY WHOM _____ DATE _____
- ☐ NONE

PRESENT REPOSITORY OF MATERIALS: _____

8. PREHISTORIC CULTURAL AFFILIATION OR DATE: 1769

9. HISTORICAL DOCUMENTATION OF SITE: Robert Creighton settled on this site in 1769. This fact is recorded in the Washington County history as published in 1878. He was the great-great grandfather of the present owners.

10. POSSIBILITY OF SITE DESTRUCTION OR DISTURBANCE: None

11. REMARKS: Present buildings built since 1900

12. MAP LOCATION

7 ½ MINUTE SERIES QUAD. NAME: _____

15 MINUTE SERIES QUAD. NAME: _____

U.S.G.S. COORDINATES: _____

D.O.T. COORDINATES: (if known) _____

ATTACH SKETCH, TRACING OR COPY OF MAP

SOURCE OF MAP:

13. PHOTOGRAPHS (optional)

(ATTACH)

In 1769 three men,
David Whedon, John Hamilton and
Robert Creighton settled in what is
now the town of Hebron. Whedon
on the place Grace Ensign and
daughter Betty now reside. John
Hamilton at the place owned
by Viola Fulwood. Both properties
are on Route 22.

The third early settler, Robert
Creighton is the only one still having
descendants in the town, as far as
can be learned.

Creighton had one son and five
daughters, Sara married William White.
They had ten children, one son
named Thomas remained on the
farm at the corner of Scott Lake Road
and Chamberlin's Mill Road. He was
the father of the late Arch T. White.

This property is owned jointly
by Creighton's great-great grandchildren
Myrtle Barkley and Kermit White.

Kermit has one son Archie Quentin,
whose son is named William Thomas,
thus keeping the early family given
names. They also reside in Hebron.

Westhaven
Present House & Barn
Dunlavan Rd.
First Cabin
Old spring
Old road Still traceable in several places
Scots Lake
Scots Lake Rd.

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

283-2

YOUR NAME: Sally Brillon DATE: Oct. 75'

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865


IDENTIFICATION

1. BUILDING NAME(S): Stone House
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Mier Lane - really was Castle Green Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Alfred Schier ADDRESS: 425 E. 80th St., N.Y.C. 10001
6. USE: Original: grist mill Present: summer house
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☑
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☑ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: clapboard gable
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☑
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: stream behind, two dam remains
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: swamp

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Building sets near stream and old road now closed, was in a settlement known as Castle Green.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Hebrons only stone house - beautiful thick walls

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1790's - 1810

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Few stone buildings in this area - only one in Hebron, ~~may have been a mill — before anyone now remembers~~. was a grist mill, owner says opening in back wall for wheel shaft. Two dam remenants above it. No equipment left. "Tommy Tom" daug. Mabel Montgomery

21. SOURCES: 1853 Map - J. Ferguson
1866 Atlas - J. Kennedy
Gore Patent.

22. THEME: Alfred Stahler

Early Settlers

284-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Carolyn C. Webber DATE: 6/75

YOUR ADDRESS: Webber Rd. Salem, R.D.#2 TELEPHONE: 854-3457


ORGANIZATION (if any): Hebron Preservation
Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

IDENTIFICATION


1. BUILDING NAME(S): dwelling
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: —
3. STREET LOCATION: Darfler Road
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Frank Darfler ADDRESS: same
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    nd dates (if known):



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☑
i. landscape features: flowers around house & across road
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Miss Margaret Reynolds
Atkinson
Cronin
Clark Wilbur
Evelyn & Frank Darfler

21. SOURCES:

285-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: HAROLD LAMBERTS DATE: 7/22/75
YOUR ADDRESS: R.D.1 GRANVILLE TELEPHONE: 854-3572
ORGANIZATION (if any): Hebron Preservation Society R.D. #2, Salem, N.Y. 12865


IDENTIFICATION

1. BUILDING NAME (S): HEATHER BROOK FARM
2. COUNTY: WASH. TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: COUNTY ROUTE 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: SAME ADDRESS:
6. USE: Original: JOHN McCONNELL Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No. ILLNESS


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☑
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    REMODELED IN 1930's

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: MAPLE TREES FLOWER GARDEN
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) YES

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: APPR. 1840

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES: HISTORY OF WASHINGTON COUNTY
PUBLISHED IN 1878

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

286-2

YOUR NAME: _____ DATE: _____

YOUR ADDRESS: Hebron Preservation Society TELEPHONE: _____

ORGANIZATION (if any) R. D. #2, Salem, N. Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME (S): School - Dist. # 5 - to be moved - 1869?
2. COUNTY: _____ TOWN/CITY: _____ VILLAGE: _____
3. STREET LOCATION: Rt. 31 - near Webber Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Ray Getty ADDRESS: _____
6. USE: Original: _____ Present: storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



HT-1

13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

287-3

YOUR NAME: Carolyn C. Webber DATE: 6-75

YOUR ADDRESS: Salem, R.D. N.Y. 12865 TELEPHONE: 854-3457
Hebron Preservation Society

ORGANIZATION (if any) R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S): house
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: off 31 Campbell Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Roy Campbell (Reg) ADDRESS: R.D. #2 Salem
6. USE: Original: Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? c. list major alterations and dates (if known):
    additions: kitchen → garage on south end

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Andrew Qua - to Joseph Qua
Thomas H. Williamson 1873 - to James Robert Campbell - 1918

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

288-3

YOUR NAME: Carolyn C. Webber DATE: 5-76

YOUR ADDRESS: Webber Rd. R.D #2 Salem, N.Y. 12865 TELEPHONE: 854-3457

ORGANIZATION (if any): Hebron Preservation Society

* * * * * * * * * * * * * * * * * * P.O. #2 Salem N.Y. 12865 * * * * * * * * * * *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Webber Rd.
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Carolyn Webber ADDRESS: Webber Rd., R.D #2 Salem
6. USE: Original: home, farm Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☒
   Interior accessible: Explain yes


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: brick-lined
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☒ h. gardens ☐
i. landscape features: _____
j. other: wagon shed

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
deed dates back to 1792 - part of lot #24
in family since 1859

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
1792 - deeded to Alexander McCleland from Alexander Kennet
1859 - James McClellen + wife Nancy
to
Hugh G. Dennison
1881 - Hugh G. Dennison + wife, Rachel Dennison
to
William McElroy
1904 - William McElroy + Wife, Eliza A.
to
Joseph C. McElroy
1950 - Joseph C. McElroy
to
Sherwood A. Webber, Jr.

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

289-3

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: _____ DATE: _____

YOUR ADDRESS: Hebron Preservation Society TELEPHONE: _____

ORGANIZATION (if any): R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: _____
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: James Arend ADDRESS: _____
6. USE: Original: farm Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: building new small barn N-W. from house

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Coy - son or brother of original Coy
Dennison
Tom & Mary Jane McGilroy - related to Dennisons on place on Ray Campbell's road

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

290-3

YOUR NAME: _____ DATE: 11/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any) Hebron Preservation Society R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S): R Farmhouse
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: ✓
3. STREET LOCATION: R.31
4. OWNERSHIP: a. public ☐ b. private ☑ Dec.
5. PRESENT OWNER: Richard Mattison 1962- ADDRESS:
6. USE: Original: Coy Farm Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ aluminum siding (1974) c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO: P/7-18A



13. MAP:



HT-1

more than 50 yrs. old

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☑ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
bell in cupalo - C. S. Bell + Co. - Hillsboro, O. - 1889 - Size 4

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:


Edward L. Coy homestead - shown on pg. 25 "Hebron, New York" a reprint of Hebron section of Wash. Co. history of 1878 pub. by Hebron Preservation Soc. 1975

Coy was well known for raising hybred seed + Ayshire cows.
E L Coy developed golden bantam corn - Sold two quarts of seeds to W. Atlee Burpee Co. for $25.00 in 1900. Burpee named it and put it on the market in 1902.

21. SOURCES:

P17—19A

290



Cupola on Richard Matteson (Coy Place) outbuilding