Folder 4 -

Building-Structure Inventory Forms

~~#1-76~~

~~#77-172~~

~~#173-290~~

#291-379

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

291-3

YOUR NAME: John Cavender DATE: Nov. 15, 1976

YOUR ADDRESS: RD2, Salem, NY. 12865 TELEPHONE: 854-3597

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S): farm house
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: County route 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: John, James, Ted Cavender ADDRESS:
6. USE: Original: Farm house Present: same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P14-2A



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY: (horse barn)
a. barn ☑ b. carriage house ☑ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
House rebuilt in 1870s. Only north end (kitchen) remains of original construction. This portion has foundation for fire-place in cellar. Date uncertain.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

J. Robinson 1853 Map
W. Robinson 1866 "

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

292-3

YOUR NAME: Jean C. Getty DATE: Feb. 1976

YOUR ADDRESS: R.D.#2 Salem Ny TELEPHONE: 518-854-7898

ORGANIZATION (if any): Hebron Preservation Society
Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

IDENTIFICATION


1. BUILDING NAME(S): House
2. COUNTY: Wash. TOWN/~~CITY~~: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Ralph + Jean Getty ADDRESS: R.D. #2 Salem, NY.
6. USE: Original: House Present: none
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain bad.

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) old house c 1772 e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☒
11. INTEGRITY: a. original site ☐ b. moved ☒ if so, when? c. list major alterations and dates (if known):

Alex Webster bldg.

12. PHOTO: P17-



13. MAP:



HP-1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: 2 maple trees
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: adjacent to Hon. Alex. Webster
(Indicate if building or structure is in an historic district)
was most prominent name in town: State Senator
1777-1785 and 1790-1793 Assembly 1788-89
Supervisor of Hebron - died 1810

18. ~~OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known)~~:
Owners
① Alex Webster ② George Webster ③ Simeon Webster
④ J. Beattie ⑤ Paul Beattie ⑥ Ray and Ralph Getty
⑦ Ralph + Jean Getty

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1772 - ?

ARCHITECT: _____

BUILDER: ? Alexander Webster

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

293-3

YOUR NAME: Jean Getty DATE: 2-1976

YOUR ADDRESS: R.D. #2 Salem NY TELEPHONE: 854-7898

ORGANIZATION (if any): Hebron Preservation Society

Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865


IDENTIFICATION

1. BUILDING NAME(S): House
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Co Road #31
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: ADDRESS: R.D. #2 Salem NY
6. USE: Original: House Present: House
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when? c. list major alterations and dates (if known):
    dining Room to modern Kitchen 1969
    new porch floor 1974
12. PHOTO: P17-20A
13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: large maple trees + 2 ~~evergreen~~ green
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: Beattie family 1870's

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

294-3

YOUR NAME: BRANSON DATE: 8/11/75

YOUR ADDRESS: R.D. #2 (County Route #31) TELEPHONE: 518-854-3339

ORGANIZATION (if any): Hebron Preservation Society R.D. #2, Salem, N.Y. 12865

* * * \

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: study

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: I suppose you could
(Indicate if building or structure is in an historic district)
make a strong argument that this was
"historic" in one way or another.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: around 1800

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Unaltered exterior —
eyebrow windows - charming setting

21. SOURCES:

Rob + Anne Crosier
1944 - Meredith + Gertrude Getty
Wood

295-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: DATE:

YOUR ADDRESS: TELEPHONE:

ORGANIZATION (if any): Hebron Preservation Society R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence of Laurence & Florence Getty
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: W. Hebron
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Ralph & Jean Getty ADDRESS: Salem, New York
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain Private

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: aluminum siding
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other Plank
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): 1936 - 1993 bathroom, nursing, insulated & kitchen drilled well aluminum siding


12. PHOTO:

1



HT-1

13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☒ c. garage ☒
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: lawns, trees
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: good trout stream

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Cornerblocks wainscoting & chair rail
square nails in kitchen originally
6 panel doors

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Later Guthrie hung himself in the barn

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: before 1848

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Cummings

Lester Guthrie - 1910
James & Stella Macklin
James Sloan
Laurence & Florence Getty
1924-1971

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

296-3

YOUR NAME: Sally Brillon DATE: July 6, 1975

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: ~~R.D.~~
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mrs. Keay ADDRESS: R.D. 2
6. USE: Original: farmhouse Present: farmhouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain

up from Dorthy


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: hilly, fields
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: farmland

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Farmhouse set on a hillside of a valley.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Stewart Adams 1925c
to
Philip Stannard
to
Egbert Shaw

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

297-3

YOUR NAME: Miss Dorothy Safford DATE: 75'

YOUR ADDRESS: RD2, Salem N.Y. 12865 TELEPHONE: 518-854-3318

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME (S):
2. COUNTY: Washington TOWN/~~CITY~~: Hebron VILLAGE:
3. STREET LOCATION: Route 31
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Dorothy Safford ADDRESS: R.D.2, Salem, N.Y. 12865
6. USE: Original: private home Present: same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☒
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
Roof of wing and porch were originally separate. Later combined into one roof. Sometime between 1916-1925





Deeds
12-15-1947 Earl Y. Safford + Helen M. Safford to Earl Y. Safford + Dorothy E. Safford
Recorded 12-22-1947 Liber 264 Page 268
10-7-1912 Ebenezer Kinney + Margaret E. Kinney to Earl Y. Safford + Helen M. Safford
Recorded 10-8-12 Book No 156 Page 64
4-2-1883 James S. Craig to Ebenezer Kinney. Recorded 4-11-1883 Liber 94 Page 82
3-26-1878 Archibald McEachron and wife to James S. Craig
Recorded 4-1-1878 Liber 83 page 552

HP-1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☒
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☒ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: Mr Copeland (father of Mrs Oliver Beebe)

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

L. Copeland on 1866 Atlas

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

298-3

YOUR NAME: Harold Craig DATE: 11/10/76.
YOUR ADDRESS: N. Hebron, N.Y TELEPHONE: 642-1749
ORGANIZATION (if any): Hebron Preservation Society.

* *


IDENTIFICATION

1. BUILDING NAME (S):
2. COUNTY: Wash TOWN/CITY: HEBRON VILLAGE: —
3. STREET LOCATION: LAING HILL RD
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: J. BERNARDO ADDRESS: R#1 GRANVILLE
6. USE: Original: HOME Present: STORAGE FOR YEARS
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    NOW BEING REPAIRED

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

299-3

BUILDING-STRUCTURE INVENTORY FORM

FOR OFFICE USE ONLY
UNIQUE SITE NO. 11611
QUAD
SERIES
NEG. NO.

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

YOUR NAME: Harold Craig DATE: Nov. 10, 1976

YOUR ADDRESS: N. Hebron, NY TELEPHONE: 642-1749.

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: SCOTT RD
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Emond, Michael ADDRESS: R#1 GRANVILLE
6. USE: Original: HOME Present: SAME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

300-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Harold Craig DATE: Nov. 10, 1976
YOUR ADDRESS: N. Hebron, N.Y TELEPHONE: 642-1749.
ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: CO RT. # 31
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Campbell, Ralph ADDRESS: RH1 SALEM
6. USE: Original: Home Present: Same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐ b. wood frame with light members ☑ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

301-3

BUILDING-STRUCTURE INVENTORY FORM

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

William and Julia Carson
YOUR NAME: Catharine L. Hicks DATE: October 1974

YOUR ADDRESS: Granville, R.D.1, N.Y. 12832 TELEPHONE: 518-642-2179

ORGANIZATION (if any): Hebron Preservation Society
R.D.#2 Salem N.Y. 12865

* * * \

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☑ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☑
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c. 1830 - 1840 (estimated)

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

302-3

BUILDING-STRUCTURE INVENTORY FORM

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

YOUR NAME: Harold Craig DATE: November 1976

YOUR ADDRESS: R.D. #1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society R.D. #2 Salem, N.Y. 12865


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: CO RTE 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Liebeg, Ken ADDRESS: RT #1 GRANVILLE
6. USE: Original: HOME Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:



21. SOURCES:

303-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Harold Craig DATE: ~~11-5-76~~ 11-10-76
YOUR ADDRESS: W. Hebron, N.Y. TELEPHONE: 642-1749.
ORGANIZATION (if any): Hebron Preservation Society.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: Co RT. #31
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Dennison, John ADDRESS: RH1 Granville
6. USE: Original: Home Present: SAME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

304-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Harold Craig DATE: Nov. 10, 1976
YOUR ADDRESS: N. Hebron, N-Y TELEPHONE: ~~Hunter~~ 642-1149
ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: PICCININI LANE
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Piccini's, FRANK ADDRESS: RH1 GRANVILLE
6. USE: Original: Home Present: SAME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

305-3

YOUR NAME: Roscoe + Marjorie Ely DATE: 11-10-76

YOUR ADDRESS: Granville, N.Y. TELEPHONE: 854-3125
R-7-20-#2 12832

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Dwelling
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: South of Belcher 2 miles
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Lorain + Florence ADDRESS: Granville, N.Y. 12832
6. USE: Original: Residence Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☒ h. gardens ☒
i. landscape features: _____
j. other: Silo & large decay barn

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Large pond - wild life marsh

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1890

ARCHITECT: _____

BUILDER: Not known

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Architect unknown, but the following houses are identical in plan & apparently built by the same person -
Ralph Keyes - Patterson Hill
John Hurd
Rosco Eli

21. SOURCES:

22. THEME:

306-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Colleen Coon DATE: 11/76

YOUR ADDRESS: RFD #2, Salem TELEPHONE: 854-7422

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: County Route 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: John E. ~~Coon~~ Clark ADDRESS: RFD #2, Salem
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain When owner is Home


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) House is situated Paralell to County Rt 30

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
House better known as the Dan Hurd Place
Interlocking beams, plaster + plank walls, Wide plank floors dog stairs - during renovation discovered old newspapers used in walls, dating back to Abe Lincoln's assination.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Appox - 1830 - 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Owners: Dan Hurd
John Hurd
Loren Mc Neil
John Coon

Carved cornice



21. SOURCES:

22. THEME:

307-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 15/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Barbara P. Reardon DATE:

YOUR ADDRESS: R.F.D #2, Salem TELEPHONE: 854-9363

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION


1. BUILDING NAME(S): Dwelling (Rose Cottage)
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Vicinity of Belcher
3. STREET LOCATION: County Rd #30 -
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Michael Sheridan ADDRESS: Huntington, L.I.
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain Summer only at this time

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐ (being remodeled)
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when? c. list major alterations and dates (if known):

running water - 1948
addition to back & put in bath - 1948
drilled well - new insulation - rewired - interior walls remodeled

12. PHOTO:



13. MAP:



UP 1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1830 – 50

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Hood Family built to use as a summer home—
Then used as a tenant house about 45-55

21. SOURCES: Ralph Reid

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

308-3

YOUR NAME: Ralph D. Reid DATE: Aug. 30, 1974

YOUR ADDRESS: RFD 2, Salem, N.Y. 12865 TELEPHONE: 518-854-7518

ORGANIZATION (if any):

* *

IDENTIFICATION


1. BUILDING NAME(S): Dwelling
2. COUNTY: Washington TOWN/CITY: Helvon VILLAGE:
3. STREET LOCATION: One mile north of Belcher-Co. Rt. 30
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Ralph D. Reid ADDRESS:
6. USE: Original: farm Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: Covered with aluminum siding
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☒ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? c. list major alterations and dates (if known):

Major repairs, and fireplace, ~~and~~ furnace and plumbing added 1930; Kitchen and cellar enlarged 1941; wood shed enlarged for garage 1963; aluminum siding 1968; Porch removed 1956; Insulation about 1950.

12. PHOTO:



13. MAP:



HP-1

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
Hen house + d. privy ☒ e. shed ☐ f. greenhouse ☐ Henhouse + Potato Storage
g. shop ☐ h. gardens ☒
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒ and farming
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: about 1825

ARCHITECT: ?

BUILDER: ?

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

Early settlers - farming

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

309-3

YOUR NAME: Barbara P. Reardon DATE: 11-10-76

YOUR ADDRESS: R.D #2, Salem TELEPHONE: 854-9363

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): Dwelling
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: —
3. STREET LOCATION: ½ mile no. of Belcher
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Robert Reid ADDRESS: R.D #2 Belcher
6. USE: Original: RESIDENCE Present: RESIDENCE
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ (PART - COVERED W/ ALUMINUM SIDING) b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? c. list major alterations and dates (if known):

*1 STORY HOUSE W/SLEEPING ATTIC CONSTRUCTED CIRCA 1790-1800 } CONSTRUCTION DETAILS BEAR THESE "LEGENDS" OUT.
ORIGINAL HOUSE LIFTED UP + COMPLETE 1ST STORY CONSTRUCTED CA. 1850
WOODSHED + SUMMER KITCHEN REMOVED, BEDROOM, LIVING ROOM + BATH ADDED - 1964
FIREPLACE ADDED - 1964 SCREENED IN PORCH - CA. 1936
GARAGE ADDED - 1965
ALUMINUM SIDING - 1969

12. PHOTO: P13-32A 13. MAP: 75' FLOWING WELL DRILLED - 1964

* ORIGINAL HOUSE HAD FIREPLACE EACH END OF HOUSE - PROBABLY REMOVED WHEN 1ST FLOOR ADDED IN 1850's.





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
SPACE BETWEEN 1ST FLOOR CEILING + 2ND FLOOR FLOOR IS 19" - TWO COMPLETE SETS OF TIMBERS AT RIGHT ANGLES TO EACH OTHER (BEARING OUT DESCRIPTION UNDER "11" ON OTHER SIDE).

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: CA 1790-1800

ARCHITECT: unk.

BUILDER: unk.

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
LAND GRANTED TO VETERAN OF REVOLUTION - HOUSE BUILT ON THIS SITE (GUILE WILSON)

21. SOURCES: Family History

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

310-3

YOUR NAME: _____ DATE: 11/76

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: R.45
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: James Stiff ADDRESS: _____
6. USE: Original: farm home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Copeland
-Haw. McNeil

21. SOURCES:

22. THEME:

ARCHEOLOGICAL SITE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK
518 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD. _____
SERIES _____
NEG. NO. _____

A 311-2

REPORTED BY: Washington County Planning Department
County Office Building
YOUR ADDRESS: Fort Edward, New York 12828 TELEPHONE: _____

ORGANIZATION (if any): _____

DATE: 11/76

* *

1. SITE NAME: Lytle Mill Site and Dam

2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____

3. LOCATION: off route 30 just no. of the cross road; to the east

4. PRESENT OWNER: _____

5. OWNER'S ADDRESS: _____

6. DESCRIPTION, CONDITION, EVIDENCE OF SITE:

☑ STANDING RUINS dam ☐ CELLAR HOLE WITH WALLS

☑ SURFACE TRACES VISIBLE mill ☐ WALLS WITHOUT CELLAR HOLE

☐ UNDER CULTIVATION ☐ EROSION ☐ UNDERWATER

☐ NO VISIBLE EVIDENCE ☐ OTHER _____

7. COLLECTION OF MATERIAL FROM SITE:

☐ SURFACE HUNTING BY WHOM _____ DATE _____

☐ TESTING BY WHOM _____ DATE _____

☐ EXCAVATION BY WHOM _____ DATE _____

☐ NONE

PRESENT REPOSITORY OF MATERIALS: _____

8. PREHISTORIC CULTURAL AFFILIATION OR DATE: _____

9. HISTORICAL DOCUMENTATION OF SITE:

10. POSSIBILITY OF SITE DESTRUCTION OR DISTURBANCE:

11. REMARKS:

12. MAP LOCATION

7 ½ MINUTE SERIES QUAD. NAME: _____

15 MINUTE SERIES QUAD. NAME: _____

U.S.G.S. COORDINATES: _____


D.O.T. COORDINATES: (if known) _____

ATTACH SKETCH, TRACING OR COPY OF MAP (P3-14)

SOURCE OF MAP:

13. PHOTOGRAPHS (optional)

Foundation of dam



(ATTACH)

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

312-2

YOUR NAME: Washington County Planning Department DATE: 11/76
County Office Building
YOUR ADDRESS: Fort Edward, New York 12828 TELEPHONE:

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: Belcher
3. STREET LOCATION: R. 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Helen Toomey ADDRESS:
6. USE: Original: drug store + P.O. Present: storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☑ if so, when? back from the road
    c. list major alterations and dates (if known):

12. PHOTO:

Smallest building



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: stream - hills
j. other: house

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Small building served as Belchers drug store and P.O. – interior unchanged still contains shelves and pigeon holes (12) for mail. Charming little building.

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

313-3

YOUR NAME: Fred & Dorothy Sutliff DATE: 12/76

YOUR ADDRESS: R.F.D. 2 Salem TELEPHONE: 854-7268

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Kehoes VILLAGE:
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Franklin Shaw ADDRESS: R.F.D. 2, Salem
6. USE: Original: Farming Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☑
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐ 4 ft. stone foundations on all sides.
   d. metal (explain)
   e. other House and barn put together with wooden pins
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: Pl-19



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☑ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Inside 7 house is brick lined. The cellar is divided into 3 sections each divided by brick walls.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

A. Beuendyl 1853 Map

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

314-3

YOUR NAME: Hebron Preservation Society DATE: 11-9-76

YOUR ADDRESS: R.D. #2, Salem, N.Y. 12865 TELEPHONE:

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME (S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mabel Harwood ADDRESS: R.D. #2 Granville, N.Y.
6. USE: Original: Present: dwelling
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☑
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: 76-18

13. MAP:





HT-1

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1853 ?

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

J + W. Wilson 1853 Map
W. Wilson 1866 "

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

315-3

YOUR NAME: Hebron Preservation Society DATE: 12/76
YOUR ADDRESS: R.D. #2, Salem, N.Y. 12865 TELEPHONE:
ORGANIZATION (if any): Hebron Preservation Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: —
3. STREET LOCATION: Rt. 31
4. OWNERSHIP: a. public ☐ b. private ☐ ?
5. PRESENT OWNER: Mrs. Charles Bohne ADDRESS: R.D. #2 Salem, N.Y.
6. USE: Original: Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1853 +
D. Beveridge 1866 Maps

21. SOURCES:

316-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Marion J. Lloyd DATE: Nov 30, 1976

YOUR ADDRESS: R.D#1 Granville TELEPHONE: 854-3387

ORGANIZATION (if any): Hebron Preservation Soc. n.y.

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Lloyd family ADDRESS:
6. USE: Original: Present: Farm home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain no

Lloyd

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☒
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    bath added on south end 1954

12. PHOTO:

13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☒
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☒ e. shed ☐ f. greenhouse ☐
g. shop ☒ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) No

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Was a story and a half house and made into a two story house by the Carrol family. This house at one time was roofed with slate and slate laid on the cellar floor that were brought at Wynnville and drawed by horses to the house.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Early 1800's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
This house is built on a land grant to Gracchenbush and we are the fourth owners. Gracchenbush to Brady then to Carrols then to the Lloyds. The old house was what they call a plank house so the lower story is of that construction. Gracchenbush was a soldier of the Revolution and was granted 1000 acres and our 96 is a part of that grant.

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

317-3

YOUR NAME: Carolyn Webber DATE: 1-30-77

YOUR ADDRESS: Salem, R.D #2 TELEPHONE: 854-3457

ORGANIZATION (if any): Hebron Pres. Society

* *

IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: ——
3. STREET LOCATION: Darfler Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Al Grasso ADDRESS: N.Y.C.
6. USE: Original: home Present: Summer home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:

13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

318-3

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION


1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: Gilchrest Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Stephen Jones ADDRESS: _____
6. USE: Original: barber shop Present: storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO: P4 - 36A

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

319-3

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: Gilchrest Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Stephen Jones ADDRESS: _____
6. USE: Original: home Present: Same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

12. PHOTO: P4-35A

13. MAP:





BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

320-2

YOUR NAME: _____ DATE: ~~5/~~ 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): _____

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: _____
3. STREET LOCATION: CO RT 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ART STEERE ADDRESS: DORSET, VT.
6. USE: Original: BLACKSMITH SH Present: VACANT
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain YES


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☒
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1840's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

321-3

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: _____
3. STREET LOCATION: COR #31
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: CLARENCE BAKER ADDRESS: RT#1 GVL
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: EARLY 1800'S, VERY OLD.

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

322-3

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: _____
3. STREET LOCATION: CO RT 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ART. STEERE ADDRESS: DORSET, VT.
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain ND


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HP-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Early 1800's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

323-2

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: _____
3. STREET LOCATION: RT 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: LILLIAN CRAIG ADDRESS: R#1 GUL
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1840's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

324-2

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: _____
3. STREET LOCATION: COR # 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ALAN YOUNG ADDRESS: RH1 GUL
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1850's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

325-2

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: _____
3. STREET LOCATION: CO RT #31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: DONALD YOUNG ADDRESS: RH1 GUL
6. USE: Original: STORE Present: STORE
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain YES


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: EARLY 1800's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

326-3

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: _____
3. STREET LOCATION: CO. RT # 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: CLIFFORD BOUTON ADDRESS: RT 1 GVL.
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1860's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

327

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: _____
3. STREET LOCATION: CO.R # 31
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: TRUMAN LIEBIG ADDRESS: R# 1 GVL.
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain ND


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. ~~open land~~ ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1870's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

328-3

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: |

ORGANIZATION (if any): H.S

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: _____
3. STREET LOCATION: CO RT 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: CECIL HICKS ADDRESS: RT1 GUL.
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HP-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: EARLY 1800's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

329-3

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: _____
3. STREET LOCATION: COR# 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: HAROLD CRAIG ADDRESS: R#1 GVL.
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain ND


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. ~~wood frame with light members~~ ☑
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Early 1800's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

330-3

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: _____
3. STREET LOCATION: C.R. #31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: HAROLD CRAIG ADDRESS: RH1 GVL
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☑
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1840's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

331-4

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: _____
3. STREET LOCATION: C.R. #31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: CLIFFORD HICKS ADDRESS: R#1 GVL.
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

333-3

YOUR NAME: _____ DATE: 2/77

YOUR ADDRESS: _____ TELEPHONE: _____

ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: ULSTER TOWN/CITY: HERON VILLAGE: _____
3. STREET LOCATION: CO. R #31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: HYMAN POLLOCK ADDRESS: R#1 GRANVILLE
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain ND


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: EARLY 1800's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

333-2

YOUR NAME: Hebron Preservation Society DATE: 12/77
R. D. #2, Salem, N.Y. 12865
YOUR ADDRESS: TELEPHONE:

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S): Farmhouse at Hebron Camp
2. COUNTY: Washi TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Presbytery Lane
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Presbytery of Albany ADDRESS:
6. USE: Original: farmhouse Present: sleeping + eating quarters for camp - Dorm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:

Neg. 18, 19, -0-19



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Within several miles of the Chamberlins Mill Historic Dist.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Fine craftsmenship used in this home. One fireplace - mantel with dimond shaped molding, curved mantel shelve

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c1800


ARCHITECT: _____

BUILDER: _____


20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Must have been built by same builder as Clark house in Belcher (form # 27) many architectural details identical: reeded window columns & pilasters; porch columns, seats, corner cupboard, window cornice

21. SOURCES:
Campbells, Prof. Johns
1866 Atlas - W. McGill

22. THEME:
Architecture




115/11 333-2



JAN • 78


Front Doorway

Porch detail



• JAN • 78


Detail on top of ~~apptly~~ posts




• JAN • 78


115/11 333-2


Mantel detail






Mantel on only fireplace, has hanb cupboard





11/333







JAN • 78

11/333












• JAN • 78




• JAN • 78

11/333







• IAN • 78




• IAN • 78

11/333







BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

334-3

YOUR NAME: Hebron Preservation Society DATE: 12/77
YOUR ADDRESS: R.D. #2, Salem, N.Y. 12865 TELEPHONE:
ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S): Bump Place
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: off
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Evert Gould ADDRESS: R.D. Granville
6. USE: Original: home Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☑
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other plank except so. basement wall, stone, brick, beam nogging
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:
P. 19, 26-36
south



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____


15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: stream and waterfall
j. other: orchard out back door

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Remote location, road to it only used by farmer,

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

wraught iron hardware, chair rail, beaded sheathing, wall cupboards, chimney strange shape & location  , red buttermilk paint, blue & white wall paper

SIGNIFICANCE


19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1866 map - W. Sweet



21. SOURCES:

on site inspection

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

334-3

YOUR NAME: Hebron Preservation Society DATE: 12/77
YOUR ADDRESS: R.D. #2, Salem, N.Y. 12865 TELEPHONE:
ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S): Bump Place
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: off
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Evert Gould ADDRESS: R.D. Granville
6. USE: Original: home Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☑
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other plank except so. basement wall, stone, brick, beam nogging
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:
P. 19, 26-36
south



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: stream and waterfall
j. other: orchard out back door

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Remote location, road to it only used by farmer,

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

wraught iron hardware, chair rail, beaded sheathing, wall cupboards, chimney strange shape & location  , red buttermilk paint, blue & white wall paper

SIGNIFICANCE


19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1866 map - W. Sweet




21. SOURCES:

on site inspection

22. THEME:


115/11 334-3




east end

Plank Construction

west





beam sections used for nogging along with stone, brick



BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

335-3

WASHINGTON COUNTY INFORMATION -
YOUR NAME: TOURISM AND HISTORIC PRESERVATION DATE: 12/77
COUNTY OFFICE BUILDING
YOUR ADDRESS: FORT EDWARD, NEW YORK 12828 TELEPHONE:

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S): Tommy Laymon Place
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: off Bunker Hill
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: David Laymon (Estate of) ADDRESS:
6. USE: Original: farm Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☑
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: plank
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:

P. 18 - 26, 31

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ (2) b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Just outside West Hebron Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Barn with beautiful timbers and stone wall, old road leads to the house, not used now.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____


20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

R. Layman – 1866 Atlas
Tommy Layman was the village jeweler at the turn of the century. Jewelry magazines found with dates of 1911 & 1917


21. SOURCES:

22. THEME:






rack found in barn



wood shingles under slate



BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

336-3

YOUR NAME: Hebron Preservation Society DATE: 1/78

YOUR ADDRESS: R.D. #2, Salem, N.Y. 12865 TELEPHONE:

ORGANIZATION (if any):

* *

IDENTIFICATION


1. BUILDING NAME(S): Lundy Tenant House
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Rte. 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Max Lundy ADDRESS:
6. USE: Original: Present: Tenant house
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

was a barn across the road - burned

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Exceptional panoramic view

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c 1878

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1866 D.W. Ripley
His wife married Thomas Thomas a Welshman
in 1930
Lundy

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

337-3

YOUR NAME: Hebron Preservation Society DATE: 1/78
YOUR ADDRESS: R.D. #2, Salem, N.Y. 12865 TELEPHONE:
ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Middle Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Wesley Nelson ADDRESS:
6. USE: Original: farm Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

338-3

YOUR NAME: Hebron Preservation Society DATE: 1/78

YOUR ADDRESS: R.D. #2, Salem, N.Y. 12865 TELEPHONE:

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Middle Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: John Sather ADDRESS:
6. USE: Original: farm Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? c. list major alterations and dates (if known): being rehabilatated

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
beautiful doorway with side lights

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1866 map Beveridge

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

339-2

YOUR NAME: Hebron Preservation Society DATE: 1/78

YOUR ADDRESS: R.D. #2, Salem, N.Y. 12865 TELEPHONE:

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S): District School # 10
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Middle Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: John Sather ADDRESS:
6. USE: Original: dist. sch. Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain ~~N/A~~


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): recently painted red + white + dist. sch. sign added

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

on 1866 map

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

340-3

YOUR NAME: Hebron Preservation Society DATE: 1/78
YOUR ADDRESS: ~~R.D. #2, Salem, N.Y. 12865~~ TELEPHONE:
ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME (S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Smith Hill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: G. Stoddard ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP: ✓



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

McConnell (or Woodard, check 1866 map)
John & Mary Smith

21. SOURCES:
Arch Crary

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

341-3

YOUR NAME: WASHINGTON COUNTY INFORMATION - TOURISM AND HISTORIC PRESERVATION DATE: 1/78
YOUR ADDRESS: COUNTY OFFICE BUILDING FORT EDWARD, NEW YORK 12828 TELEPHONE:

ORGANIZATION (if any):

* *

IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Middle Rd.
4. OWNERSHIP: a. public ☐ private ☑
5. PRESENT OWNER: Giambalbob ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:

19-2A



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

McClellan
Newton Shaw
Mrs. Miller

21. SOURCES:

22. THEME:

1

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

342-3

YOUR NAME: WASHINGTON COUNTY INFORMATION - TOURISM AND HISTORIC PRESERVATION DATE: 1/78
YOUR ADDRESS: COUNTY OFFICE BUILDING FORT EDWARD, NEW YORK 12828 TELEPHONE:

ORGANIZATION (if any):

* * * \

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
beautifully molded doorway on the gable end

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Safford
Allen

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

343-83

YOUR NAME: _____ DATE: 1/78

YOUR ADDRESS: Hebron Preservation Society R.D. #2, Salem, N.Y. 12865 TELEPHONE: _____

ORGANIZATION (if any): _____

* *

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: Liebes Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: W. Carson ADDRESS: R.D. Granville
6. USE: Original: tenant house Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑ being torn down
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



JAN • 78

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: being torn down and moved to Al Greene's property on Bostown Rd.


15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
beaded sheathing, plank construction

front



SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____
ARCHITECT: _____
BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:
observation

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

344-2

YOUR NAME: _____ DATE: 1/78

YOUR ADDRESS: Hebron Preservation Society R.D. #2, Salem, N.Y. 12865 TELEPHONE: _____

ORGANIZATION (if any): _____

* *

IDENTIFICATION

1. BUILDING NAME(S): Coywel
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: Liebey Rd.
4. OWNERSHIP: a. public ☐ b private ☑
5. PRESENT OWNER: J. & W. Carson & K. Hicks ADDRESS: _____
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   other _____
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



JAN • 78

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☑ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☑
i. landscape features: _____
j. other: picket fence, carriage block

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

wonderful unspoiled setting

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPO

1866 L. Welch

21. SOURCES:

22. THEME:

1. Coywel (Home of Catharine L. Hicks)

George III, King of England, granted 2,000 acres to George Schneider, a German mercenary officer in 1764. This tract, later to become part of Hebron, was sold by Schneider to Pierre de Peyster in 1793. A year later an indenture was drawn up to secure the purchase of this farm by Caleb Greene, a family ancestor. The original indenture hangs in the living room.

Millions of years ago during the Ice Age this entire area was covered by a great ice field. When it receded, the land was liberally covered with rocks and stones. From the farm's highest point the Adirondacks can be seen to the west and the Green Mountains to the east.

The large kitchen-living room (including pantry and utility room) and attic sleeping area above comprise the original house built before 1794. In this large room the local church was organized in 1817. The rest of the house was built about 1830.

On the old loom, blankets, towels and spreads were woven of either flax or wool. The wide floor boards are of pine from trees felled on the land, and the latches on the plank doors are hand-made. Of special interest to the visitor are the Williamsburg wallpapers, the Hitchcock chairs with original stencils and seats, the cricket-on-the-hearth, the pier mirror, the copper pump and the well-sweep.

Quilts were a family occupation. O[illegible], in a logcabin pattern, has pieces of material dated 1876 in celebration of the country's centennial.

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

345-3

YOUR NAME: Hebron Preservation Society DATE: 1/78

YOUR ADDRESS: R.D. #2, Salem, N.Y. 12865 TELEPHONE:

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Sheppard Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Gary Wilson ADDRESS:
6. USE: Original: farm Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)


18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
magnificent setting and views from property
Greek Revival central portion with wings

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____
ARCHITECT: _____
BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

19-3



21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

346-3

YOUR NAME: DATE: 1/78

YOUR ADDRESS: Hebron Preservation Society TELEPHONE:
R.D. #2, Salem, N.Y. 12865

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron ~~VILLAGE~~ hamlet Slateville
3. STREET LOCATION: Slateville Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Edward Reutling ADDRESS:
6. USE: Original: Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: 19-8A



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Montgomery

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

347-3

YOUR NAME: Hebron Preservation Society DATE: 1/78
YOUR ADDRESS: R.D. #2, Salem, N.Y. 12865 TELEPHONE:
ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S): Hamlet
2. COUNTY: Wash. TOWN/CITY: Hebron ~~VILLAGE~~ Slateville
3. STREET LOCATION: Smith Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Jerold Walmans ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM (if known): a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):
    remodeled recently

12. PHOTO: 19-5A



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ ✓ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: iron fence - not original

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Garrett
Sheppard

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

348-3

YOUR NAME: Hebron Preservation Society DATE: 1/78

YOUR ADDRESS: ~~R.D. #2, Salem, N.Y. 12865~~ TELEPHONE:

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Smith Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Warner Walman ADDRESS:
6. USE: Original: home Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: 19-7A



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Griffith

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

349-3

YOUR NAME: Hebron Preservation Society DATE: 1/78

YOUR ADDRESS: R.D. #2, Salem, N.Y. 12865 TELEPHONE:

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: abandon lane
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: M. Woodard ADDRESS: R.D. Salem
6. USE: Original: farm Present: abandon
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☑
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other plank
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: foundations of barns

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: orchard

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
had end chimney. no evidence of fireplaces

Front wall double plaster


SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____
ARCHITECT: _____
BUILDER: _____


20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
~~Dixon~~ G. Chapman – 1866 Map
Hemingston

21. SOURCES:

22. THEME:



JAN • 78




Top Floor board

Sub Flooring

Sill


1



1

Southwest corner

North wall



JAN • 78

A 350-2

ARCHEOLOGICAL SITE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK
518 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD.
SERIES
NEG. NO.

REPORTED BY: Sally Bailey
YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520
ORGANIZATION (if any): H.P.S.
DATE: Jan. 78'

* *

1. SITE NAME:
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: Slateville
3. LOCATION: Off Route 31
4. PRESENT OWNER: Liebes
5. OWNER'S ADDRESS: R.D. Granville
6. DESCRIPTION, CONDITION, EVIDENCE OF SITE:

- ☐ STANDING RUINS
- ☐ CELLAR HOLE WITH WALLS
- ☑ SURFACE TRACES VISIBLE
- ☐ WALLS WITHOUT CELLAR HOLE
- ☐ UNDER CULTIVATION
- ☐ EROSION
- ☐ UNDERWATER
- ☐ NO VISIBLE EVIDENCE
- ☐ OTHER Dam, stone

7. COLLECTION OF MATERIAL FROM SITE:

- ☐ SURFACE HUNTING BY WHOM DATE
- ☐ TESTING BY WHOM DATE
- ☐ EXCAVATION BY WHOM DATE
- ☐ NONE

PRESENT REPOSITORY OF MATERIALS:

8. PREHISTORIC CULTURAL AFFILIATION OR DATE:

9. HISTORICAL DOCUMENTATION OF SITE:

1866 Atlas - Saw Mill

10. POSSIBILITY OF SITE DESTRUCTION OR DISTURBANCE:

11. REMARKS:

12. MAP LOCATION


7 ½ MINUTE SERIES QUAD. NAME: _____

15 MINUTE SERIES QUAD. NAME: _____

U.S.G.S. COORDINATES: _____

D.O.T. COORDINATES: (if known) _____

ATTACH SKETCH, TRACING OR COPY OF MAP



SOURCE OF MAP:

13. PHOTOGRAPHS (optional)

(ATTACH)

A 350-2

⇓ dam



JAN • 78

1

Stream

southside of dam

⇓



JAN • 78

1

← North side of dam


A 350-2



• JAN • 78

Northwall of dam

looking west



• JAN • 78

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

351-3

YOUR NAME: ~~WASHINGTON COUNTY INFORMATION – TOURISM AND HISTORIC PRESERVATION~~ COUNTY OFFICE BUILDING DATE: 2/78
YOUR ADDRESS: FORT EDWARD, NEW YORK 12828 TELEPHONE:

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: (New) Castle Green Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Stuart Garrett ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐ distance, in winter
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): much remodeling, late 1960's

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: brick Smoke house

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
was some type of small [redacted] mill down at the stream on the road, blacksmith shop up near house, brick Smoke house
CH. Sheldon 1866 Atlas
Geo. Sheldon -

21. SOURCES:
Greg Greene

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

352-3

YOUR NAME: WASHINGTON COUNTY INFORMATION - TOURISM AND HISTORIC PRESERVATION DATE: 2/78
YOUR ADDRESS: COUNTY OFFICE BUILDING FORT EDWARD, NEW YORK 12828 TELEPHONE:
ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: ~~Baxter~~ Bog Town Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Baxter ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: Ha m



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Original fireplace - stone, mantel
~~boxed~~ had beams covered with reeded columns
Six panel doors, Norfolk latches, window lentels that stick out (exterior)

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c1900

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

M. Mullen - 1866 Atlas

21. SOURCES:

Mary Baxter

22. THEME:

353-2

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: _____ DATE: 75'

YOUR ADDRESS: _____ TELEPHONE: 854-3358

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: WASHINGTON TOWN/CITY: W. HEBRON VILLAGE: _____
3. STREET LOCATION: RT. 31 - Suttlif RD.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ROBERT + BARBARA Gerber ADDRESS: RD#2 Salem, N.Y.
6. USE: Original: Farm House Present: Farm House
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☑
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) _____
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Land purchased in 1791 or 1792 as the "glebe" farm or parsonage for the "Associate Reformed Presbyterian Church" which stood at the corner of Sutliff Rd & County Rt 31.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Possibly 1798- when first Preacher was called to Serve Church

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: (1853 MAP McEachron)
1869 Will Chamberlin Sold James A Bockes.
1880 BOCKES TO HEIRS
1880 heirs to Will J. Dunlap
1882 Dunlap to Robt C. White
1907 R. White to John Campbell
1927 J. Campbell (1927 DIED) - Stuart Campbell
1941 Stuart Adams - Chas Gifford
1946 Gifford to F. Sutliff
1947 F. Sutliff - Maynard Jackson
Maynard - Graziano

21. SOURCES: 1965 Graziano - Brusky 1967 Brusky

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 11511
QUAD
SERIES
NEG. NO.

354-3

YOUR NAME: John P. Hurd DATE: 2-9-78

YOUR ADDRESS: R.D. #2 Salem, NY TELEPHONE: 854-3357

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Rt. 30
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: John P. Hurd ADDRESS: R.D. 2 Salem
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING: (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Adjacent field recently sold. Expect two homes to be built there.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Elevated site overlooking Hudson River valley - Glens Falls visible in the distance.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Approx 1888

ARCHITECT: ?

BUILDER: ?

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Wm Shields had house built. Daniel Hurd bought house from widow Shields 63 years ago.

21. SOURCES:
John Hurd, present owner

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

355-3

YOUR NAME: WASHINGTON COUNTY INFORMATION TOURISM AND HISTORIC PRESERVATION DATE: 11/76
YOUR ADDRESS: COUNTY OFFICE BUILDING FORT EDWARD, NEW YORK 12828 TELEPHONE:
ORGANIZATION (if any): H.P.S.

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Bob Bauer ADDRESS:
6. USE: Original: farm late tenant house Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: Siding
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Magnificent view south

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	11511
QUAD	
SERIES	
NEG. NO.	

356-3

YOUR NAME: WASHINGTON COUNTY INFORMATION ~~TOURISM AND HISTORIC PRESERVATION~~ DATE: 11/79

YOUR ADDRESS: County Office Building ~~Fort Edward, New York 12828~~ TELEPHONE: 747-9690

ORGANIZATION (if any): _____

* *

IDENTIFICATION


1. BUILDING NAME(S): _____
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE: _____
3. STREET LOCATION: So. Grimes Hill
4. OWNERSHIP: a. public ☑ b. private ☐
5. PRESENT OWNER: Town ADDRESS: _____
6. USE: Original: _____ Present: _____
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain _____


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) lattice
   e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
    c. list major alterations and dates (if known):

12. PHOTO: Page 10- #22

13. MAP:





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

One of two lattice bridges in Hebron,
the other side is next to the one pictured, used as a fence.

21. SOURCES:

22. THEME:

Historic Resources Survey

Missing Pages

Hebron-T-357-377-01-02

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115111
QUAD
SERIES
NEG. NO.

378-3

YOUR NAME: WASHINGTON COUNTY INFORMATION ~~TOURISM AND HISTORIC PRESERVATION Planning Department~~ DATE: 11/79

YOUR ADDRESS: ~~County Office Building Fort Edward, New York 12828~~ TELEPHONE: 747-9690

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Saw Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Jeff Wilde ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: Page 10-23



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

J. Smith in 1866 - (Jeremiah) He was a black man that married a Welsh lady from Granville
He raised onions for seed

21. SOURCES:

Jeff Wilde

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/15
QUAD
SERIES
NEG. NO.

379-3
~~379-2~~

YOUR NAME: WASHINGTON COUNTY INFORMATION - ~~TOURISM AND HISTORIC PRESERVATION~~ DATE: 1/79
COUNTY OFFICE BUILDING
YOUR ADDRESS: ~~FORT EDWARD, NEW YORK 12828~~ TELEPHONE: 747-9690

Irving Jones
3140

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH. TOWN/CITY: ~~Salem~~ + Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Robt. Patterson ADDRESS:
6. USE: Original: farm Present: rented house
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): remodeled

12. PHOTO: Pg. 9-30



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

225 acres

Need to locate someone who knows about this farm

Parrish Farm

21. SOURCES:

22. THEME:

Historic Resources Survey

Missing Pages

Hebron-I-380-385-01-02

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

386-3

YOUR NAME: DATE: May 82

YOUR ADDRESS: TELEPHONE:

ORGANIZATION (if any):

* *

IDENTIFICATION


1. BUILDING NAME(S): Darrow Farm
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Klaas Koster ADDRESS: R.D. Salem
6. USE: Original: farm Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM (if known): a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known)

it is still a farm

12. PHOTO:



N

Tiplady's Rd.

R 22

cem. ☐

⊗

HP-1

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

D. Darrow - 1853 Wall Map

J. Darrow - 1866 Atlas

21. SOURCES:

1866 Atlas

22. THEME:

HEBRON VALLEY GRANGE HALL

1859-1974

The Methodist Episcopal Church was organized in Belsher in 1836 and served the towns of Argyle, Hartford and Hebron. In 1859 nine members decided that West Hebron needed a church building of their own so the 3rd. Chapel of the Ashgrove Society was bought, taken down, moved and rebuilt on the lot on which it now stands. When it was completed the pews were auctioned off to the highest bidder so each family could own their own seat.

In 1874, the new frame building, now standing was built, the old building becoming a hall. For a number of years it was known as Ashley Hall, then Reids Hall.

In the late 1890's an entertainment was given in Ashley by the young people of the village and the money used to renovate the stage and make much needed general improvements to the hall. The West Hebron Band, which was active for many years furnished the music for the occasion. Many Medicine Shows and other traveling shows came and entertained for many years.

HEBRON VALLEY GRANGE NO.1103 was organized in March 1907 with 49 Charter members, of these Charter members 6 were still active members at the 25th. Anniversary celebration. At the 50th. Anniversary only Harold Getty was still an active member although some of them were still living. Now in 1974 all are gone.

On the 13th of March 1907 an open meeting was held at which the following officers were installed by Deputy Sidney Potter of Granville, with John Chamberlain acting as escort:

Master	John Getty
Overseer	W.G.McClellan
Lecturer	W.D.Beveridge
Steward	Thomas McElroy
Assistant Steward	Floyd McConnell
Chaplain	J.W.P.Campbell
Treasurer	J.T.McConnell
Secretary	Wm.E.Getty
Gate Keeper	Lewis Matteson
Ceres	Mrs.J.McConnell
Pomona	Mrs.John Getty
Flora	Mrs. W.D.Beveridge
Lady Assistant Steward	Mrs.Floyd McConnell
Organist	Mrs.Lewis Matteson
Choirister	G.F.McKnight-- who served many years.

Mrs. Lewis Matteson bought the hall from Emma J.Reid in December, 1906. The Grange purchased it from Mrs.Matteson in May, 1911 for $450. That same year a new slate roof was put on and is still in very good condition.

One of the minutes of that time which is rather amusing-tous now-was that a motion was made and adopted that "posts be bought and set of a size suitable for hitching horses".

In the first years the Grange grew rapidly and among those iniated was Alta White who was a 50 year member in February 1958. Now deceased.

Many open meetings were held and from 150 to 175 attended to hear the orchestra which was led by Etel Ina Ely and composed of the Getty family.

This was one of two orchestras the grange has had. The other was organized and directed by Lewis Matteson in 1923.

The year the Grange was organized they had an exhibit at the fair and for several succeeding years. In 1909 they took 2nd.prize which was $100.

At one time they tried out cooperative buying of both feed and groceries. This must have the forerunner of the G.L.F.-The Grange Federation League, now Agway.

The leaders have always tried to promote better farming methods,and to that end clubs have been formed among them a Corn club,poultry club and a potato club. Most of these things are now handled by the Farm Bureau.

They had a dramatic Club for a number of years and it is stated that the community was treated to some "high class" entertainment.

In 1916 the Grange sponsored Farmers Institutes and from 1918 to 1923 they held Lecture Courses which proved very popular. Liberty Bond mass meetings were held in 1917. In 1924 and for anumber of years following they held a local fair which was very successful financially.

In April of 1916 the matter was brought up concerning the removal of the Court House from Salem and Hebron Valley went on record asbeing opposed. This is a subject still being discussed and we still feel the same about it.

Itisrecorded in our Secretary's book that in June 1915 we entertained Pomona and at a cost of $34.10 approximately 700 meals were served that day. How much would it cost today?

In May of 1931 a Juvenile Grange was organized with 23 members and Mrs.Mae White as Matron.Now it is called Junior Grange.

There seems to be a decided change in the trend of Grange work in the last 40 years. Co-ops, Farm Bureau and other farm orginazions have taken over the things the Grange used to sponcer. More Grange members are not farmers today but they are interested in gardening and the restoration of old buildings and the history of the country. Community Service was the important thing for a number of years and was sponsored by Sears Roebuck. In 1943 we adopted a Finnish family.In1950 with Howard Dunham as our Chairman of Community Service we were awarded a plack and 2 $25 bonds. We sponsored the Boy Scouts for a number of years.

We painted the outside and painted and redecorated the hall, remodeled the kitchen and installed an oil furnace in the late 50's.

The hall is used by church groups for meetings,suppers,bazaars,wedding receptios etc. The Grange holds benefit card parties,suppers,barbecuesand at Christmas pack boxes for the underpriveliged. They exhibit at the Washington County fair each year. They have fine Lecturers programs and Contests

We hope that the friendly cooperation of the Patrons may make this Grange a real influence in this community for many,many years to come.

We welcome you to our hall on this Historic"Highlights of Hebron Tour".

COME AGAIN.