Folder 2 -

Building-Structure

Inventory Forms

~~#1 - 76~~

#77 - 172

77-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Mary Emma Campbell DATE: July 6, 1975

YOUR ADDRESS: R.D.2, Salem TELEPHONE:

ORGANIZATION (if any): Hebron Pres. Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Stone House Rd - County Rt. 47
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Richard Campbell ADDRESS: R.D. 2, Salem, N.Y.
6. USE: Original: Farmer Present: farmer
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain no


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P-16-5A



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☒
i. landscape features: _____
j. other: surrounding fields

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets on the edge of a woods and inlet of Barkley Pond.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: approximately 1860

ARCHITECT: _____

BUILDER: William & James Barkley

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Old saw mill was behind house on stream whose course was changed to power the wheel or turbine.

21. SOURCES: not shown on 1853 map

22. THEME:

78-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Mary Emma Campbell DATE: July 6

YOUR ADDRESS: R.D.2, Salem TELEPHONE:

ORGANIZATION (if any): Hebron Pres. Soc.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: State House Rd; County Rt. 47
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Frost Frontier ADDRESS: Salem, N.Y.
6. USE: Original: Farm House Present: House
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain no


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: Lake shore property

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets on shore of beautiful natural pond.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Middle 1800's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

79-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Mary Emma Campbell DATE: July 26, 1975

YOUR ADDRESS: R.D.2, Salem TELEPHONE:

ORGANIZATION (if any): Hebron Pres. Soc.

* *

IDENTIFICATION


1. BUILDING NAME (S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Stone House Rd.; Counties Rt. 47
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: John Gawronski. ADDRESS: R.D. 2 Salem, N.Y.
6. USE: Original: Farm House Present: Same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain No

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

roof raised and second story added in 1915

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☒ h. gardens ☐
i. landscape features: _____
j. other: ~~Sap~~ Sap house until Fall 1975 - across road near stream

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1813

ARCHITECT: _____

BUILDER: William Barkley

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

To
80-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Alvin E. Greene DATE: 2/16/76

YOUR ADDRESS: R.D. 2 Salem, N.Y. TELEPHONE: 518-854-3125

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S): John Farrier
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlain Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: John Farrier ADDRESS: RD 2 Salem, N.Y.
6. USE: Original: House Present: House
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: _____
j. other: barn fell in about 1972, boards + beams used to repair barn at Flacke Brillon House

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Grant Chamberlin, Jennie Irwin, wife
McCroskey
Fink

21. SOURCES:

81-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Alan E Greene DATE: 2/10/76

YOUR ADDRESS: RD 2 Salem, N.Y. TELEPHONE: 518-754-3123

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlain Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Paul A Rudman ADDRESS: RD #2 Salem, N.Y.
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



81-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☑ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: smoke house brick

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1811

ARCHITECT: _____

BUILDER: [redacted] Creighton ?

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

52-3

YOUR NAME: Alvin E. Greene DATE: 2/10/76

YOUR ADDRESS: RD 2 Salem, N.Y. TELEPHONE: 518-854-3125

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlain Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mrs. Irene Ferguson ADDRESS:
6. USE: Original: House Present: House
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☑ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1890

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

83-3

YOUR NAME: Alan E. Greene DATE: 9/9/76

YOUR ADDRESS: RD #2 Salem, N.Y. TELEPHONE: 518-854-3125

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlain Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Isabel S Ferguson ADDRESS: RD #2 Salem, N.Y.
6. USE: Original: Home, farm Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    Vinal siding added 1925

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑ Two sides
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: None

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) No

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

First recorded deed is april 1, 1842
John R. Hall to Richard Hague

Sara Hague

21. SOURCES:

84-4

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Alma E Greene DATE: 2/10/76

YOUR ADDRESS: RD #2 Salem, N.Y. TELEPHONE: 518-854-3125

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: McKnight Hill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Harry Tilden ADDRESS:
6. USE: Original: Home farm Present: House
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HI-7

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Farm Pond
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1922

ARCHITECT: William Macklin, Cossayuna 1922

BUILDER: Jim Cary

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

(Will. Cary on the property)

Jim + Mame Cary
Charlie Fair

21. SOURCES:

85-3

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Alma E. Greene DATE: 2/10/96

YOUR ADDRESS: RD 2 Salem, N.Y. TELEPHONE: 518-854-3423

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: —
3. STREET LOCATION: McKnight Hill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mrs. Evelyn C McKnight ADDRESS: Salem, N.Y. 12865
6. USE: Original: Farm House Present: House
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☑
   Interior accessible: Explain 12 rooms, all used


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☑
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Addison McKnight
Leland "

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

86-2

YOUR NAME: Alvin E. Greene DATE: 1/10/76

YOUR ADDRESS: RD #2 Salem N.Y. TELEPHONE: 518-854-3123

ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlain Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Cliff ROGERS ADDRESS: RD #2 Salem, N.Y.
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☑ c. garage ☑
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) no

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1840

ARCHITECT: _____

BUILDER: CHARLES ROGERS

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Albert Rogers, Bertha McEachron (wife) (niece of Dr. McEachron preached in North Church for 50 years)

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

86-2

YOUR NAME: Alvin E. Greene DATE: 1/16/76

YOUR ADDRESS: RD #2 Salem N.Y. TELEPHONE: 518-854-3123

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlain Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Cliff ROGERS ADDRESS: RD #2 Salem, N.Y.
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☑ c. garage ☑
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district) NO

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1840

ARCHITECT: _____

BUILDER: CHARLES ROGERS

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Albert Rogers, Bertha McEachron (wife) (niece of Dr. McEachron preached in North Church for 50 years)

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

87-3

YOUR NAME: Elizabeth R Wilson DATE: Jan 5 1976

YOUR ADDRESS: R.D #2, Salem N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Rte 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Henry Wilson ADDRESS: RD #2, Salem N.Y.
6. USE: Original: Residence Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



NF-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☒ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Shop was old Welsh Church moved from Quarry Rd, Salem township. Was first used after move as carriage house

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1875

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES: Earle Wilson, owner until 1972

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

58-4

YOUR NAME: Elizabeth R. Wilson DATE: Jan 6, 1976

YOUR ADDRESS: RD #2, Salem, N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Allen Lane
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Arnold Parker ADDRESS: Montreal
6. USE: Original: Residence Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☒
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

not much information available

12. PHOTO:



13. MAP:



BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 1105/11
QUAD
SERIES
NEG. NO.

89-3

YOUR NAME: Elizabeth R. Wilson DATE: Jan 10, 1976

YOUR ADDRESS: R.D. #2 Salem N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlain Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Wilfarms, Inc. ADDRESS: R.D #2, Salem, N.Y.
6. USE: Original: Residence Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Second story added 1876

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☑ c. garage ☑
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Probably about 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Original salt-box house located in back of this house now gone. This was home of original owner, Robert Wilson, who settled property in 1772. Accepted as Bicentennial Farm in 1976.

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 1155/11
QUAD
SERIES
NEG. NO.

90-3

YOUR NAME: Elizabeth R. Wilson DATE: Jan 5, 1976

YOUR ADDRESS: R.D#2, Salem, N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Rte. 22
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Sedgwick, Ps V ADDRESS: R.D#2, Salem, N.Y.
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

Present kitchen extensively remodelled about 1970

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☑ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: about 11 outbuildings

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
One of buildings at back of house was original house.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: About 1870

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

91-3

YOUR NAME: Elizabeth R. Wilson DATE: Jan 5, 1976

YOUR ADDRESS: R.D #2, Salem, N.Y. TELEPHONE: 518-854-3313

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/~~CITY~~: Hebron VILLAGE:
3. STREET LOCATION: Rte 22
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Sedgwick, Peter ADDRESS: R.D #2, Salem, N.Y.
6. USE: Original: Residence Present: Storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☑
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☑ if so, when?
    c. list major alterations and dates (if known):

This was original house on Ingersoll property. Possibly ~~Probably~~ moved here when new house was built. Has hewn beams, 4 rooms up, 4 rooms down, center chimney.

12. PHOTO:

13. MAP: Burned 75-76





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

82-1

YOUR NAME: Elizabeth R Wilson DATE: Jan 5, 1976

YOUR ADDRESS: R. D #2, Salem, N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S): Second Advent Church
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Rte. 22
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Peter Sedgwick ADDRESS: R.D #2, Salem, N.Y.
6. USE: Original: Church Present: Vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: None

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1852

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES: History of Washington Co. 1878

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

93-3

YOUR NAME: Elizabeth P. Wilson DATE: Jan 5, 1976

YOUR ADDRESS: RD #2, Salem N.Y. TELEPHONE: 518-854-3313

ORGANIZATION (if any):

* *

IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Tiplady Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Wilson Durham ADDRESS: R.D #2, Salem N.Y.
6. USE: Original: Residence Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐ No exposed corner beams
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other Walls of main part of house made of 2x4's laid solidly.
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

wing added

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☑ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Eyebrow windows - Recessed doorway

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Possibly about 1810

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

94-3

YOUR NAME: Elizabeth R. Wilson DATE: Jan 5, 1976

YOUR ADDRESS: R.D#2, Salem N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *

IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Tiplady Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Elizabeth R. Wilson ADDRESS: R.D#2, Salem, N.Y.
6. USE: Original: Residence Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Extra room and porch added 1967. Indications that stairway to second floor had been changed from front entrance. Some walls were solid unfinished panelling, covered with lath & plaster.

12. PHOTO: P8-34 13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐ (was original carriage house)
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: Shed is salt-box

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Probably 1790-1800

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 1151/11
QUAD
SERIES
NEG. NO.

95-3

YOUR NAME: Elizabeth R. Wilson DATE: Jan 5 1976

YOUR ADDRESS: R.D#2, Salem, N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/~~CITY~~: Hebron VILLAGE:
3. STREET LOCATION: Tiplady Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: John Meagher ADDRESS: R.D#2, Salem N.Y.
6. USE: Original: Residence Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when? c. list major alterations and dates (if known):

Wing added. Extensive renovating, but no fundamental change

12. PHOTO: P.C-35

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: Several out buildings

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: About 1820 ?

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

96-2

YOUR NAME: Elizabeth R Wilsa DATE: Jan 5, 1976

YOUR ADDRESS: R.D #2, Salem, N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Tiplady Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Wilsa, Durham ADDRESS: RD #2, Salem N.Y.
6. USE: Original: School Present: storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☑ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

97-3

YOUR NAME: Elizabeth R. Wilson DATE: Jan 5, 1976

YOUR ADDRESS: R.D. #2, Salem, N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/~~CITY~~: Hebron VILLAGE:
3. STREET LOCATION: Rte 22
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Earle Erwin Wilson ADDRESS: R.D. #2, Salem N.Y.
6. USE: Original: Residence Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlockin joints ☐
   b. wood frame with light memoers ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☑ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Walls are brick-filled. Recessed doorway

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: About 1840?

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

98 b.-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bullen DATE: Nov. 76

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: S. Grimes Hill
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: David Kriger ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    roof raised 1900 before 1920

12. PHOTO: P12-15

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Peter Hannibal
Margaret " Wood (Hus. Chester)

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

98-2

YOUR NAME: Elizabeth R Wilson DATE: Jan 5, 1976

YOUR ADDRESS: R.D# 2, Salem, N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *


IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Rt 22
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Viola Fulwood ADDRESS: R.D# 2, Salem, N.Y.
6. USE: Original: Blacksmith Shop - Present: Empty
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☒ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Probably before 1840

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

99-3

YOUR NAME: Sally Ballou DATE: Mar. 76'

YOUR ADDRESS: R.D. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: S. Grimes Hill
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Judge Droban ADDRESS: R.D. Salem (Summer)
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    Chas. Smith built wing in 1900 & porches which have since been removed

12. PHOTO:

13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets on a hill and over looks valley & open fields.
337 acres one time

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Eyebrow windows (used to have side lights at the front door and smaller eyebrow windows)

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Eli. Hatch
Horace Ayers
Maud Rogers (93 in 1976) (sold about 1957)
Myers

21. SOURCES:

Everett Gould
Maud Rogers

22. THEME:

Agric.

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

100 - 3

YOUR NAME: Sally Bailey DATE: Mar. 76'

YOUR ADDRESS: R.D. 2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): ~~Hebron~~ Preservation Society
R. D. #2, Salem, N. Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME (S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: John Anderson ADDRESS:
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P12-15A



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1. Jos. Smith
2. N. Bidell
3. Garrick
4. Horace Ayers

21. SOURCES:

Arthur Smith
Maud Rogers

22. THEME:

Agric.

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

ID1 -3

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: P.O.Z, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: N. Grimes Hill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Everett Gould ADDRESS: West Pawlet or Granville
6. USE: Original: farm Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): Porch addition in 1865, 50ft. long

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: saphouse - 1963
j. other: smoke house - brick - 2 large slabs of slate for roof

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Farm sets on a hill side, many trees in front,

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
molding around doors, front door with side lights and windows

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____
ARCHITECT: _____
BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
1880 Seeds were raised on this farm for Rice Seed in Cambridge
Sam. Ayers b. 1807 m. Elmira Hatch may have come down thru her family
Harlen Rasey b. 1850, m. Elimina Ayers
Marshall Gould m. Elmina Rasey
Extensive maple sugaring process at present.

21. SOURCES:
Mr. & Mrs E. Gould

22. THEME:
Farming

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

102-3

YOUR NAME: Sally Bullen DATE: Mar. 76'

YOUR ADDRESS: R.D. 2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society ~~R.D. #2, Salem, N.Y. 12865~~

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: N. Grimes Hill Road
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Arthur Smith ADDRESS: RD. Granville
6. USE: Original: farm Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn [5] ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: ~~Large~~ largest barn 1893 - built by Chas. Smith
j. other: brick Smoke house, (Sap house 1930)



16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets in the valley, beautiful farm and out buildings

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Fine collection of farm building in excellant condition.
Excellant interior moldings hand planed by Chas. Smith, panels under windows, chimney cupboards upstairs.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1876

ARCHITECT: _____

BUILDER: Chas. Smith took from June 15 - Nov. 2, 76'

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

1876 built for Michael McFadden
1919 - Mar. 5 - Mr. & Mrs. Arthur Smith (Elsa McFadden)

There was an earlier farm house on the same location as present house.

21. SOURCES:

Arthur Smith

22. THEME:

Farming

Arthur Smith's House

Built by Chas. Smith - Arthur's ~~grand~~ father
paid 1.50 a day

Diggers of stone paid $1.00 a day as were cellar diggers

1 pair window sash - .50¢

Lumber - 300ft 2x4 hemlock From Finch Pyrn
9¢ ft. for good
7¢ bad

Bricks - from Pepper's in Middle Granville
2000 soft $7.00 a 1000
1000 hand $9.00

Porch posts & brackets built at the house, 30-40 bevels in each

Michael McFadden was determined to have a better house than James Braymer on Route 22, 1st house south on the right.

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

103-2

YOUR NAME: Sally Baillon DATE: Mar. 76'

YOUR ADDRESS: R.D. 2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): ~~Hebron Preservation Society~~
R. D. #2, Salem, N. Y. 12865

* * * \

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: located on the "School Lot"
j. other: wood shed

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Located on Great Northern Turnpike
Exterior not altered.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c1847

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Jessie Garrety taught there
Arthur Smith has school records for this district all in one book from 1813-1957.
Probably second or third building on this site.
At one time 76 children in this district!

21. SOURCES:
Arthur Smith + Jessie Garrety

22. THEME:
Education

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

104-2

YOUR NAME: Sally Bailey DATE: Mar. 76

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

IDENTIFICATION

1. BUILDING NAME(S): Clapps Tavern
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Robt-Ed Chanda ADDRESS: 413-6th St., Brooklyn
6. USE: Original: Tavern on Turnpike Present: Summer residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): orig. tavern was back L, was removed. Present building built on front of L.

12. PHOTO: P12-10

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
Located on Great Northern Turnpike

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Upstairs was once a ball room - chair rail goes thru new partitions

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Clapps Tavern (wid. Clapp)
H. Braymer
Chas. Van Blankom

Busy location in the times of the Turnpike

21. SOURCES:
Arthur Smith, Jessie Garrety

22. THEME:
Transportation - Commercial

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

105-3

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Philip Stachow ADDRESS:
6. USE: Original: blacksmith shop Present: garage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO: P.12-13



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: house
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Sets close to road

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Completely remodeled.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Was a blacksmith shop next to L.L. Brown's store, located on Great Northern Turnpike.

21. SOURCES:

Arthur Smith

22. THEME:

106-2

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Nov. 30, 75'

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S): was L.L. Brown's Store & Porter P.O.
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Route 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Philip Stockow ADDRESS:
6. USE: Original: Residence + Brown's store Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: hilly
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located on the old Great Northern Turnpike

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

One of three Greek Revival Temple Form buildings, Arthur Smith says porch was always there.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

One wing was L.L. Brown's Store c1900
Porter P.O.

Red building so. was blacksmith shop

21. SOURCES:

Arthur Smith b. 1893

22. THEME:

Transportation - Commercial

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

107-3

YOUR NAME: Sally Bullen DATE: Mar. 76'

YOUR ADDRESS: RD 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society Hebron Preservation Society RD #2, Salem, N.Y. 12865

* * * \

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located on the edge of E. Hebron, on the Great Northern Turnpike

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Eye brow windows

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c 1830-40's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Pearl Hatch
Otto Hadaway (store owner)
Townsend
Moore

21. SOURCES:

Grace Ensign

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

108-2

YOUR NAME: Sally Bullen DATE: Mar 76'

YOUR ADDRESS: RD. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865


* *


IDENTIFICATION

1. BUILDING NAME(S): Cheese Factory - Grange Hall [Hamlet-]
2. COUNTY: Washington TOWN/CITY: Hebron ~~VILLAGE~~: E. Hebron
3. STREET LOCATION: Route 22
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Joe Verticheo ADDRESS: 26 Stanford St, Glens Falls
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain) UNUSUAL
   e. other 3rd floor holds 2nd floor by suspension, metal rods
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): roof was raised when purchased by O.B. Hadaway.
12. PHOTO:
13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located in Hebron's earliest settlement on the Great Northern Turnpike

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Construction, note: front sheet

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

last of Hebron's five cheese factories.

Cheese fac. stopped in 1920's, became apt. house
King Beebe ran cheese fac.
Hadaway bought about 1916

21. SOURCES:

Grace Ensign - Arthur Smith

22. THEME:

local Industry

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

109 - 1

YOUR NAME: Sally Billen DATE: 854-3520

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): ~~Hebron Preservation Society~~
R.D. #2, Salem, N.Y. 12865


IDENTIFICATION

1. BUILDING NAME(S): East Hebron Store
2. COUNTY: Washington TOWN/CITY: Hebron ~~VILLAGE~~ Hamlet: E. Hebron
3. STREET LOCATION: Route 22
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Fred Baker ADDRESS: R.D. 2 Salem
6. USE: Original: general store, Grange hall Present: storage in store area, home attached
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: home attached to south end, very early

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
located in the earliest settlement in Hebron on the Great Northern Turnpike from Lansingburg to Granville.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Community hall on the 2nd floor, many years was the Grange
was a bell on the north peak.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c 1790-1800

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Upstairs was Grange Hall and dance floor, chickens also kept upstairs, in bac
Dr. Long (David)
Geo. Allen
Frank Boynton
O.B. Hadaway
Store was the social center for the community of E. Hebron.
Jenkins Rowe - Shipeck - Rae
Aldrich
Closed
blacksmith next to store, north

21. SOURCES:
Grace Ensign

22. THEME:
Commercial
Social

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

110-3

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron ~~VILLAGE~~ Hamlet: E. Hebron
3. STREET LOCATION: Route 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Fred Baker ADDRESS: R.D. Salem
6. USE: Original: Storage for general store Present: garage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located in Hebron's earliest settlement, on the Great Northern Turnpike

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Storage shed for store,
Hadaway had a garage there

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

111 - 3

YOUR NAME: Sally Britton DATE: Mar. 76

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): ~~Hebron Preservation Society~~ Hebron Preservation Society R. D. #2, Salem, N. Y. 12865

~~R. D. #2, Salem, N. Y. 12865~~

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron ~~VILLAGE:~~ Hamlet E. Hebron
3. STREET LOCATION: R. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Steve Sheldon ADDRESS: R.D. Salem
6. USE: Original: home of cheese maker Present: tenant house
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in Hebron's earliest settlement,

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

maybe Nelson's built
K. Beebe

21. SOURCES:

Grace Ensign

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

112-3

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron ~~VILLAGE~~ Hamlet: E. Hebron
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Bessie Murtha ADDRESS: R.D. Salem
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    1901 remodeled

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in Hebron's earliest Settlement, on the Great Northern Turnpike

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Cape Style

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Elmer Cary

1901 bought by Martha - in a shambles - done over then

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

113-2

YOUR NAME: Sally Bullen DATE: Mar. 76

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S): District School No. 12 (16)
2. COUNTY: Washington TOWN/CITY: Hebron ~~VILLAGE~~ Hamlet: E. Hebron
3. STREET LOCATION: Route 22
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: ADDRESS:
6. USE: Original: school house Present: storage
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in Hebron's earliest settlement, on the Great Northern Turnpike.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Original condition since being closed in the 30's.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Fine existing example of a one room rural school

Mary Ameden taught there

Unchanged from the 50's

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

114-3

YOUR NAME: Sally Bullen DATE: Mar. 76

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3570

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem N.Y.

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron ~~VILLAGE~~ Hamlet: E. Hebron
3. STREET LOCATION: Rt. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Edmund Wood ADDRESS: R.D. Salem
6. USE: Original: home Present: —
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☑ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in Hebron's earliest settlement, on the Great Northern Turnpike

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Decorative cap on windows - pediment, decorative in gable, block molding at front entrance (perhaps added), end chimney

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Frank Darrow, Jay Darrow

21. SOURCES:

Grace Ensign

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

115-3

YOUR NAME: Sally Brillon DATE: Mar. 76'

YOUR ADDRESS: R.D.2 TELEPHONE: 8543520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron ~~VILLAGE~~ Hamlet: E. Hebron
3. STREET LOCATION: Route 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Lessie Shaw ADDRESS: R.D. Salem
6. USE: Original: home Present: home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



NR-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☑
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in the earliest settlement in Hebron

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

with Lincoln

1927 - Robt Shaw, ran a garage, he built it, gas pumps were there

21. SOURCES:
Mrs. Everett Gould

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

116-2

YOUR NAME: Sally Bailey DATE: Mar. 76

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron ~~VILLAGE:~~ Hamlet E. Hebron
3. STREET LOCATION: R. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Will. Wood ADDRESS: R.D. Salem
6. USE: Original: farmhouse Presbyterian Manse Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located in Hebron's earliest settlement

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: (church was built 1846) orig. church 1790 further north

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

was the Presbyterian Manse

21. SOURCES:

Grace Ensign

22. THEME:

Religious

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

117-3

YOUR NAME: Sally Braillon DATE: Mar 76'

YOUR ADDRESS: R.D 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlin's Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Lenny Chu ADDRESS: 100 Beekman St., N.Y.C apt. 27c
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: asbestos shingles on porch
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Just west of E. Hebron & Turnpike

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Dr. Thom. Glines – home and office

21. SOURCES:

Arthur Smith

22. THEME:

Medicine

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

118-3

YOUR NAME: Gert Getty DATE: Mar. 76'

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-7610

ORGANIZATION (if any): Hebron Pres. Soc.

* *

IDENTIFICATION


1. BUILDING NAME(S): Residence
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlin Mills Rd.
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Rev. & Mrs. Craig ADDRESS: Salem, New York
6. USE: Original: Mill owners home Present: Real estate office + home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☒ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? c. list major alterations and dates (if known):

1965 ROOM ON REAR NO REALESTATE OFFICE
PORCH REMOVED IN 1951

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☒ h. gardens ☐
i. landscape features: Black Creek flows near and
j. other: was the site of several mills

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☒
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: Stone bridge foundation + perhaps evidence of crossing of Old Sparta Road.

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Remains of old mills + bridges
Large addition built about 1867. Decorative wooden trim.
It was known as Bassett's Mills after 1823
There was crushed stone to make limestone for
grasses on the property. Other mills: grist, saw, cider + fulling mill

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
E. L. Spear was a State Legislator for 1 year

Blacksmith shop out next to mill also carriage factory.


Tall addition they say about 1865, molding seems earlier
significant plaster cornice, medallion on ceiling, also medallions on door + window casings, very unusual, marblized slate


1823 - Jabez + Polly Rogers built Cape in Eight to Clark Rogers
water privileges lot 15, Campbell Patent 50 ac.
saw mill + fulling mill + rights to build a dam
to James Bassett
Oct. 28, 1861 E. L. Spear 50 ac.
He was son-in-law of
1880 - James Jenkins
1920 - John Jenkins
1974 - Arch + Polly Craig, Granddaughter of Jabez Jenkins,

21. SOURCES:
Deeds + the Craigs

22. THEME:
Early Industries

115/11/118





Arch Craig - west addition 1860's
Chamberlain Mills Rd.

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

119-2

YOUR NAME: Sally Bullen DATE: Mar. 76

YOUR ADDRESS: R.D.2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S): District School No. 14
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Route 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ADDRESS:
6. USE: Original: school house Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: recently been purchased

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☑ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: stonewalls, maples, fields
j. other: woodshed

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: hiway

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

on Great Northern Turnpike

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

An existing example of a one room school.
Grace Ensign taught there.

21. SOURCES:

Grace Ensign

22. THEME:

Education

120-2

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Feb. 776

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S): Day Barn
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Route 30
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Joyce Day ADDRESS: R.D. Hartford
6. USE: Original: barn Present: barn
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☑
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved if so, when?
    c. list major alterations and dat (n/a):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: fields

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Building sets on hill across from site of Belcher Inn also built by Jesse Day

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

♡ cut out in gable end, large over-hang above location of original door, no over-hang on gable end.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c 1790

ARCHITECT: _____

BUILDER: Jesse Day

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

fine example of the earliest style of barn in our area.

21. SOURCES:

Joyce Day

22. THEME:

Farming

owner

121-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Brillon DATE: Feb. 76'

YOUR ADDRESS: P.O. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Pres. Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S): Beaty House
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Dunnigan Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Fred Cary ADDRESS:
6. USE: Original: farmhouse Present: abandon
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

3 eyebrow windows

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: c.1834

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

(Granddaught of Robt. Creighton) 1st Settler of W. Hebron
Mary, daughter of Will. White married a Thom. Beattie and that was their farm. She was born 1814 died (1842 or 6), therefore house must be from about c1834.

21. SOURCES: Myrtle Barkley

22. THEME:

122-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bullin DATE: Feb. 76'

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Soc.

* *

IDENTIFICATION

1. BUILDING NAME(S): Sap House
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: off ~~Bromley Rd~~ Blossom Rd.
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Casper Bromley ADDRESS: R.D. Salem
6. USE: Original: saphouse Present: saphouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☑
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: sets nicely in a hollow

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1900's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Regional building having to do with the process of maple sap to syrup.

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

123-3

YOUR NAME: Elizabeth R Wilson DATE: Jan 5, 1976

YOUR ADDRESS: R.D # 2, Salem, N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *

IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Rte 22 — corner Typlady Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mrs. Bruno Gingras ADDRESS: R.D # 2, Salem, N.Y.
6. USE: Original: ? Present: Store
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Large wing added about 1950?

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Store in late 1800's - early 1900 owned and run by Tiplady family - John Tiplady and two daughters.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Probably before 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

124-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Elizabeth R. Wilson DATE: Jan 5, 1976

YOUR ADDRESS: R.D # 2, Salem N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Rte 22 - corner Tiplady Rd.
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Viola Fulwood ADDRESS: R.D # 2, Salem, N.Y.
6. USE: Original: Residence Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. sh[illegible] g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Large wing added - Eyebrow windows

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known [X] b. zoning [ ] c. roads [ ]
d. developers [ ] e. deterioration [ ]
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn [X] b. carriage house [ ] c. garage [X]
d. privy [ ] e. shed [ ] f. greenhouse [ ]
g. shop [ ] h. gardens [ ]
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land [X] b. woodland [ ]
c. scattered buildings [ ]
d. densely built-up [ ] e. commercial [ ]
f. industrial [ ] g. residential [ ]
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Old blacksmith shop listed separately on this property.
brick across road.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1820 ?

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Site of David ~~Hamilton~~ Hopkins's farm - one of the first three settlers in Hebron.

21. SOURCES:

22. THEME:

125-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Elizabeth R Wilson DATE: Jan 5, 1976

YOUR ADDRESS: R.D #2, Salem, N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/~~CITY~~: Hebron VILLAGE:
3. STREET LOCATION: Rte 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Henry Wilson ADDRESS: R.D #2, Salem, N.Y.
6. USE: Original: Residence Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY: none
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Abt 1850-60 ?

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

126-3

YOUR NAME: Elizabeth R. Wilson DATE: Jan 5, 1976

YOUR ADDRESS: R.D.# 2, Salem, N.Y. TELEPHONE: 518-854-3363

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: R.D.# 2, Rte 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Mrs. Mary Patterson ADDRESS: R.D.# 2, Salem, N.Y.
6. USE: Original: Residence Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

located on Great Northern Turnpike

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

7 Reported that one building at back was previously the Methodist Church at Porter (between Hebron and Granville)
(Moved there by owner. J. Parrish - One Meth. Ch. from Porter moved to one end of carriage fac. in Salem on R. 30

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Parrish
Poor

21. SOURCES:

Arthur Smith

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

127-3

YOUR NAME: Sally Baillon DATE: Mar. 76

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* * * \

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Old part in the back –

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Walt Glasier

21. SOURCES:

Maud Rogers

22. THEME:

Agric.

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

128-3

YOUR NAME: Sally Billin DATE: Mar. 76'

YOUR ADDRESS: R.D.2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2 Salem N.Y. 12865

* * * \

14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

J. Murphy (1853 Map)
Oscar Smith

21. SOURCES:

Maud Rogers

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

129-3

YOUR NAME: Sally Billm DATE: Mar. 76

YOUR ADDRESS: R.D.2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2 S.I. 12211 865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron ~~VILLAGE~~: PORTER
3. STREET LOCATION: R. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Hayman Sam Drago ADDRESS:
6. USE: Original: farm - tavern Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Sap house
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located on Gr. Nor. Turnpike
Stone ~~basalt~~ dug into ~~bank~~ bank - Judge Porters

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: Geo. Holmes

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Site of Will. Porter Manison, 1882 burned, Gr. Revival
tall columns
winding staircase
built by N.Y.C. carpenters

Judge Porter was from city
(owned: from Tollgate farm to the store)
Sam. Smith forman for Porter (A Smith Grandf.)
Layman Lawrence

21. SOURCES:
Present house:
Geo Holmes
Austin Nelson
Dennison
Arthur Smith

22. THEME:
Present house was a tavern.

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

129-3

YOUR NAME: Sally Billow DATE: Mar. 76

YOUR ADDRESS: R.D.2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2 S.I. N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron ~~VILLAGE~~: PORTER
3. STREET LOCATION: R. 22
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Clayman Sam Drago ADDRESS:
6. USE: Original: farm - tavern Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: sap house
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Located on Gr. Nor. Turnpike
Stone basalt dug into bank - Judge Porters

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: Geo. Holmes

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Site of Will. Porter Manison, 1882 burned, Gr. Revival tall columns
Judge Porter was from city winding staircase
(owned: built by N.Y.C.
from Tollgate farm to the store) carpenters
Sam. Smith forman for Porter (A Smith Grandf.)
Layman Lawrence

21. SOURCES: Present house:
Arthur Smith Geo Holmes
Austin Nelson
Dennison

22. THEME: Present house was a tavern.

130-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ballou DATE: Mar. 76'
YOUR ADDRESS: R.D.2 Salem TELEPHONE: 854-3520
ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Cham berlins Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Robt. Brown ADDRESS: R.D. Salem
6. USE: Original: farm Present: part-time residence; farm, horse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn [5] b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: hills
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
On the edge of W. Hebron Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____


BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Early dwelling across from house called by some the SLAVE HOUSE, no record of slaves in Hebron in 1790 census, however.

The Crosier's lived there 98 yrs. Hiram (father) Paul (son)

21. SOURCES:

22. THEME:



Early house, called "slave house" by tradition



Smoke House

131-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bolla DATE: Mar. 76

YOUR ADDRESS: Box 2 TELEPHONE: 854-3570

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlins Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Will Jameson ADDRESS: R.D. Salem
6. USE: Original: farm Present: farm
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ with b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☑ over it g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: wooden silos - 6 bay open shed

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: rock outcropping - beautiful land in valley

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Robt. Hague (Georgie Lundy's father)

James Lundy

21. SOURCES:

22. THEME:

132-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Buller DATE: Mar. 76

YOUR ADDRESS: P.O. 2 TELEPHONE: 854-3520

ORGANIZATION (if any): ~~R. D. #2, Salem, N.Y. 12865~~ Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Heaphy Rd. - Henderson Rd.
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Will. VanDyke ADDRESS: P.O. 2 Salem (summer)
6. USE: Original: farm Present: summer residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Close to log cabin built by S. Guthrie

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Guthrie (1853 map)
Will. Henry Jameson
Mrs. Henderson

21. SOURCES:

22. THEME:

133-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bullen DATE: Mar. 76
YOUR ADDRESS: R.D.2 Salem TELEPHONE: 854-3520
ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlins Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Norman Crouse ADDRESS: R.D. Salem
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



NC Gibsonville

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Iron or wood grates over eyebrow windows 
Grape design on molding of recessed doorway

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
(Black Creek Cheese Factory (Ed Sloane ran it)
Peltcher - he made cheese, daughter taught school, Dist. #11
Beatrice married Rosco Wilson
Ed Sloane

21. SOURCES:

22. THEME:

134-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ball DATE: Mar. 76'

YOUR ADDRESS: R.D.2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any) Hebron Preservation Society ~~R.D. #2, Salem, N.Y. 12865~~

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlin's Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Will. Van Dyke ADDRESS: R.D. Salem (summer)
6. USE: Original: farm Present: rental
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☑ b. wood frame with light members ☐ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Foundation of very early dwelling (tenant house) on corner east of house, had cooking fireplace, red mantle, pantry & cupboard above oven (in pant... Probably orig. house - fell in several years ago

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Geo. McKnight, Jennie
J.W.-P. Campbell

21. SOURCES:

Evelyn McKnight
Florence Getty

22. THEME:

135-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bullen DATE: Mar. 76'

YOUR ADDRESS: R.D.2 TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlin's Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Al Baltz ADDRESS: R.D. Salem
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known): 1960's

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn [5] b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: early dwelling

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Eyebrow windows

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
Early house set across from it, McGill's daughter Ada, married James Cary, lived there.

McGill
John W. Beattie, daughter Mabel
John Mahaffy -
Wood

21. SOURCES:
Florence Getty

22. THEME:

136-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 11511
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bullen DATE: Mar. 76

YOUR ADDRESS: R.D.2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N Y 1 2865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlins Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Ivan Campbell ADDRESS: R.D. Salem
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

A. Foster (1853 Map)

Sam Campbell

21. SOURCES:

22. THEME:

137-4

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ball DATE: Mar. 76

YOUR ADDRESS: R.D.2 Salem TELEPHONE: 8543520

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlins Mill Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Francis Crosier ADDRESS: R.D. Salem
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: Sawmill

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

On edge of Chamberlins Mill Historic District

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Sylvester Spoor – member N.Y.S. Assembly in 1865

Jenkins
Shaw
Raymond Crosier

21. SOURCES:

Polly Craig

22. THEME:

138-3

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Ballou DATE: Feb. 76'

YOUR ADDRESS: R.D. 2, Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Dunnigan Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Fred Cary ADDRESS: R.D. Salem
6. USE: Original: farmhouse Present: farmhouse
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Ferguson
Elmer Cary

21. SOURCES:

Isabell Ferguson

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/118
QUAD
SERIES
NEG. NO.

139-3

YOUR NAME: Hebron Preservation Society DATE: 75'
YOUR ADDRESS: R.D. #2, Salem, N.Y. 12865 TELEPHONE:
ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S): Turkey Roost Farm
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: 8 Pine Hill Road
4. OWNERSHIP: a. public ☐ b. private ☑ 854 W. 181st St., New York, N.Y. 10033
5. PRESENT OWNER: Jacobs, Augustus ADDRESS: R.D. 2, Salem, N.Y. 12865
6. USE: Original: Farmhouse Present: Same
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain Private residence


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): Removal of 3 hanging chimneys & addition of chimney & fireplace; removal of interior partitions to convert parlor, bedroom & closet into living room. (c. 1960)

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ 2 b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☑
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: Cultivated fields

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Most of the buildings on Pine Hill Road are old farmhouses of the Greek Revival Period or earlier.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Original wooden grilles in frieze windows.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Before 1852

ARCHITECT: Unknown

BUILDER: "

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Well-proportioned example of Yorkstate Greek Revival farmhouse.

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

140-3

YOUR NAME: Gerald and Maria DaCosta DATE: 12.22, 1975

YOUR ADDRESS: Pine Hill Road TELEPHONE: unlisted

Hebron Preservation Society
P.O. Box #2, Salem, NY 12865
ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S): The Three Plows
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: Hebron
3. STREET LOCATION: Pine Hill Road
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: DaCosta, G0& M.D. ADDRESS: Pine Hill Road
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain No, except to History Taker


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒ These are now seen only in the basement and in the attic.
   b. wood frame with light members ☐
   c. masonry load bearing walls ☒
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): 1st. between 1946-1952
    2nd. " 1956-1964

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐ between Grimes Mill & Pine Hill
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☒ c. garage ☒
d. privy ☒ e. shed ☒ f. greenhouse ☐ Pig sty, chicken coup
g. shop ☒ h. gardens ☒ (flowers in rock garden and veg. not
i. landscape features: Lawn, rail fence, flr. border (in use.)
j. other: foundation plantings.

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district) Do not know. Tried to ascerta date of house but were unable. searched in Montpelir, Ruppert, twice in Washington Co. Ft. Ed. our earliest deed dated 1835 — house was built before that but cannot verify this in our search —

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

The house interior has been changed considerably on the first floor. Liv. room is made up of former kitchen, pantry, bedroom. Ceilings lowered, beams put in to support walls upstairs. Floors are wide and have been varnished. All floors had to be taken up, except liv. rm. which has been laid over by former owner with pine to be covered with carpet. Beacuse of sunken floors on account of decayed beams

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

and sills the entire second floor floors have been removed, saved those floor boards were sound and relayed with a second floor under the top floor. Hanging chimneys taken out, side walls doubled inside with rock wool in between. Pine floors were old boards acquired, except in the dinig room where the boards were in excellent condition, since this room was a former front room, and as such seldom used, however because the floor leaped 6" in one corner 4" in another — 3" in another & 1" in the last. The floor had to be taken up & relaid to level floor & push up beams — Raised back roof to put in Bath Room, enlarged one room & put in closet — bath room has 4" of poured concrete under ceramic tile & floor & side walls — Towel closet in bath room — all together there are 14½ closets — 2 walk in — attic floored and insulated with 4" of Mica pellets —

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

141-3

YOUR NAME: John M. Wetherby DATE: 1975
YOUR ADDRESS: Pine Hill Rd - RD1 Granville N.Y. 12832 TELEPHONE: 642-1678
Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865
ORGANIZATION (if any): Hebron Preservation Society

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: South side of Pine Hill Road
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Howard John M. Wetherby ADDRESS: Pine Hill Rd.
6. USE: Original: ~~Hse~~ Farm House Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☒ (wings) c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: Shingled on roof originally, some slate
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other Stone roots mainly of flat up slabs of stone - Ends supported by stone walls also
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    1951 we had the addition to original house removed. The date on the new section was made or finished on May 16, 1796. Our builder Gordon Borden told us the ell on original house was at least
12. PHOTO: 20 yrs older - perhaps around 1776 13. MAP: ~~Sketch~~ as shown on tax map (1780)





14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: C 1776-1780

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

142-3

YOUR NAME: James Chapman DATE: 1975

Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

YOUR ADDRESS: Pine Hill Road RD1 Granville N.Y. 12832 TELEPHONE:

ORGANIZATION (if any): Hebron Preservation Society

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Wash. TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Pine Hill
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Chapman ADDRESS:
6. USE: Original: Farm House Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):


12. PHOTO:



13. MAP:

North

House faces South on North side of Pine Hill Rd



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

143-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2 Salem N. Y. 12865


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: FARNLEY RD 1
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Cochran, Leroy ADDRESS: R#1 GRANVILLE
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
PICTURED IN WASH CO. HISTORY OF 1878

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: SIGN ON BARN SAID 1803,

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

144-3

YOUR NAME: Wilson Pozzuoli DATE: 2-23-76

YOUR ADDRESS: RFD #1 GRANVILLE N.Y. TELEPHONE: 642-2579

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME (S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE: N. Hebron
3. STREET LOCATION: Middle Rd
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Wilson Pozzuoli ADDRESS:
6. USE: Original: dwelling Present: dwelling
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☑
d. privy ☑ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Circa 1880

ARCHITECT: Unknown

BUILDER: Unknown

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Typical house and barns of the late 19 century.

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

145-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society

* * * * * * * * * * * * * * * * * * R.D. #2, Salem, N.Y. 12865 * * * * * * * * *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: Co RT # 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Bitterly, Fred ADDRESS: R#1 GRANVILLE
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Appx 1870

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

146-2

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D. #1 Granville TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: N. HEBRON
3. STREET LOCATION: CO RT # 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Burch, Vila ADDRESS: R# 1 GRANVILLE
6. USE: Original: CHURCH Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☑ if so,when? APPX 1870
    c. list major alterations and dates (if known): SAID TO HAVE BEEN A CHURCH ON TAYLOR HILL.

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: LATE 1830's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

YOUR NAME: JOHN M. ZUBELL DATE: 3/3/76

141-3

YOUR ADDRESS: RD-1 GRANVILLE TELEPHONE: 642-2209

ORGANIZATION (if any):

* *

IDENTIFICATION


1. BUILDING NAME(S): RESIDENCE
2. COUNTY: WASH TOWN/CITY: VILLAGE: NORTH HEBRON
3. STREET LOCATION: RT. 31
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Zubell, John & Mau[illegible] ADDRESS: RFD-1 GRANVILLE N.Y.
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

Received S.H.P. Mar 05 1976

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: Maple trees - Chestnut Tree
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Not known. Oldest date on deed after 1869 a number of previous owners prior to 1869

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

148-2

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D. # Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society

* * * * * * * * * * * * * * * * * * R.D. #2, Salem, N.Y. 12865 * * * * * * * * *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: N-HEBRON
3. STREET LOCATION: CO RT # 31
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ED-BARNES ADDRESS: RT 1 GRANVILLE
6. USE: Original: INN Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☑ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Was used as a tavern and a stage coach stop at early time. Wm. Fosmire buys the Inn in 1840's.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: VERY EARLY 1800'S OR LATE 1700'S

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

Hebron Preservation Society
R. D. #2, Salem, N.Y. 12865

149-2

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#1 Granville TELEPHONE: 642-1749

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: N. HEBRON
3. STREET LOCATION: LIEBIG RD
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Kraft, Minnie ADDRESS: R# 1 GRANVILLE
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: BEFORE 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

150-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any):

* * * * * * * * * * * * * * * * Hebron Preservation Society * * * * * * * * * *
R. D. #2, Salem, N. Y. 12865


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: N. HEBRON
3. STREET LOCATION: LIEBIG RD.
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Bardin, Elsie ADDRESS: RH1 GRANVILLE
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: NONE

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: ABOUT 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

151-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D. #1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society

* * * * * * * * * * * * * * * * * * R.D. #2, Salem, N.Y. 12865 * * * * * * * *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: LITTLE BURCH HILL RD 1
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Young Don ADDRESS: R#1 GRANVILLE, N.Y.
6. USE: Original: HOME Present: SAME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: ABOUT 1875

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 11/5/11
QUAD
SERIES
NEG. NO.

152-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any):

* * * * * * * * * * * * * * * * Hebron Preservation Society * * * * * * * * * * * *
R. D. #2, Salem, N. Y. 12865

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: BARDIN RD.
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Bardin, Robt ADDRESS: RH1 GRANVILLE
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: BEFORE 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

153-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#4 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society

* * * * * * * * * * * * * * * * * * R. D. #2, Salem, N. Y. 12865 * * * * * * * *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: LIEBIG RD
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Liebeg, George ADDRESS:
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain No


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐ b. wood frame with light members ☑ c. masonry load bearing walls ☐ d. metal (explain) e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when? c. list major alterations and dates (if known):

12. PHOTO:

13. MAP:





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: BEFORE 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

154-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D. #1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N.Y. 12865

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: LIEBIG RD
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Liebeg, Lucille ADDRESS: R#1 GRANVILLE
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☑ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1848

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

155-3

YOUR NAME: Harold Craig DATE: March 1976
YOUR ADDRESS: R.D.#1 Granville N.Y. 12832 TELEPHONE: 642-1749
ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *

IDENTIFICATION

1. BUILDING NAME(S): Baptist Church Parsonage
2. COUNTY: Washington TOWN/CITY: VILLAGE: Hebron
3. STREET LOCATION: R.D. #1
4. OWNERSHIP: a. public ☒ b. private ☐
5. PRESENT OWNER: CHURCH ADDRESS: SAME
6. USE: Original: PARSONAGE Present: SAME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain ~~YES~~ NO

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): ~~[illegible]~~

12. PHOTO:



HT-1

13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: EARLY 1870's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

156-2

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: RD#1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society

~~* * * * * * * * * * * * * * * * R.D. #2, Salem, N.Y. 12865 * * * * * * *~~


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: BIG BURCH HILL RD1
4. OWNERSHIP: a. public ☑ b. private ☐
5. PRESENT OWNER: N. Hebron Church ADDRESS:
6. USE: Original: Baptist Church Present: SAME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain YES


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): 1850's + 1870's

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1826

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Early Baptist Church built by the community and owned by them.

Has a Meneely bell in the steeple

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

157-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any):

* * * * * * * * * * * * * * * * Hebron Preservation Society * * * * * * * * * *
R. D. #2, Salem, N. Y. 12865


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: RTE BURCH HILL RD
4. OWNERSHIP: a. public ☑ b. private ☐
5. PRESENT OWNER: Emslg, Signey ADDRESS:
6. USE: Original: Home Present: ABONDED
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:




14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☒
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☒
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Iron or wooden grates in front of eye brow windows 

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: EARLY 1800's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. 115-11
QUAD
SERIES
NEG. NO.

158-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D. #1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any) ~~Hebron~~ Preservation Society

~~R.D. #2, Salem, N.Y. 12865~~


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: EMSIG RD
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Emsig, Sidney ADDRESS: RH2 GRANVILLE
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: EARLY 1800's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

159-4

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D #1 Granville N.Y. 12832 TELEPHONE: 642-1149

ORGANIZATION (if any): Hebron Preservation Society

* * * * * * * * * * * * * * * * *R.D. #2, Salem, N.Y. 12865* * * * * * * * * *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: BIG BURCH HILL RD
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: LULU WEHYMER ADDRESS: R#2 GRANVILLE
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☒ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: EARLY 1800s

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

FOR OFFICE USE ONLY	
UNIQUE SITE NO.	115/11
QUAD	
SERIES	
NEG. NO.	

160-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#1 Granville N.Y. TELEPHONE: 642-1749

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: B. 6 Birch Hill RD
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: RALPH BARDWELL ADDRESS: R#2 GRANVILLE
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain ND

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☑
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: BEFORE 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

161-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any):

* * * * * * * * * * * * * * Hebron Preservation Society * * * * * * * * * * * *
R. D. #2, Salem, N. Y. 12865


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: CO RT # 28
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: ADDRESS:
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: wooden silo

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Magnificent setting overlooking Vermont

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1840's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Beautiful collection of barns

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

162-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society
* * * * * * * * * * * * * * * * * R.D.#2 Salem N.Y. 12865 * * * * * * * * * *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: COURT #28
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Marrold, ROBERT ADDRESS:
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☑ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
    c. list major changes and dates (if known):

12. PHOTO: Pg-124



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1843

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Greek designs at the top of pilasters on corners & doorway.
Recessed doorway with Greek columns

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

163-3

Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

YOUR NAME: ELMER ROBERTS DATE:

YOUR ADDRESS: RD GRANVILLE NY TELEPHONE: (513) 642 0659

ORGANIZATION (if any):

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Co. Rte. 28
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Roberts, Elmer ADDRESS:
6. USE: Original: Present:
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: VINAL Siding
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☒
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☒ c. garage ☒
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: FARM LAND

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
DONT KNOW

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: ABOUT 1870

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

164-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D. #1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N.Y. 12865

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: CO RT # 28
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Miller Don ADDRESS: RT #1 GRANVILLE
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain NO

DESCRIPTION


8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☒ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☒
   b. wood frame with light members ☐
   c. masonry load bearing walls ☑
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

Porch removed 1975

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: MID 1800's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

165-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society

* * * * * * * * * * * * * * * * * * R.D. #2, Salem, N.Y. 12865 * * * * * * * * * *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: CO. RT. # 28
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Nelson, Danny ADDRESS: R#1 GRANVILLE
6. USE: Original: Farm Home Present: Farm Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: EARLY 1800s

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

166-3

YOUR NAME: J. DATE:

YOUR ADDRESS: Hebron Preservation Society R.D. #2, Salem, N.Y. 12865 TELEPHONE:

ORGANIZATION (if any):

* *

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASHINGTON TOWN/CITY: HEBRON VILLAGE: NORTH HEBRON
3. STREET LOCATION: So. GRANVILLE - No. HEBRON ROAD
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Corbett, CHARLES ADDRESS: R.F.D. #1 GRANVILLE N.Y. 12832
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain No - FAMILY HOME


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☒ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☐
   c. masonry load bearing walls ☒
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
    c. list major alterations and dates (if known):
    WOOD FRAME ADDITIONS - ABOUT 1935

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☒ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

—

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: prior to 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

167-3

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D. #1 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE:
3. STREET LOCATION: LANG Hill RD
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Liebeg, Walter ADDRESS: RT1 GRANVILLE
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: ~~[illegible]~~ AFTER 1850

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

168-4

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#1 Cranville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any):

* * * * * * * * * * * * * * * Hebron Preservation Society * * * * * * * * * * *
R. D. #2, Salem, N. Y. 12865

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: SLATE VILLE
3. STREET LOCATION: CO. RT. 31
4. OWNERSHIP: a. public ☐ b. private ☐
5. PRESENT OWNER: Warner, J ADDRESS: GRANVILLE
6. USE: Original: HOME Present: HOME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐ e. cobblestone ☐ f. shingles ☑ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☑
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: EARLY 1800's ? addition obviously later

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

169-4

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/31
QUAD
SERIES
NEG. NO.

YOUR NAME: Harold Craig DATE: March 1976

YOUR ADDRESS: R.D.#4 Granville N.Y. 12832 TELEPHONE: 642-1749

ORGANIZATION (if any): Hebron Preservation Society
R.D. #2, Salem, N.Y. 12865

IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: WASH TOWN/CITY: HEBRON VILLAGE: SLATEVILLE
3. STREET LOCATION:
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Button, Clarence ADDRESS: R#1 GRANVILLE
6. USE: Original: HOME Present: SAME
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
   Interior accessible: Explain NO


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☒ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☒
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO:



13. MAP:



HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Appx. 1915

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

170 -3

YOUR NAME: Sally Ballou DATE: Mar. 76'

YOUR ADDRESS: R.D. 2 Salem TELEPHONE: 854-3520

ORGANIZATION (if any): Hebron Preservation Society
R. D. #2, Salem, N. Y. 12865

* *

IDENTIFICATION


1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Chamberlin's Mill Rd
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Arvil Jones ADDRESS: R.D. Salem
6. USE: Original: farm Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☑ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):

12. PHOTO: P6-5

13. MAP:





HT-1

14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☑ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Clarence Boynton

21. SOURCES:

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

171-4

YOUR NAME: Sally Brillon DATE: Mar. 76

YOUR ADDRESS: Hebron Preservation Society TELEPHONE: 854-3520

ORGANIZATION (if any): R. D. #2, Salem, N. Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: TOWN/CITY: VILLAGE:
3. STREET LOCATION: Bog Town (Shawness Hill)
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: M. Migliore ADDRESS:
6. USE: Original: home Present: -
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐
   e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. wood frame with interlocking joints ☐
   b. wood frame with light members ☑
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☑ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☑ b. moved ☐ if so,when?
    c. list major alterations and dates (if known):





14. THREATS TO BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☑ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☑
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Shawnessy
Jones (Avril Jones father)

21. SOURCES:

172-2

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY
UNIQUE SITE NO. 115/11
QUAD
SERIES
NEG. NO.

YOUR NAME: Sally Bailey DATE: Mar. 76

YOUR ADDRESS: ~~Hebron Preservation Society~~ TELEPHONE: 854-3520

ORGANIZATION (if any): R.D. #2, Salem, N.Y. 12865

* *


IDENTIFICATION

1. BUILDING NAME(S):
2. COUNTY: Washington TOWN/CITY: Hebron VILLAGE:
3. STREET LOCATION: Bog Town Rd.
4. OWNERSHIP: a. public ☐ b. private ☑
5. PRESENT OWNER: Warren Wood ADDRESS: Glens Falls, N.Y.
6. USE: Original: possible tenant house Present: vacant
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☑ No ☐
   Interior accessible: Explain


DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☑ b. stone ☐ c. brick ☐ d. board and batten ☐ e. log ☐ f. shingles ☐ g. stucco ☐ other:
9. STRUCTURAL SYSTEM: (if known)
   a. log frame with interlocking joints ☑
   b. wood frame with light members ☐
   c. masonry load bearing walls ☐
   d. metal (explain)
   e. other
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☐ d. deteriorated ☑
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when?
    c. list major alterations and dates (if known): c.1870's window caps

12. PHOTO:



13. MAP:



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☑
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☑ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Fireplace on right
Early house in Victorian disguise
Upstairs front room stenciled
Two houses put together, can still see clapboards on inside wall.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Geo. Sheldon (owned)
Jameson

Fine example of stenciling, early type, all over the wall, covered with wall paper.

21. SOURCES:

Observation
Florence Getty

